UNICORN 6.3 1(1) User: Default 6/6/2018 2:47:29 PM -07:00 Run By : Default 6/6/2018 2:45:48 PM -07:00 Result: DJA2 07_07_17 SEC 200 -Conc B_Chrom.1:DJA2 07_07_17 SEC 200 -Fraction_Chrom.1:DJA2 07_07_17 SEC 200 Cond_Chrom.1:DJA2 07_07_17 SEC 200 PreC pressure_Chrom.1:DJA2 07_07_17 SEC 200 Injection Chrom.1:DJA2 07 07 UV Chrom.1:DJA2 07 07 17 SEC 200 -- Run Log_Chrom.1:DJA2 07_07_17 SEC 200 mAU (Error) Hardware Manager. Fraction Collector Box (F9 C): (23): The locked frac door was forced open Block (Issued) (Processing) (Completed) Data collection settings adjusted for curve UV. (Processing) (Completed) Block (Issued) End Е3 -ml Ó