$$\sigma_{3-4} = \frac{E}{L_T/3} (0.3056 - 0.1389) \frac{PL_T}{EA} = 0.500 \frac{P}{A}$$

These stresses are exact.