ME 712, Finite Element Method Applications Exam 1, Spring 2006

One formula sheet, closed notes. Test books will be provided. Two hours. *Problems must be done in order in the test books*. 10 points each.

- 1. Strain ϵ_x is given by $\epsilon_x = \frac{\partial u}{\partial x}$. What expression for ϵ_x is given when u in a four-noded element is given by $u = a_1 + a_2 x + a_3 y + a_4 x y$? Four a mesh of such elements, what can you say about the interelement continuity of ϵ_x ?
- 2. Determine the 1,4 element of the stiffness matrix for a beam in local coordinates (the beam being between x = 0 and x = l) presuming E is constant, but $I(x) = I_1 + (I_2 I_1)\frac{x}{l}$. Set up all math, but solve only for K_{14} .

$$N = \left[1 - 3\frac{x^2}{l^2} + 2\frac{x^3}{l^3} \quad x - 2\frac{x^2}{l} + \frac{x^3}{l^2} \quad 3\frac{x^2}{l^2} - 2\frac{x^3}{l^3} \quad -\frac{x^2}{l} + \frac{x^3}{l^2}\right] \tag{1}$$


3. A piezoelectric rod (truss) of constant properties has an energy, to be treated like a potential energy, of

$$U = \frac{1}{2}EA\epsilon(x)^2 - eA\frac{dV(x)}{dx}\epsilon(x) - \frac{1}{2}\bar{\epsilon}A\left(\frac{dV(x)}{dx}\right)^2$$
 (2)

where all variables are constant except those indicated above to be functions of x (note that ϵ is not the same as $\bar{\epsilon}$). Using the linear 1-D shape functions to represent the field variables u(x), displacement, and V(x), voltage field, in terms of nodal field quantities, u_j and V_j , determine the governing equations, in matrix form, in terms of the nodal field quantities. **Hint:** expand both $u(x) = \epsilon(x)$ and V(x) in terms of shape functions and modal displacements.

4. Two collinear cantilever beams are connected by a frictionless hinge as shown. Flexural stiffness, EI_z , is the same for both beams. Load P and deformations are confined to the xy plane. Write the stiffness matrix that operates on the "active" DOFs. Ignore transverse shear deformation. The elemental stiffness matrix is given by

$$K = \frac{EI_x}{L^3} \begin{bmatrix} 12 & 6L & -12 & 6L \\ 6L & 4L^2 & -6L & 2L^2 \\ -12 & -6L & 12 & -6L \\ 6L & 2L^2 & -6L & 4L^2 \end{bmatrix}$$



5. Define plane strain. Give an example of a problem for which the plane strain assumption is appropriate.

6. The rod mass matrix for a uniformly distributed rod is

$$M = \frac{\rho A \ell}{6} \begin{bmatrix} 2 & 1 \\ 1 & 2 \end{bmatrix}$$

What is the matrix in 3-D?