ME 712 Lab 3: Numerical Integration Due June 6

Program the Newmark beta method and apply it to the geometry shown in Figure 11.17-1 subject to the loads of section 11.18. Perform the comparison of all of the five Newmark beta methods shown in 11.13-1, similar to what is shown in figure 11.18-2 and table 11.18-1.