

SAFE OPERATING PROCEDURE

Drill Press

LOCATION: Various

TOI-OHOMAI
Institute of Technology

PERSONAL PROTECTIVE EQUIPMENT



Version: 2	Key Contact: George Fisher
Effective Date: 18/09/2020	Speciality/Position: Technician
Review Date: Sept 2022	Contact number: 021 190 4236
Permits required: N/A	Confined space ☐ Hot Works ☐ Working at Heights ☐

HAZARDS ASSOCIATED WITH THIS EQUIPMENT

PERMANENT HAZARDS Remove as necessary	List	Control Method	Lock out Yes or No
Electric shock	Power	Check leads for any damage, test and tag	No
Moving Machinery	Drill spins and entanglement could occur, drill also moves down and could crush	Keep hands clear of any moving parts	No
Noise	Machinery	Wear hearing protection	
Moving materials	Material being drilled may move	Secure material with clamps	No
Sharp objects	Sharp edges and swarf can be produced which can cause cuts or enter eyes	Wear eye protection and be aware of swarf	No
Hot surfaces	Swarf can be produced and burn	Be aware of hot swarf and metal	No

PURPOSE/PROCESS

PROCEDURES:

DO NOT use this machine unless you have proven to your trainer that you are competent in its safe use and operation

Pre Start Check

1. Ensure the operating area is uncluttered and well lit.
2. Check power leads and switches for damage (cuts, burns, cracks and exposed cables).
3. Check that all the attachments (including the handle) are secure and correctly fitted.
4. Use the correct drill bit for the material (pilot hole may be required). The drill bit must be sharp.
5. Check that the drill bit is tight and the chuck key is removed (if it has one)
6. If it is a keyless chuck hold the ring and turn the sleeve counter clockwise to open and clockwise to tighten.
7. Ensure the drill is firmly secured in the pedestal and that the pedestal is secured.
8. The drill should have a Perspex guard fitted over the chuck.
9. Always be sure that the electricity is switched off before adjusting or checking function of the drill or drill bit.



Operation

1. Centre punch before drilling. Drill a pilot hole for large holes.
2. Select rotation forward or reverse.
3. Select speed (some have multiple speeds)
4. Ensure the work is secured firmly – held in a vice or clamped.
5. Hold the drill handle firmly.
6. Let drill reach operating speed before applying a firm pressure. Too much pressure will break the drill bit.
7. When the drill is nearly through reduce the pressure (the drill bit can catch which may break it.)
8. Let the drill stop completely before removing work.

Close Down

1. Switch off the drill before adjustments or replacing the bit.
2. Disconnect the power lead and tidy the area.

Routine maintenance

Lock out and/or isolate any equipment before inspection or maintenance

	Name	Title/Position	Signature	Date
Author	Marie Dennis	HSW Manager		
Reviewed by	George Fisher	Technician		
Reviewed by	Tony Middlemiss	Health and safety rep		
Manager	Joe Nathan			

Document Control

Date	Revision number	Modifications	Revised by	Approved by
29/11/2019	1	New template and photos	Marie Dennis	
17/03/2020	2	Updated	George Fisher	