| S.No | ANALYSIS | |
|---|---|---|
| 1 | Failure Identification | Rubbing |
| 2 | Root Cause | • Normal Fatigue Failure<br>• Misalignment<br>• Loose Fits<br>• Tight Fits |
| 3 | Counter Measures | • Proper Lubrication<br>• Alignment<br>• Contamination Control<br>• Temperature Control<br>• Vibration Control |
| 4 | Co-Related Systems | • Pressure Plate<br>• Fork/Pivot<br>• Seals and Gaskets<br>• Slave Cylinder (in Hydraulic Systems) |
| 5 | Recommendations | • Avoid Overloading<br>• Appropriate Driving Practices<br>• Temperature Management<br>• Avoid Excessive Clutch Slippage |