
Caution!! During the firmware update, please do not execute any other application and remove all USB devices on the box.

Firmware Ver1.0 update guide


Step1. Execute the update tool "FwUpdateTool.exe"

AORUS_GAMING_BOX_VER10H2D.bin	2019/1/3 11:11	BIN 文件	304 KB
BNi5i7_TBT_FW_rev33_sign	2018/3/24 4:07	文件	300 KB
ECSIoDriver.sys	2017/11/14 21:34	系统文件	14 KB
ECSIoDriverX64.sys	2017/11/14 21:34	系统文件	14 KB
eHMTIoDriverLibrary.dⅡ	2017/11/14 21:34	应用程序扩展	1,719 KB
⋤ FwUpdate	2018/3/27 22:51	应用程序	1,727 KB
FwUpdateAPI.dll	2018/3/24 19:38	应用程序扩展	50 KB
♠ FwUpdateTool	2018/4/2 23:09	应用程序	473 KB
🖺 Gaming box update guide	2019/1/24 19:03	PDF 文件	745 KB


Step2. Click Next



Step3. Select "GIGABYTE, Gaming box" for the device and click "Next".




Step4. Click "Browse" to choose file




Step5. Select the corresponding file according to port1


AORUS_GAMING_BOX_VER10H2D.bin	2019/1/3 11:11	BIN 文件	304 KB
BNi5i7_TBT_FW_rev33_sign	2018/3/24 4:07	文件	300 KB
ECSIoDriver.sys	2017/11/14 21:34	系统文件	14 KB
ECSIoDriverX64.sys	2017/11/14 21:34	系统文件	14 KB
eHMTIoDriverLibrary.dll	2017/11/14 21:34	应用程序扩展	1,719 KB
I ■ FwUpdate	2018/3/27 22:51	应用程序	1,727 KB
	2018/3/24 19:38	应用程序扩展	50 KB
♠ FwUpdateTool	2018/4/2 23:09	应用程序	473 KB



Step7. Click "Start Thunderbolt $^{\text{TM}}$ firmware update" to update



Step8. When the update is in process, please do not disconnect the Thunderbolt cable.



Step9. After the update is finish, please restart your PC.

