

*** FACSIMILE TRANSMITTAL ***

INLAND AUTO BODY -- FONTANA, CA

TO : Meridian Claims Intake
FROM : R. Salcedo / Inland Auto Body
FAX : (877) 555-0100
RE : New claim - Policy CA-CA-88123-18
DATE : 09/08/2025
PAGES : 7 (incl. cover)

Estimate + supplement for the above claim. Damage
photos to follow under separate cover. Please call
with any questions. Thank you.

INLAND AUTO BODY

1155 S Cucamonga Ave, Fontana, CA 92337
(909) 555-0173 BAR AB-204471

VEHICLE REPAIR ESTIMATE

Estimate # : IAB-9930 Written : 2025-09-05
Claim # : pending assignment Adjuster: --
Estimator : R. Salcedo Type : Original

INSURED / POLICYHOLDER

Pacific Freight Partners Inc.
Policy CA-CA-88123-18
Fontana, CA 92335

CLAIMANT

Gloria Mendez (bodily injury claim - handled
separately by Meridian; see medical file)

VEHICLE

2018 Freightliner M2 106 Medium Duty
Body: box / cargo GVWR class 6
Odometer 128,540 Unit # PFP-114

LOSS

Rear impact. Damage to rear bumper, RH cargo
door and RH tail lamp. Vehicle damage only on
this estimate; medical / BI reserved separately.

INLAND AUTO BODY

1155 S Cucamonga Ave, Fontana, CA 92337
(909) 555-0173 BAR AB-204471

DAMAGE ASSESSMENT

Point of impact : rear (6 o'clock), offset right
Inspection : in-shop, unit on ground
Prior damage : see note below

Rear bumper cover deformed and torn at RH mount;
reinforcement bar to be R&I and inspected. RH
cargo door skin creased, hinge alignment off,
door to be replaced. RH tail lamp lens cracked,
housing separated - replace assembly.

NOTE: rear quarter shows corrosion and prior
paint edges not consistent with a fresh impact.
Flagged for adjuster review. Photographs on file
(rear bumper, rear quarter, cargo door).

OPERATIONS SUMMARY

Replace rear bumper cover, cargo door,
 RH tail lamp assembly
R&I bumper reinforcement bar
Refinish rear panel and replaced door
Align / fit rear body opening

INLAND AUTO BODY**1155 S Cucamonga Ave, Fontana, CA 92337****(909) 555-0173 BAR AB-204471**

ESTIMATE LINE ITEMS

LN	DESCRIPTION	OPER	HRS	AMOUNT
PARTS				
1	Bumper cover, rear	R&R		1,800.00
2	Cargo door, rear RH	R&R		640.00
3	Tail lamp assembly, RH	R&R		288.50
	Paint & materials	--		120.00
LABOR				
4	R&I rear bumper / reinf.	BODY	1.5	93.00
5	R&R cargo door, rear RH	BODY	2.5	155.00
6	Align / fit rear body	BODY	2.0	124.00
7	Refinish rear panel/door	REFN	3.0	186.00

Parts & materials: 2,848.50

Labor: 558.00

INLAND AUTO BODY**1155 S Cucamonga Ave, Fontana, CA 92337****(909) 555-0173 BAR AB-204471**

PARTS DETAIL

LN	DESCRIPTION	PART NO.	QTY	PRICE
1	Bumper cover, rear	A66-11288-000	1	1,800.00
2	Cargo door, rear RH	A18-66341-002	1	640.00
3	Tail lamp assembly, RH	A66-06327-001	1	288.50

OEM parts via Freightliner/Daimler dealer feed.
Part numbers per unit VIN build. Cargo door
quoted as complete shell assembly, RH.

PARTS SUBTOTAL

Parts (line 1-3):	2,728.50
Paint & materials:	120.00
Parts & materials:	2,848.50

INLAND AUTO BODY**1155 S Cucamonga Ave, Fontana, CA 92337****(909) 555-0173 BAR AB-204471**

LABOR OPERATIONS

LN	DESCRIPTION	OPER	HRS	RATE	AMOUNT
4	R&I rear bumper / reinf.	BODY	1.5	62.00	93.00
5	R&R cargo door, rear RH	BODY	2.5	62.00	155.00
6	Align / fit rear body	BODY	2.0	62.00	124.00
7	Refinish rear panel/door	REFN	3.0	62.00	186.00

Body 6.0 hr @ 62.00 Refinish 3.0 hr @ 62.00

Labor total: 558.00

PAINT & MATERIALS

Color base coat	48.00
Clearcoat	30.00
Primer / sealer	22.00
Hazardous waste disposal	12.00
Masking / fine-line	8.00

Paint & materials total 120.00

INLAND AUTO BODY

1155 S Cucamonga Ave, Fontana, CA 92337

(909) 555-0173 BAR AB-204471

ESTIMATE RECAP

Parts:	2,728.50
Paint & materials:	120.00
Labor:	558.00
Sales tax (8.75%):	249.24

VEHICLE TOTAL: 3,655.74

Vehicle damage only. Bodily-injury / medical is handled separately by Meridian. This estimate does not include prior-damage repairs. Supplements require prior authorization.

Estimator : R. Salcedo
Shop : Inland Auto Body, BAR AB-204471
Date : 2025-09-05