## = HMS Hereward (H93) =

HMS Hereward , named after Hereward the Wake , was an H @-@ class destroyer built for the Royal Navy in the mid @-@ 1930s . She was assigned to the Mediterranean Fleet before and the ship spent four months during the Spanish Civil War in mid @-@ 1937 in Spanish waters , enforcing the arms blockade imposed by Britain and France on both sides of the conflict . When the Second World War began in September 1939 , the ship was in the Mediterranean , but was shortly transferred to the South Atlantic Command to hunt for German commerce raiders and blockade runners , capturing one of the latter in November . Hereward was transferred to the Home Fleet in May 1940 and rescued Queen Wilhelmina of the Netherlands after the Germans had invaded .

The ship was transferred back to the Mediterranean Fleet later that month , and escorted convoys to Malta as well as escorting the larger ships of the fleet . She sank an Italian submarine in December before sinking the Italian torpedo boat Vega the following month . Hereward participated in the Battle of Cape Matapan in March 1941 and helped to evacuate Allied troops from Greece in April . In May the ship sank several small ships of a German convoy attempting to land troops on Crete . Later that month , she was bombed and sunk by German dive bombers as she was evacuating Allied troops from Crete . Her survivors were rescued by Italians and they became prisoners of war .

## = = Description = =

Hereward displaced 1 @,@ 350 long tons ( 1 @,@ 370 t ) at standard load and 1 @,@ 883 long tons ( 1 @,@ 913 t ) at deep load . The ship had an overall length of 323 feet ( 98 @.@ 5 m ) , a beam of 33 feet ( 10 @.@ 1 m ) and a draught of 12 feet 5 inches ( 3 @.@ 8 m ) . She was powered by Parsons geared steam turbines , driving two shafts , which developed a total of 34 @,@ 000 shaft horsepower ( 25 @,@ 000 kW ) and gave a maximum speed of 36 knots ( 67 km / h ; 41 mph ) . Steam for the turbines was provided by three Admiralty 3 @-@ drum water @-@ tube boilers . Hereward carried a maximum of 470 long tons ( 480 t ) of fuel oil that gave her a range of 5 @,@ 530 nautical miles ( 10 @,@ 240 km ; 6 @,@ 360 mi ) at 15 knots ( 28 km / h ; 17 mph ) . The ship 's complement was 137 officers and men in peacetime , but this increased to 146 in wartime .

The ship mounted four 45 @-@ calibre 4 @.@ 7 @-@ inch ( 120 mm ) Mk IX guns in single mounts . For anti @-@ aircraft ( AA ) defence , Hereward had two quadruple Mark I mounts for the 0 @.@ 5 inch Vickers Mk III machine gun . She was fitted with two above @-@ water quadruple torpedo tube mounts for 21 @-@ inch torpedoes . One depth charge rail and two throwers were fitted ; 20 depth charges were originally carried , but this increased to 35 shortly after the war began . Beginning in mid @-@ 1940 , the ship 's anti @-@ aircraft armament was increased , although when exactly the modifications were made is not known . The rear set of torpedo tubes was replaced by a 12 @-@ pounder AA gun .

## = = Service = =

The ship was laid down by the High Walker Yard of Vickers Armstrong at Newcastle @-@ on @-@ Tyne on 28 February 1935 , launched on 10 March 1936 and completed on 9 December 1936 . Excluding government @-@ furnished equipment like the armament , the ship cost £ 249 @,@ 591 . She tested the twin @-@ gun mounted intended for use on the Tribal @-@ class destroyers in January ? March 1937 at Gibraltar . It was removed at the end of the trials and her two forward guns were replaced immediately afterwards . The ship was then assigned to the 2nd Destroyer Flotilla of the Mediterranean Fleet and began patrolling Spanish waters in the Mediterranean enforcing the Non @-@ Intervention Agreement during the Spanish Civil War . Hereward was refitted in Malta from 30 September to 30 October 1937 and again a year later , this time in Portsmouth Dockyard in June ? July 1939 and she returned to the Mediterranean afterwards .

Hereward was transferred to Freetown to hunt for German commerce raiders in the South Atlantic with Force K in October . The ship and her sisters , Hardy , Hasty , and Hostile , rendezvoused with

the battlecruiser Renown , the aircraft carrier Ark Royal , and the light cruiser Neptune on 17 December . They refueled in Rio de Janeiro , Brazil , before proceeding to the estuary of the River Plate in case the damaged German pocket battleship Admiral Graf Spee attempted to escape from Montevideo , Uruguay , where she had taken refuge after losing the Battle of the River Plate . Hereward captured the German blockade runner Uhenfels on 5 November . The ship was based at Trinidad from 20 November to 23 January 1940 and blockaded the German merchant ship Arauca in Port Everglades , Florida whilst based there . She escorted the battleship Valiant to Halifax , but suffered weather damage en route that required three weeks for repairs . Hereward then escorted the light cruiser Orion to the UK as the latter carried the ashes of John Buchan , Governor General of Canada , home . She required further repairs at Portsmouth upon arrival and missed the Battles of Narvik in April .

Hereward escorted ships into Scheveningen , Netherlands on 11 May to evacuate British citizens after the Germans invaded the previous day . She evacuated Queen Wilhelmina and her family from the Netherlands on 13 May , and was transferred to the Mediterranean Fleet a few days later . The ship arrived at Alexandria on 24 May and began escorting convoys and larger ships of the fleet . Hereward participated in the Battle of Calabria in July 1940 , where she was hit by splinters from a near @-@ miss of the Italian battleship Giulio Cesare . The ship escorted a convoy during Operation Collar and then fired at retreating Italians in Cyrenaica after the Battle of Sidi Barrani . Together with her sister Hyperion , she sank the Italian submarine Naiade on 13 December . Hereward escorted the battleships of the Mediterranean Fleet as they bombarded Valona on 19 December and then sortied into the North Atlantic when Convoy WS @-@ 5A reported that it had been attacked by the German cruiser Admiral Hipper on 25 December . She escorted three of the convoy 's ship to Gibraltar on 29 December .

The ship participated in Operation Excess in early January 1941 and sank the Italian torpedo boat Vega on 10 January with a torpedo in the Strait of Sicily . Together with the destroyer Decoy and the gunboat Ladybird , Hereward landed commandos on the island of Kastelorizo as part of Operation Abstention , but they were overwhelmed by an Italian counter @-@ attack . Only a few survivors were taken off two days later . The ship participated in the Battle of Cape Matapan in early March 1941 and the evacuation of Greece in April 1941 . She sank a number of fishing boats transporting German troops to Crete on 21 May and helped evacuate the Allied garrison of Heraklion on 29 May . Later that day she was attacked by German Junkers Ju 87 " Stuka " dive bombers and hit by one bomb just in front of her forward funnel . She turned towards the nearby coast of Crete , but was sunk by further attacks . Four officers and 72 crewmen were killed , but the 89 survivors were rescued by Italian MAS torpedo boats and taken prisoner .