HMS Aurora was one of seven Orlando @-@ class armoured cruisers built for the Royal Navy in the mid @-@ 1880s . The ship spent a brief time in reserve before she was assigned to the Channel Squadron for two years in 1890 . In 1893 Aurora became a coast guard ship in Ireland for two years before she was placed in reserve again . The ship recommissioned in 1899 for service on the China Station and some of her crew participated in the Battle of Tientsin in 1900 during the Boxer Rebellion . Aurora returned home two years later and was again reduced to reserve . She was taken out of service in 1905 and sold for scrap on 2 October 1907 .

= = Design and description = =

The Orlando @-@ class cruisers were enlarged versions of the Mersey class with more armour and a more powerful armament . Like their predecessors , they were intended to protect British shipping . Aurora had a length between perpendiculars of 300 feet (91 @.@ 4 m) , a beam of 56 feet (17 @.@ 1 m) and a draught of 24 feet (7 @.@ 3 m) . Designed to displace 5 @,@ 040 long tons (5 @,@ 120 t) , all of the Orlando @-@ class ships proved to be overweight and displaced approximately 5 @,@ 535 long tons (5 @,@ 624 t) . The ships were powered by a pair of three @-@ cylinder triple @-@ expansion steam engines , each driving one shaft , which were designed to produce a total of 8 @,@ 500 indicated horsepower (6 @,@ 300 kW) and a maximum speed of 18 knots (33 km / h ; 21 mph) using steam provided by four boilers with forced draught . The ship carried a maximum of 900 long tons (910 t) of coal which was designed to give her a range of 8 @,@ 000 nautical miles (15 @,@ 000 km ; 9 @,@ 200 mi) at a speed of 10 knots (19 km / h ; 12 mph) . The ship 's complement was 484 officers and enlisted men .

Aurora 's main armament consisted of two breech @-@ loading (BL) 9 @.@ 2 @-@ inch (234 mm) Mk V guns , one gun fore and aft of the superstructure on pivot mounts . Her secondary armament was ten BL 6 @-@ inch (152 mm) guns , five on each broadside . Protection against torpedo boats was provided by six quick @-@ firing (QF) 6 @-@ pounder Hotchkiss guns and ten QF 3 @-@ pounder Hotchkiss guns , most of which were mounted on the main deck in broadside positions . The ship was also armed with six 18 @-@ inch (457 mm) torpedo tubes : four on the broadside above water and one each in the bow and stern below water .

The ship was protected by a waterline compound armour belt 10 inches (254 mm) thick . It covered the middle 200 feet (61 @ .@ 0 m) of the ship and was 5 feet 6 inches (1 @ .@ 7 m) high . Because the ship was overweight , the top of the armour belt was 2 feet (0 @ .@ 61 m) below the waterline when she was fully loaded . The ends of the armour belt were closed off by transverse bulkheads 16 inches (406 mm) . The lower deck was 2 ? 3 inches (51 ? 76 mm) thick over the full length of the hull . The conning tower was protected by 12 inches (305 mm) of armour .

= = Construction and service = =

Aurora , named for the eponymous Roman goddess of the dawn , was the eighth ship of her name to serve in the Royal Navy . She was laid down on 1 February 1886 by Pembroke Dockyard . The ship was launched on 28 October 1887 by Mrs. Sophia Morant , wife of Captain George Morant , Captain @-@ Superintendent of the dockyard and completed in July 1889 at a cost of £ 258 @,@ 390 .

Aurora went straight into reserve at Devonport after completion , but was commissioned for service with the Channel Squadron in 1890 ? 92 . She was transferred to Bantry , Ireland , in 1893 to serve as the local coastguard ship until 1895 . That year the ship was reassigned to the Devonport Reserve and remained there until 1899 . Aurora participated in Queen Victoria 's Diamond Jubilee Fleet review on 26 June 1897 at Spithead .

Aurora was recommissioned for service in the Far East in 1899 under the command of Captain Edward Bayly and some of her crew , including Bayly , took part in the Battle of Tientsin in July 1900 during the Boxer Rebellion . In early February 1902 she was ordered to leave , homebound , arriving

at Aden on 3 March , at Malta 17 March , and at Plymouth on 26 March . Officers and crew received the China War Medal (1900) on 15 April , before she paid off at Devonport two days later . Aurora was refitted in Clydebank upon her return and was placed in Devonport Reserve in 1904 before she was taken out of service the following year . The ship was sold for scrap to Payton , of Milford Haven , Wales , on 2 October 1907 .