

CHF



737-300/400/500 TASK CARDS

AIRLINE CARD NO		TITLE MLG SHOCK STRUT - LEFT			BOEING CARD NO. 12-021-12-01	
DATE	TASK LUBRICATE				RELATED CARD	
TAIL NUMBER	WORK AREA L MAIN GEAR	VERSION 1.1	THRESHOLD 7 DY	REPEAT 7 DY	APPLICABILITY AIRPLANE ALL ENGINE ALL	
STATION	SKILL AIRPL	ACCESS			ZONE 310	
Clean exposed surface of left main landing gear strut piston with a cloth moistened with MIL-H-5606 hydraulic fluid and wipe with dry cloth. Check X-dimension extension on strut piston to verify that piston is not flat.						
EFFECTIVITY CHF ALL		SOURCE MPD	MLG SHOCK STRUT - LEFT D6-38278-3C1 12-021-12-01			

CHF



737-300/400/500 TASK CARDS

DATE	TAIL NUMBER	STATION	AIRLINE CARD NO.	BOEING CARD NO. 12-021-12-01	MECH	INSP
TASK 12-21-11-600-801						
1. <u>Main Landing Gear Shock Strut Servicing</u>						
A. Procedure						
SUBTASK 12-21-11-610-001						
(1) Clean exposed surface of main landing gear strut piston with a cloth moistened with MIL-H-5606 hydraulic fluid and wipe with dry cloth. Check X-dimension extension on strut piston to verify that piston is not flat.						
————— END OF TASK —————						
EFFECTIVITY CHF ALL		SOURCE MPD	MLG SHOCK STRUT - LEFT			
			D6-38278-3C1			
			12-021-12-01			
			Page 2 of 2			
			Mar 25/2015			