
UT19, 100 s^{-1}
force in the specimen, F_{out} (kN, unfiltered)
time from the start of loading (μs)
centred (gaps)
in contact


UT19, 500 s^{-1}
force in the specimen, F_{out} (kN, unfiltered)
time from the start of loading (μs)
centred (gaps)
in contact


UT19, 1000 s^{-1}
force in the specimen, F_{out} (kN, unfiltered)
time from the start of loading (μs)
centred (gaps)
in contact