

100 s^{-1} (target)
500 s^{-1} (target)
1000 s^{-1} (target)
engineering stress, mean of F_{in} and F_{out} / A_0 (MPa)
UT19
UT40
engineering strain (%)
R_{mod} (%)