DP1000 law: when does the force stop rising?



Why necking is an instability