
UT40, 100 s^{-1} (error 2 %)
UT40, 500 s^{-1} (error 4 %)
UT40, 1000 s^{-1} (error 65 %)
engineering stress (MPa)
0
200
400
600
800
1000
1200
1400
1600
true force in the specimen
(cross-section, simulation only)
force read on the output bar
gauge (what the test measures)
0
5
10
15
20
25
30
engineering strain (%)
engineering strain (%)
engineering strain (%)