
UT40, 500 s^{-1} (error 4 %)
engineering stress (MPa)
1600
1400
1200
1000
800
600
400
200
0
0
5
10
15
20
25
30
engineering strain (%)
true force in the specimen
(cross-section, simulation only)
force read on the output bar
gauge (what the test measures)