
Power on
Initialize the hardware
Read and filter the inputs
Check the E-stop and limit switches
Start button: clear the faults or restart the cycle
Fault latched?
No
Yes
Run the cycle and move the axes
Safe state: stop the axes, hold the part
Report the state over Modbus
Next pass