


rut

SPI -> serial peripheral Interface

Hardware Interface

55



moss: master out put slave input miso: master Input slave output clk-sck—> clock

ss-cs-Nss-Ncs-> slaveselect


Note:-

ef I want to allow Broad casting


Pisconnect themeso line L> simplex

you can conecct 55 to GNd to Enable
the Slave -> IF I only have one
slave

3-number of slaves in SPI Network depend on (number of GPI o Pinsin) master



through= No of Latabits \_ 8 Put Lotal Frame



Start bit

(data)

Evame

Start condition

SSU CLKA