

#	Name	Parts (inc Fasteners)	Parts (no fasteners)	Adjustments	Time	Necessary parts	Efficiency	Expected Time (min)
A1	Frame Assembly	45	11	1	78.97	2	8%	13.2
A2	Y Axis Assembly	73	21	2	236.41	9	11%	39.4
A3	X Axis Assembly	21	14	4	130.23	6	14%	21.7
A4	Z Axis Assembly	32	10	6	141.18	4	8%	23.5
A5	Extruder Assembly	78	31	31	475.22	15	9%	79.2
A6	LCD Assembly	15	5	4	62.20	3	14%	10.4
A7	Heatbed Assembly	35	14	2	305.00	3	3%	50.8
A8	PSU Assembly	11	7	1	91.05	3	10%	15.2
A9	Electronics Assembly	37	9	22	198.25	3	5%	33.0
A10	Spool Holder + Assembly	5	5	0	20.75	1	14%	3.5
Prusa MK3 Printer		352	127	73	1739.26	49	8%	4.8 Hours
29.0 minutes								