71 chambers previously aligned with a quoted uncertainty of "1-2 mm" new alignment corrections shown below

