Metric Tap &		Tap Drill				Clearance Drill				
Clearance Drill		75% Thread for		50% Thread for						
_		Aluminum, Brass,		Steel, Stainless,		Close Fit		Standard Fit		
Sizes		& Plastics		& Iron						
Screw Size	Thread	Drill Size	Closest American	Drill Size	Closest American	Drill Size	Closest	Drill Size	Closest American	
(mm)	Pitch (mm)	(mm)	Drill	(mm)	Drill	(mm)	American Drill	(mm)	Drill	
M1.5	0.35	1.15	56	1.25	55	1.60	1/16	1.65	52	
M1.6	0.35	1.25	55	1.35	54	1.70	51	1.75	50	
M 1.8	0.35	1.45	53	1.55	1/16	1.90	49	2.00	5/64	
M 2	0.45	1.55	1/16	1.70	51	2.10	45	2.20	44	
	0.40	1.60	52	1.75	50					
M 2.2	0.45	1.75	50	1.90	48	2.30	3/32	2.40	41	
M 2.5	0.45	2.05	46	2.20	44	2.65	37	2.75	7/64	
M 3	0.60	2.40	41	2.60	37	3.15	1/8	3.30	30	
	0.50	2.50	39	2.70	36					
M 3.5	0.60	2.90	32	3.10	31	3.70	27	3.85	24	
M 4	0.75 0.70	3.25 3.30	30 30	3.50 3.50	28 28	4.20	19	4.40	17	
M 4.5	0.75	3.75	25	4.00	22	4.75	13	5.00	9	
W 4.3	1.00	4.00	21	4.40	11/64	4.73	13	3.00	7	
M 5	0.90	4.10	20	4.40	17	5.25	5	5.50	7/32	
	0.80	4.20	19	4.50	16					
M 5.5	0.90	4.60	14	4.90	10	5.80	1	6.10	В	
	1.00	5.00	8	5.40	4	6.30	E	6.60	G	
M 6	0.75	5.25	4	5.50	7/32					
M 7	1.00	6.00	В	6.40	E	7.40	L	7.70	N	
/W. /	0.75	6.25	D	6.50	F					
M 8	1.25	6.80	Н	7.20	J	8.40	Q	8.80	S	
m o	1.00	7.00	J	7.40	L					
M 9	1.25	7.80	N	8.20	Р	9.50	3/8	9.90	25/64	
	1.00	8.00	0	8.40	21/64					
W 10	1.50	8.50	R 44/22	9.00	T	10.50	Z	11.00	7/16 15/32	
M 10	1.25 1.00	8.80 9.00	11/32 T	9.20 9.40	23/64 U					
M 11	1.50	9.50	3/8	10.00	X	11.60	29/64	12.10		
/// 11	1.75	10.30	13/32	10.90	27/64	11.00	27/04	12.10	13/32	
M 12	1.50	10.50	Z	11.00	7/16	12.60	1/2	13.20	33/64	
	1.25	10.80	27/64	11.20	7/16	,	.,_			
M 14	2.00	12.10	15/32	12.70	1/2		37/64	15.50	39/64	
	1.50	12.50	1/2	13.00	33/64	14.75				
	1.25	12.80	1/2	13.20	33/64					
M 15	1.50	13.50	17/32	14.00	35/64	15.75	5/8	16.50	21/32	
M 16	2.00	14.00	35/64	14.75	37/64	16.75	21/32	17.50	11/16	
	1.50	14.50	37/64	15.00	19/32					
M 17	1.50	15.50	39/64	16.00	5/8	18.00	45/64	18.50	47/64	
M 18	2.50	15.50	39/64	16.50	41/64	19.00	3/4	20.00	25/32	
	2.00	16.00	5/8	16.75	21/32					
	1.50	16.50	21/32	17.00	43/64	20.00	25 /22			
M 19	2.50	16.50	21/32	17.50	11/16	20.00	25/32	21.00	53/64	
M 20	2.50	17.50	11/16	18.50	23/32	21.00	53/64	22.00	55/64	
M 20	2.00	18.00	45/64 47/64	18.50 19.00	47/64 3/4					
	1.50	18.50	47/64	17.00	3/4					





## the premier source of parts and accessories for mini lathes and mini mills LittleMachineShop.com • (800) 981-9663

Tap &	Clearar	nce Dri	ll Sizes	Tap Drill				Clearance Drill			
Screw Size	Major Diameter	Threads Per Inch	Minor Diameter	Aluminum Plas	read for , Brass, & stics	50% Thread for Steel, Stainless, & Iron		Close Fit		Free Fit	
0	0400	00	0447	Drill Size	Dec. Eq.	Drill Size	Dec. Eq.	Drill Size	Dec. Eq.	Drill Size	Dec. Eq.
0 .0600	.0600	80 64	.0447	3/64 53	.0469	55 1/16	.0520 .0625	52	.0635	50	.0700
1	.0730	72	.0560	53	.0595	52	.0635	48	.0760	46	.0810
2	.0860	56	.0641	50	.0700	49	.0730	43	.0890	41	.0960
		64	.0668	50	.0700	48	.0760				
3	.0990	48	.0734	47	.0785	44	.0860	37	.1040	35	.1100
		56	.0771	45	.0820	43	.0890				
4 5	.1120	40	.0813	43	.0890	41	.0960	32 30	.1160	30	.1285
		48	.0864	42	.0935	40	.0980				
		40	.0943	38	.1015	7/64	.1094		.1285	29	.1360
		44	.0971	37	.1040	35	.1100				
6	.138	32	.0997	36	.1065	32	.1160	27	.1440	25	.1495
		40	.1073	33	.1130	31	.1200				
8 .1640	.1640	32 36	.1257	29 29	.1360	27 26	.1440	18	.1695	16	.1770
		24	.1299 .1389	25	.1360 .1495	20	.1470 .1610		.1960	7	.2010
10	.1900	32	.1517	21	.1590	18	.1695	9			
		24	.1649	16	.1770	12	.1890				
12	.2160	28	.1722	14	.1820	10	.1935	2	.2210	1	.2280
		32	.1777	13	.1850	9	.1960				
1/4	.2500	20	.1887	7	.2010	7/32	.2188	F	.2570	Н	.2660
		28	.2062	3	.2130	1	.2280				
		32	.2117	7/32	.2188	1	.2280				
5/16	.3125	18	.2443	F	.2570	J	.2770	P	.3230	Q	.3320
		24	.2614		.2720	9/32	.2812				
		32	.2742	9/32	.2812	L	.2900				
3/8	.3750	16	.2983	5/16	.3125	Q	.3320	W	.3860	Х	.3970
		24	.3239	Q	.3320	S	.3480				
		32	.3367	11/32	.3438	T	.3580				
7/16	.4375	14	.3499	U	.3680	25/64	.3906	29/64	.4531	15/32	.4687
		20 28	.3762 .3937	25/64 Y	.3906 .4040	13/32 Z	.4062 .4130				
		13	.4056	27/64	.4219	29/64	.4531				
1/2	.5000	20	.4387	29/64	.4531	15/32	.4688	33/64	.5156	17/32	.5312
		28	.4562	15/32	.4688	15/32	.4688				
9/16	.5625	12	.4603	31/64	.4844	33/64	.5156	37/64	.5781	19/32	.5938
		18	.4943	33/64	.5156	17/32	.5312				
		24	.5114	33/64	.5156	17/32	.5312				
5/8	.6250	11	.5135	17/32	.5312	9/16	.5625	41/64	.6406	21/32	.6562
		18	.5568	37/64	.5781	19/32	.5938				
		24	.5739	37/64	.5781	19/32	.5938				
11/16	.6875	24	.6364	41/64	.6406	21/32	.6562	45/64	.7031	23/32	.7188
3/4		10	.6273	21/32	.6562	11/16	.6875	49/64	.7656	25/32 27/32	.7812
		16	.6733	11/16	.6875	45/64	.7031				
12/16		20	.6887	45/64	.7031	23/32	.7188				0.420
13/16	.8125	20 9	.7512 .7387	49/64 49/64	.7656 .7656	25/32 51/64	.7812 .7969	53/64	.8281	Z113Z	.8438
7/8	.8750	14	.7874	13/16	.8125	53/64	.8281	57/64	.8906	29/32	.9062
		20	.8137	53/64	.8281	27/32	.8438				
15/16	.9375	20	.8762	57/64	.8906	29/32	.9062	61/64	.9531	31/32	.9688
1	1.000	8	.8466	7/8	.8750	59/64	.9219	1-1/64	1.0156	1-1/32	1.0313
		12	.8978	15/16	.9375	61/64	.9531				
		20	.9387	61/64	.9531	31/32	.9688				