CnC Tech IDC Socket / Header Mating Guide

Part Number Explanation - IDC Socket

Example PN **3030-10-0101-00**

3030=Series

10=Number of Positions

0101=Features

• 0101= Feed Through

• 0102= Feed Through, Polarizing Key

• 0103= Polarizing Key, Strain Relief

• 0104= Feed Through, Strain Relief

00=Contact Finish

• 00= Gold Flash

• 99= Tin 80μin (2.03μm)

Part Number Explanation - Header

Example PN

3010-10-001-13-00

3010=Series

10=Number of Positions

001=Mounting

• 001= Through Hole

• 002= Through Hole, Right Angle

• 003= Surface Mount

13= Fastening Type

• 11= No Latch Lock

• 12= Latch Lock/Eject Hooks, Short

• 13 = Latch Lock/Eject Hooks, Long

00=Contact Finish

• 00= Gold Flash

• 99= Tin 80μin (2.03μm)

3030 Series	Mating Part Numbers						
3030-XX-0101-XX	3010-XX-001-12-XX	3010-XX-002-12-XX	3010-XX-003-12-XX	3010-XX-001-11-XX	3020-ALL		
3030-XX-0102-XX							
3030-XX-0103-XX	3010-XX-001-13-XX	3010-XX-002-13-XX	3010-XX-003-13-XX	3010-XX-001-11-XX	3020-ALL		
3030-XX-0104-XX							

3130 Series	Mating Part Numbers						
3130-XX-0101-XX	3110-XX-001-12-XX	3010-XX-002-12-XX	3110-XX-003-12-XX	3010-XX-001-11-XX	3120-ALL		
3130-XX-0102-XX							
3130-XX-0103-XX	3110-XX-001-13-XX	3110-XX-002-13-XX	3110-XX-003-13-XX	3110-XX-001-11-XX	3120-ALL		
3130-XX-0104-XX							

3230 Series	Mating Part Numbers					
3230-XX-0101-XX	3210-XX-001-11-XX	3210-XX-001-12-XX	3210-XX-002-12-XX	3210-XX-003-12-XX	3221-ALL and 3220-ALL	
3230-XX-0102-XX						
3230-XX-0103-XX	3221-ALL					
3230-XX-0104-XX						