



Appendix C: Detailed and Assembly Drawing

C.1 Assembly Demonstration




Part 1 - Per assembled components

Both the base frame and the gear box/motor sections will be prefabricated. The rivets in the base frame are permanent and therefore must be put together by the manufacturer. Similarly the gear box has precision fit components and will be pre assembled before shipping.




Part 2 - Cutting components

The blade assembly with shaft and spacers, along with the teeth assembly with the rod and spacers are easy to assemble. The blades must be rotated by 135 degrees each iteration, and the teeth must be inserted with just the same orientation. This set may be done by the consumer or manufacturer, depending on the packaging requirements.




Part 3 - Assembly of frame.

Depending on packaging requirements the frame assembly will largely be done by the consumer. Some components will be delivered per assembled such as the handle, the gear mechanism and the rivet nut that are bonded to the frame. All other fasteners may be assembled by the user, with the distance of a component from the base assembly showing when that component should be added, closer components should be added first.



C.2.1 Technical Drawing of the Blades



C.2.2 Technical Drawing of the Shaft Assembly

