

1 2 3 4 5 6 7 8

NOTES: (UNLESS OTHERWISE SPECIFIED)

1. SEE OH-PL-INTERCONNECT FOR INTERCONNECT PARTS LIST.
2. SEE OH-SPEC-002 FOR ABSIS CABLE SPECIFICATIONS.
3. TERMINATE ALL UNUSED CONDUCTORS BY FOLDING BACK CONDUCTORS AND HEAT SHRINKING CONDUCTOR ALONG CABLE.

A

A

B

B

C


C


D

D

E

E





RENUMBER CABLES



