

Hubitat Master Task List

Combined working list — Hubitat / jshimota drivers & apps + Echos Speak

ID	AREA	DEVICE / APP	TASK / ISSUE	SOURCE	STATUS
1	Thermostat — Thermostat	MEM v1.8.6 / dev:510	Fix setpoint re-entry / race condition. MEM can initiate a setpoint change and the thermostat's synchronous event can re-enter the evaluation chain before pending-write protection is established. This is the issue behind the 70° ↔ 74° bouncing.	Existing investigation	OPEN: Open — root cause identified
2	Thermostat — Thermostat	MEM v1.8.6	Debounce evaluatePeriods(). Gemini found the Morning transition causing the same MEM evaluation 4 times in ~1.5 sec. Add a 1–2 sec state/event buffer so the event cascade results in one evaluation.	Gemini PDF Action 3	OPEN: Open
3	Thermostat — Thermostat	Centralite Pearl dev:510	Prevent redundant setpoint writes. Before issuing a heating/cooling command, compare the requested value with currentValue() and skip the command when already at the target.	Gemini PDF Action 1	OPEN: Open
4	Thermostat — Thermostat	Centralite Pearl dev:510	Clean up duplicate thermostat logging. Eliminate command-side "Setting heatingSetpoint..." / "Setting coolingSetpoint..." messages where the resulting device event already provides the useful "was set to..." log.	Gemini PDF Action 2	OPEN: Open
5	Device Health — Device Health	dev:622 / dev:498	Investigate/add passive device-health check-ins.	Existing Hubitat list	OPEN: Open
6	Motion — Motion	dev:577 / dev:578	Investigate Stairwell Motion re-arm/cooldown behavior; target approximately 30–60 seconds.	Existing Hubitat list	OPEN: Open
7	Lighting — Lighting	dev:638 / app:500	Remove redundant lighting commands being generated by the control chain.	Existing Hubitat list	OPEN: Open
8	Echos Speak — Echos Speak	WHA / Group Dispatch	Complete WHA Group Dispatch work. This is one of the two tasks carried forward from the Echos Speak-specific list.	Echos Speak list	OPEN: Open — next Echos task
9	Echos Speak — Echos Speak	Echo Show	Implement/finish Echo Show Display Power support. This is the second task carried forward from the Echos Speak-specific list.	Echos Speak list	OPEN: Open
10	Echos Speak — Echos Speak	app:946 / Bridge	Improve bridge timeout resilience and quiet the resulting log noise. Gemini found unhandled HTTP/socket timeout errors from the Node bridge. Add concise error handling and controlled retry behavior.	Gemini PDF Action 4	OPEN: Open
11	Echos Speak — Echos Speak	app:946	Legacy GUI cleanup.	Echos Speak list	COMPLETE: Complete
12	Echos Speak — Echos Speak	app:946	Voice / Speak functionality.	Echos Speak list	COMPLETE: Complete
13	Echos Speak — Echos Speak	app:946	Playback functionality.	Echos Speak list	COMPLETE: Complete
14	Echos Speak — Echos Speak	app:946	Command guards.	Echos Speak list	COMPLETE: Complete
15	Echos Speak — Echos Speak	app:946	Server log review.	Echos Speak list	COMPLETE: Complete
16	Echos Speak — Echos Speak	app:946	W/Sensors level / capability work.	Echos Speak list	COMPLETE: Complete

How to read the list

Source distinguishes items carried forward from the existing Hubitat list, the Echos Speak task list, and the Gemini 24-hour log evaluation. Overlapping findings were consolidated rather than duplicated. **Open — root cause identified** means the investigation has established the mechanism and the next step is implementation/testing.

The Gemini evaluation specifically identified dev:510 as the highest-chatter jshimota device, with rapid setpoint flipping and repeated setter execution, and identified repeated MEM Morning evaluations as a separate debounce opportunity. It also identified bridge timeout logging in Echos Speak.