DC-6006L Command

1. Serial Port Setting

arg	value
baudrate	115200
xonxoff	True

2. Command List



ser.write(cmd + "\r\n").encode('ascii'))

cmd		python ex.
N	power on	self.ser.write("N" + "\r\n").encode('ascii'))
F	power off	
Q	log	
W	logging	
Z	noprotect	
V	set voltage	5V setting example value = "V%04d" % (5.0 * 100) ser.write((value + "\r\n").encode('ascii'))
I	set current	"I%04d" % (value * 1000)
В	set ovp	"B%04d" % (value * 100)

DC-6006L Command 1

cmd		python ex.
D	set ocp	"D%04d" % (value * 1000)
E	set opp	"E%04d" % (value * 10)
Н	set ohp (hr.)	"H%02d" % (value / 3600)
M	set ohp (min.)	"M%02d" % ((value % 3600) / 60)
S	set ohp (sec.)	"S%02d" % (value % 60)
X	ohp enable	
Υ	ohp disable	

DC-6006L Command 2