

Incident Report for 5/18/2026 Environmental Incident (Incident ID: 5970)

☒ Initial ☐ Update ☐ Close Out

Incident Details				Reporting Party Details			
Description:		Truck and tanker slide into south ditch of intersection of 81st St SE and 37th Ave SE (GPS location 46.244734, -99.607343) some leakage of milk from tanker lid and some leakage of diesel fuel under truck. Truck and tanker are laying on the passenger side.		Incident Date and Time:		5/18/2026 03:00 AM	
Incident Type:		Environmental Incident		Incident Subtype :		Vehicle Accident	
Source Type:		Transportation		Source Subtype:		Freight Road Transport Vehicle	
Incident Status:		Active		Released Into Medium :		Soil	
Site Details				Incident Location			
Is Spill Continuous:		Yes		Is Spill Contained:		Unknown	
Discovered/Start Date and Time:		5/18/2026 01:30 PM		End Date and Time:		5/18/2026 07:00 PM	
Reported to NRC:		No		Estimated Duration:		16 Hrs	
Well Name :				NDIC File Number :			
Oil/Gas Operator :				Oil/Gas Field Name :			
Extent of Spill/Release: Extent Undetermined				Address: 81 St SE, Wishek, ND 58495			
Extent Details:				Location Description: Intersection of 81st ST SE & 37th Ave SE			
				Latitude:		46.244323062425	
				Longitude:		-99.6066893807474	
				Section:		20	
				Township:		132 N	
				Range:		71 W	
				Quarter:		NW¼	
				Qquarter:		NW¼	
				Source Water Protection Area:			
				County/Tribe:		McIntosh County	
				Fire District:		WISHEK FIRE	
				Federal Property:		No	
				Trust Land:		No	
Incident Contacts							
Responsible Authority Contact				Responsible Authority Compliance Contact			
Name: Kim Sayler				Name: Kim Sayler			
Title: Owner/ Secretary				Title: Owner/ Secretary			
Company Name: Royal Farms Transport Inc				Company Name: Royal Farms Transport Inc			
Company Address: PO Box 393, Wishek, ND 58495, United States				Company Address: PO Box 393, Wishek, ND 58495, United States			
Phone: 701-452-2107		24 Hr.Phone:		Phone: 701-452-2107		24 Hr.Phone:	
Email:		Mobile/Pager:		Email:		Mobile/Pager:	
Property Owner Contact							

Incident Report for 5/18/2026 Environmental Incident (ID: 5970)

Incident and Risks

Expected Cause of Transportation Vehicle Human Error, Weather
Accident :

Weather : Heavy Rain

Distance from Nearest Occupied Building :

Distance from Nearest Water Well :

Known Health Risks : none

Nature of Locale where Incident Occurred : Other: county road

Wind Direction : Wind Speed :

Number of Confirmed Injuries : 1

Number of Confirmed Fatalities : 0

Immediate Potential Threats (first 24 Hr) :

Fire: fuel leak

Delayed Potential Threats (after first 24 hr) :

None of the Above: Removed before 24 hours

Response Details

Estimated Clean Up Completion Date :

Protective Actions Taken : Reported incident to insurance, county sheriff, 911, and ND hazmat. Took employee in accident to ER.

Waste Disposal Location :

Other Response Details : reported incident

Evacuations :

No Response Reason :

Shelter In Place :

Clean Up Action Taken :

Incident Chemicals/Released Substances

Pesticides/Herbicides are not involved

CAS Number	Name	Trade Name	Is EHS	Is Radioactive	Estimated Volume	Estimated Volume in Barrels	Estimated Volume in Pounds	Recovered Volume	Recovered Volume in Barrels
N/A	Diesel		No	No	1 gal	0.02	0	0 gal	0
N/A	Milk		No	No	10 gal	0.24	0	0 gal	0

Incident Observations

Note Added Date	Incident Observations
5/19/2026	Spoke with the RP and completed the Incident Report. Verified that the amount of diesel released was confined to a small dripping through the vent cap. The volume of milk spilled was also very low. With no water impacts milk is a non-hazardous substance. A site visit will be made to confirm truck recovery and minimal impacts.
5/18/2026	Received call from trucking company at 2:01 pm. Semi truck with tanker is currently in a steep ditch in McIntosh County at the intersection of 81st st SE and 37th Ave. Some fuel and milk have spilled. The driver sustained minor injuries. RP was guided to start an online incident report and for their company to take all practicable steps to stop the flow of fluids. Follow-up is needed.