

Incident Report for 5/17/2026 Environmental Incident (Incident ID: 5981)

☒ Initial ☐ Update ☐ Close Out

Incident Details		Reporting Party Details	
Description:	North of Banks Lutheran Cemetery/Church approximately 200 yards North of Church approach on west side of ND-1806. Approximate Coordinates 49.99959, -103.19833, Truck Rollover	Incident Date and Time:	5/17/2026 12:05 PM
Incident Type:	Environmental Incident	Incident Subtype :	Vehicle Accident
Source Type:	Transportation	Source Subtype:	Freight Road Transport Vehicle
Incident Status:	Active	Released Into Medium :	Soil
Site Details		Incident Location	
Is Spill Continuous:	No	Is Spill Contained:	Yes
Discovered/Start Date and Time:	5/17/2026 12:05 PM	End Date and Time:	5/17/2026 12:15 PM
Reported to NRC:	No		
Well Name :		NDIC File Number :	
Oil/Gas Operator :		Oil/Gas Field Name :	
Extent of Spill/Release:	Extent Undetermined		
Extent Details:	Supervac Truck Rolled over spilled about 10 bbls of Fresh water and approximately 10 gallons of Hydraulic Oil		
Reporting Party Name:		Sam Hansen	
Reporting Party Phone:		Reporting Party Email:	
Reported Date and Time:		5/21/2026 2:58 PM	
Address:		North of Banks Lutheran Cemetery/Church approximately 200 yards North of Church approach on west side of ND-1806. Approximate Coordinates 49.99959, -103.19833	
Latitude:		47.9995899999992	
Longitude:		-103.1983299999998	
Section:		10	
Township:		152 N	
Range:		98 W	
Quarter:		SE¼	
Qquarter:		NE¼	
Source Water Protection Area:			
County/Tribe:		McKenzie County	
Fire District:		WATFORD CITY FIRE	
Federal Property:		No	
Trust Land:		No	
Incident Contacts			
Responsible Authority Contact		Responsible Authority Compliance Contact	
Name: Sam Hansen		Name: Sam Hansen	
Title: Safety Director		Title: Safety Director	
Company Name: Castle Oilfield Services		Company Name: Castle Oilfield Services	
Company Address: 501 48TH Ave W, Williston, ND 58801, United States		Company Address: 501 48TH Ave W, Williston, ND 58801, United States	
Phone: 701-317-5726		Phone: 701-317-5726	
24 Hr.Phone:		24 Hr.Phone:	
Email:		Email:	
Mobile/Pager:		Mobile/Pager:	
Property Owner Contact			

Incident Report for 5/17/2026 Environmental Incident (ID: 5981)

Incident and Risks

Expected Cause of Transportation Vehicle Unknown
Accident :

Weather : Light Rain

Distance from Nearest Occupied Building : 600 feet

Distance from Nearest Water Well :

Known Health Risks : N/A

Nature of Locale where Incident Occurred : Highway

Wind Direction : Wind Speed :

Number of Confirmed Injuries : 1

Number of Confirmed Fatalities : 0

Immediate Potential Threats (first 24 Hr) :

None of the Above: None Known

Delayed Potential Threats (after first 24 hr) :

None of the Above: Non Known

Response Details

Estimated Clean Up Completion Date : 05/27/2026

Protective Actions Taken : Cleaned up Debris and ensured spill was contained

Evacuations :

Shelter In Place :

Clean Up Action Taken : Cleaned up all debris and ensured hydraulic oil was contained

Waste Disposal Location :

Other Response Details :

No Response Reason :

Incident Chemicals/Released Substances

Pesticides/Herbicides are not involved

CAS Number	Name	Trade Name	Is EHS	Is Radioactive	Estimated Volume	Estimated Volume in Barrels	Estimated Volume in Pounds	Recovered Volume	Recovered Volume in Barrels
128-39-2	ISO-32	INDOL	No	No	10 gal	0.24	0	0 gal	0

Incident Observations

Note Added Date	Incident Observations
5/22/2026	A truck accident occurred that resulted in Hydraulic oil and fresh water being spilled alongside a road. Follow-up needed.
5/22/2026	Company representative was contacted via email regarding completing the report and the issue of delayed reporting.