

Incident Report for 5/25/2026 Oil/Gas Spill (Incident ID: 5986)
☒ Initial ☐ Update ☐ Close Out

Incident Details				Reporting Party Details			
Description:	Flowline developed a hole from corrosion resulting in a release of produced water.	Incident Date and Time:	5/25/2026 12:00 PM	Reporting Party Name:	Dusty Tescher	Reporting Party Company:	Petro Hunt LLC
Incident Type:	Oil/Gas Spill	Incident Subtype :	Equipment Failure	Reporting Party Phone:		Reporting Party Email:	
Source Type:	Fixed Facility	Source Subtype:		Reported Date and Time:	5/26/2026 10:13 AM		
Incident Status:	Active	Released Into Medium :	Soil				
Site Details				Incident Location			
Is Spill Continuous:	No	Is Spill Contained:	Yes	Address:	258 119th Ave SW, Killdeer, ND 58640-_____		
Discovered/Start Date and Time:	5/25/2026 11:50 AM	End Date and Time:	5/25/2026 11:50 AM	Location Description:			
Reported to NRC:	No			Latitude:	48.1127962137682	Longitude:	-102.880680742614
Well Name :		NDIC File Number :		Section:	34	Township:	154 N
Oil/Gas Operator :		Oil/Gas Field Name :		Range:	95 W	Quarter:	SE¼
Company Name:	Petro Hunt LLC	Facility Name:	Section 34 Station	Qquarter:	SW¼	Source Water Protection Area:	
Facility Address:	ND, Keene, ND 58847	Nature of Business:	Oil & Gas production	County/Tribe:	McKenzie County	Fire District:	KEENE FIRE
Extent of Spill/Release:	Confined to Property of Origin - Contained to Pad			Federal Property:	Yes	Trust Land:	No
Extent Details:							
Incident Contacts							
Responsible Authority Contact		Responsible Authority Compliance Contact		Property Owner Contact (Property Owner is Informed)			
Name:	Dusty Tescher	Name:	Dusty Tescher	Name:			
Title:	HSE Director	Title:	HSE Director	Company Name:			
Company Name:	Petro Hunt LLC	Company Name:	Petro Hunt LLC	Company Address:			
Company Address:	390 119th Ave SW, Killdeer, ND 58640, United States	Company Address:	390 119th Ave SW, Killdeer, ND 58640, United States	Phone:			
Phone:	701-260-9647	Phone:	701-260-9647	Email:			
	24 Hr.Phone:		24 Hr.Phone:				
Email:	Mobile/Pager:	Email:	Mobile/Pager:				

Incident Report for 5/25/2026 Oil/Gas Spill (ID: 5986)

Incident and Risks

Expected Cause of Fixed Facility Equipment Failure :	Equipment Failure/Malfunction	Nature of Locale where Incident Occurred : Oil and Gas Facilities	
Weather :	Clear/Sunny	Wind Direction :	Wind Speed :
Distance from Nearest Occupied Building :	1.55 miles	Number of Confirmed Injuries :	0
Distance from Nearest Water Well :	1.55 miles	Number of Confirmed Fatalities :	0
Known Health Risks :	Contaminated surface material		

Immediate Potential Threats (first 24 Hr) :

None of the Above: NA

Delayed Potential Threats (after first 24 hr) :

None of the Above: NA

Response Details

Estimated Clean Up Completion Date :	05/31/2026	Waste Disposal Location :	TBD
Protective Actions Taken :	A catch tank was put under the leak to catch the fluid and a truck was used to recover the fluid and haul it off.		
Evacuations :	No Response Reason : NA		
Shelter In Place :			
Clean Up Action Taken :	Standing fluid was recovered, contaminated soil will be removed and taken to disposal.		

Incident Chemicals/Released Substances

Pesticides/Herbicides are not involved

CAS Number	Name	Trade Name	Is EHS	Is Radioactive	Estimated Volume	Estimated Volume in Barrels	Estimated Volume in Pounds	Recovered Volume	Recovered Volume in Barrels
N/A	Produced Water	Produced Water	No	No	10 bbl	10	0	5 bbl	5

Incident Observations