

Incident Report for 5/24/2026 Environmental Incident (Incident ID: 5991)

☒ Initial ☐ Update ☐ Close Out

Incident Details		Reporting Party Details	
Description:	Release of upto 1,000 lbs of R-134a refrigerant due to system malfunction at the NDARNG RJB Complex, located at 4200 E. Miriam Drive, Bismarck, ND 58501	Incident Date and Time:	5/24/2026 07:00 PM
Incident Type:	Environmental Incident	Incident Subtype :	Equipment Failure
Source Type:	Fixed Facility	Source Subtype:	
Incident Status:	Inactive	Released Into Medium :	Air
Site Details		Incident Location	
Is Spill Continuous:	No	Is Spill Contained:	Yes
Discovered/Start Date and Time:	5/24/2026 07:00 PM	End Date and Time:	5/24/2026 08:00 PM
Reported to NRC:	Yes		
Well Name :		NDIC File Number :	
Oil/Gas Operator :		Oil/Gas Field Name :	
Company Name:	ND Army National Guard	Facility Name:	NDNG - RJB FMS 4 (Tier II Facility ID: 1340)
Facility Address:	4200 East Miriam Ave., Bismarck, ND 58506	Nature of Business:	Military
Extent of Spill/Release:	Extent Undetermined		
Extent Details:	System malfunction from the cooling system, estimated at discharging 1,000 lbs of R-134a into the Air		
Address:		4200 E. Miriam Ave., Bismarck, ND 58501	
Location		Building 4200	
Description:		Latitude: 46.8295537168847 Longitude: -100.720010462518	
Section:		25 Township: 139 N	
Range:		80 W Quarter: SE¼	
Qquarter:		NW¼ Source Water Protection Area:	
County/Tribe:		Burleigh County Fire District: BISMARCK FIRE	
Federal Property:		No Trust Land: No	
Incident Contacts			
Responsible Authority Contact		Responsible Authority Compliance Contact	
Name: Roy Peterson		Name: Andrew Schirado	
Title: Physical Plant Director		Title: Env. Compliance Manager	
Company Name: OTAG / NDARNG		Company Name: OTAG / NDARNG	
Company Address: 4200 E. Miriam Ave., Bismarck, ND 58501, United States		Company Address: 30 Fraine Barracks, Bismarck, ND 58501, United States	
Phone: 701-791-3660 24 Hr.Phone:		Phone: 701-791-3071 24 Hr.Phone:	
Email: Mobile/Pager:		Email: Mobile/Pager:	
Property Owner Contact (Property Owner is Informed)			
Name:			
Company Name:			
Company Address:			
Phone:			
Email:			

Incident Report for 5/24/2026 Environmental Incident (ID: 5991)**Incident and Risks**

Expected Cause of Fixed Facility Equipment Failure :	Equipment Failure/Malfunction	Nature of Locale where Incident Occurred :	Other: Building
Weather :	Clear/Sunny	Wind Direction :	Wind Speed : 0
Distance from Nearest Occupied Building :		Number of Confirmed Injuries :	0
Distance from Nearest Water Well :		Number of Confirmed Fatalities :	0
Known Health Risks :	none		
Immediate Potential Threats (first 24 Hr) :		Delayed Potential Threats (after first 24 hr) :	
None of the Above: R-134a refrigerant release to the Air		None of the Above: R-134a refrigerant release to the Air	

Response Details

Estimated Clean Up Completion Date :	05/24/2026	Waste Disposal Location :	
Protective Actions Taken :	Contact the NRC and reporting to www.spill.nd.gov	Other Response Details :	
Evacuations :		No Response Reason :	atmospherically released
Shelter In Place :			
Clean Up Action Taken :	Working on fixing and refilling the system		

Incident Chemicals/Released Substances

Pesticides/Herbicides are not involved

CAS Number	Name	Trade Name	Is EHS	Is Radioactive	Estimated Volume	Estimated Volume in Barrels	Estimated Volume in Pounds	Recovered Volume	Recovered Volume in Barrels
811-97-2	1,1,1,2 -Tetrafluoroethane	R-134A	No	No	1000 lbs	0	1000	0 lbs	0

Incident Observations

Note Added Date	Incident Observations
5/27/2026	According to the incident, refrigerant was released. Incident will be forwarded to air quality for follow-up.