## 04\_CVD: Red Hat OCP Post-Deployment

## **Red Hat OCP Post-Deployment**

- 1. Setup/Verify NTP setup on all OCP cluster virtual machines (master and worker nodes)
- 2. Verify cluster is registered with <a href="console.redhat.com">console.redhat.com</a>
- 3. Provision affinity rules for master and worker nodes on VMware vCenter
- 4. From Red Hat OCP cluster console, provision **machineset** to modify CPU, memory as needed. <u>NVIDIA User Guide</u> provides the following guidance for worker nodes when using vGPUs:

Resource	Requirements
vCPUs	16
RAM	64 GB
Storage	500 GB thin provisioned virtual disk
NIC	VMXNet 3 NIC connected to network