

Anisotropy orientation (fiber director) maps -- the raw design field, before toolpath delineation


(a)




(b)



(c)



(d)



(e)

