Running IOEDIT

Hanness II needed

If more than

192 I's or o's

- 1) Place diskette containing IOEDIT. COM file into drive A.
- 2) Place diskette containing files created when running compact program into drive B. The files are; compact.MT, SIMFILE.MT, IOTERM.MT, TERMS.MT
- 3) On the Keyboard, type IOEDIT and hit return.
- 4) Follow the user Freindly prompts on the display.

Console display format

IOTERM Harness Editor
Revised 7-8-83

which disk drive is IOTERM. MT in ? B

Which harness do you want to modify?

(1 or 2, Return to put on disk) 1

Enter the term that you want to modify or press return to go
to the next one (enter Q to guit): IXX

IXX = Ø

Enter: the desired column number

A: for auto-increment (the last column was Ø)

Return for no change

1-192