
* . A	1		16
X B	2	G	15
ЖС	3	A T	14
785 VCC	4	Ë	13
X D S	5	_	12
X E S	6	A R	11
X F S	7	R	10
K G- S	8	Y	9 .
		CONTROL OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY.	

N	X
Μ	及
L	×
K	X
VEE	WEE
J	*
I	X
Н	义



K, M = I J + C D + E F + G H + A ; T  
7,6 = 10 9 + 14 15 + 16 1 + 2 3 + 11 ; 13  

$$\overline{K}$$
,  $\overline{M}$  =  $\overline{I}$  J +  $\overline{C}$  D +  $\overline{E}$  F +  $\overline{G}$  H +  $\overline{A}$  ; T  
8, 5 = 10 9 + 14 15 + 16 1 + 2 3 + 11 ; 13

## Macro Definition:

CRAY RESEARCH, INC. COMPANY PRIVATE

Type: X Power Dissipation: -5.2V. -2.0V. LOADING FOR MIT