When drawing foil paths from a jumper to a chip hole and then to a resistor it should be drawn that way as the best case. If for some reason it can not be drawn in that manner it can be drawn from the chip hole to the jumper then to the resistor, use this only as a last resort.

