Foil paths must start at the center of a hole location and end in the center of another hole location. This includes chip holes, resistors, grounds jumpers and via's.

