
A CONSTANT NUMBER IS ADDED TO THE COEFFICIENT WHEN ANY INSTRUCTION IS ISSUED THAT USES THE FLOATING MULTIPLY UNIT. A ROUNDING NUMBER IS ADDED IN AFTER THE PYRAMID IS FORMED. THERE ARE THREE DIFFERENT ROUNDING NUMBERS AND A DIFFERENT ONE IS ADDED, DEPENDING ON THE INSTRUCTION TYPE. THE VARIATIONS ARE ILLUSTRATED IN THE FOLLOWING DIAGRAMS.



COEFFICIENT ROUND CONTROL