TA and puts

¥ ,	VECTOR MASK, RTC, AND
LOCAL MEMORY CONTROL	VECTOR LOGICAL CONTROL
JA WA	JA VL
TERM TERM DEFINITION	TERM TERM DEFINITION
ONA IIA ENABLE CONSTANT READ	OTA IIA GO MASK
ONB IIB ENABLE CONSTANT WRITE	OTB IIB ENTER M FROM Sj
	OTC IIC "M" OR "RTC" TO Si
	OTD IID GO VECTOR
SCALAR SHIFT CONTROL	OTE IIE F 20
Boilding Billing Continue	OTF IIF F 2 <sup>1</sup>
JA GB	OTG IIG F 2 <sup>2</sup>
TERM TERM DEFINITION	
TERM DEFINITION	
OOA-OOF INA-INF JK DATA (SHIFT COUNT)	FLOATING ADD CONTROL
Designation and Designation an	
	JA FA
	TERM TERM DEFINITION
OQC IOC AK SHIFT	That that builting
	OUA IJA ENABLE VECTOR ADD
COLLAR TAMPOND INCH COMMON	OUB IJB ENABLE SCALAR ADD
SCALAR INTEGER UNIT CONTROL	OUC IJC 20 OF "F" FIELD
JA GA	2
TERM TERM DEFINITION	OUE IJE 22 OF "F" FIELD
OPA IPA GO BIT	THE SAME WITH STRUCK COMMISSION
OPB IPB F 20	FLOATING MULTIPLY CONTROL
OPC IPC F 21	
OPD IPD K 2 <sup>0</sup>	JA ME
	TERM TERM DEFINITION
	00 00000
VECTOR ADD CONTROL	OVA IVA GO SCALAR MUTIPLY
	OVB IVB GO SCALAR RECIP./SQ. RT.
JA VA	OVC IVC GO VECTOR MULTIPLY
TERM TERM DEFINITION	OVD IVD GO VECTOR RECP./SQ. RT.
	OVE IVE 20 OF "F" FIELD
ORA IRA GO VECTOR ADD	OVF IVF 2 <sup>1</sup> OF "F" FIELD
ORB IRB 20 OF "F" FIELD	
ORC IRC 2 <sup>1</sup> OF "F" FIELD	
ORD IRD GO COMPRESS IOTA	BACKGROUND PORT STATUS REG. CONTROL
	JA EA
VECTOR SHIFT, POP COUNT,	TERM TERM DEFINITION
LEADING ZERO CONTROL	
Es al	OXA IHA 20 OF "K" FIELD
JA VB	OXB IHB 21 OF "K" FIELD
TERM TERM DEFINITION	OXC IHC ENABLE ERROR MODE CHANGE
-	
OSA ISA GO SHIFT	
OSB ISB 20 OF "F" FIELD	
OSC ISC: 21 OF "F" FIELD	
OSD ISD GO POP/LEADING ZERO	
OSE ISE 20 OF "K" FIELD	
	14

C0012S0501