Scalar Leading Zeroes Count Functional Unit

Function: Scalar leading zeroes count

Module : GA

Instruction Summary

107ij- Enter Si with leading zero count in Sj