





2025 Rd05 Saudi Arabian Grand Prix Practice 3 Fastest Lap: 01:27.489 (NOR)








































| | Time | Category | Message | Status | Flag | Scope | Sector | RacingNumber | Lap |
|----|---------------------|----------|---|--------|-----------|--------|--------|--------------|-----|
| 0 | 2025-04-19 13:16:20 | 0ther | PINK HEAD PADDING MATERIAL MUST BE USED | | | | nan | | |
| 1 | 2025-04-19 13:30:01 | Flag | GREEN LIGHT - PIT EXIT OPEN | | GREEN | Track | nan | | |
| 2 | 2025-04-19 13:35:12 | 0ther | INCIDENT INVOLVING CAR 7 (DOO) NOTED - FAILING TO FOLLOW RACE DIRECTORS INSTRUCTIONS | | | | nan | | |
| 3 | 2025-04-19 13:36:23 | 0ther | FIA STEWARDS: INCIDENT INVOLVING CAR 7 (DOO) WILL BE INVESTIGATED AFTER THE SESSION - FAILING TO FOLLOW RACE DIRECTORS INSTRUCTIONS | | | | nan | | |
| 4 | 2025-04-19 13:44:33 | 0ther | INCIDENT INVOLVING CAR 7 (DOO) NOTED - FAILING TO FOLLOW RACE DIRECTORS INSTRUCTIONS | | | | nan | | |
| 5 | 2025-04-19 13:46:06 | 0ther | FIA STEWARDS: INCIDENT INVOLVING CAR 7 (DOO) WILL BE INVESTIGATED AFTER THE SESSION - FAILING TO FOLLOW RACE DIRECTORS INSTRUCTIONS | | | | nan | | |
| 6 | 2025-04-19 14:21:13 | Flag | YELLOW IN TRACK SECTOR 17 | | YELLOW | Sector | 17.0 | | |
| 7 | 2025-04-19 14:21:14 | 0ther | DRS DISABLED IN ZONE 2 | | | | nan | | |
| 8 | 2025-04-19 14:21:16 | 0ther | DRS ENABLED IN ZONE 2 | | | | nan | | |
| 9 | 2025-04-19 14:21:16 | Flag | CLEAR IN TRACK SECTOR 17 | | CLEAR | Sector | 17.0 | | |
| 10 | 2025-04-19 14:30:00 | Flag | CHEQUERED FLAG | | CHEQUERED | Track | nan | | |
| 11 | 2025-04-19 14:30:07 | 0ther | FIRST CAR TO TAKE THE FLAG - CAR 31 (OCO) | | | | nan | | |