Dell Red Hat Cloud Solutions Bill of Materials Guide - Version 2.0



Contents

Trademarks	3
Notes, Cautions, and Warnings	4
Overview	5
Pilot Bundle Bill of Materials - PowerEdge R620	6
Pilot Bundle Bill of Materials PowerEdge - R720xd Storage Node	8
Bill of Materials - Networking Force10 S4810 and S55 Server Racks and Power Networking Equipment	11
References	

Trademarks Page 3

Trademarks

© 2014 Dell Inc. All rights reserved. Reproduction of this material in any manner whatsoever without the express written permission of Dell Inc. is prohibited. For more information, contact Dell. Dell, the Dell logo, and the Dell badge, and PowerEdge are trademarks of Dell Inc.

Trademarks used in this text: Dell[™], the DELL logo, Dell Precision[™], OptiPlex[™], Latitude[™], PowerEdge[™], PowerVault[™], PowerConnect[™], OpenManage[™], EqualLogic[™], KACE[™], FlexAddress, Force10[™], and Vostro[™] are trademarks of Dell Inc. Intel[®], Pentium[®], Xeon[®], Core[®], and Celeron[®] are registered trademarks of Intel Corporation in the U.S. and other countries. AMD[®] is a registered trademark and AMD Opteron[™], AMD Phenom[™], and AMD Sempron[™] are trademarks of Advanced Micro Devices, Inc. Microsoft[®], Windows Server[®], MS-DOS[®], and Windows Vista[®] are either trademarks or registered trademarks of Microsoft Corporation in the United States and/or other countries.

Red Hat®, Red Hat® Enterprise Linux®, the Shadowman logo, and JBoss are trademarks of Red Hat, Inc., registered in the U.S. and other countries. Linux® is the registered trademark of Linus Torvalds in the U.S. and other countries. Novell® is a registered trademark and SUSE™ is a trademark of Novell Inc. in the United States and other countries. Oracle® is a registered trademark of Oracle Corporation and/or its affiliates. Citrix®, Xen®, XenServer® and XenMotion® are either registered trademarks or trademarks of Citrix Systems, Inc. in the United States and/or other countries. VMware®, Virtual SMP®, vMotion®, vCenter®, and vSphere® are registered trademarks or trademarks of VMware, Inc. in the United States or other countries.

DISCLAIMER: The OpenStack® Word Mark and OpenStack Logo are either registered trademarks/ service marks or trademarks/service marks of the OpenStack Foundation, in the United States and other countries, and are used with the OpenStack Foundation's permission. We are not affiliated with, endorsed or sponsored by the OpenStack Foundation or the OpenStack community.

Other trademarks and trade names may be used in this publication to refer to either the entities claiming the marks and names or their products. Dell Inc. disclaims any proprietary interest in trademarks and trade names other than its own.

Notes, Cautions, and Warnings

- A **Note** indicates important information that helps you make better use of your system.
- A **Caution** indicates potential damage to hardware or loss of data if instructions are not followed.
- A **Warning** indicates a potential for property damage, personal injury, or death.

This document is for informational purposes only and may contain typographical errors and technical inaccuracies. The content is provided as is, without express or implied warranties of any kind.

Overview Page 5

Overview

This guide provides Bill of Material information necessary to purchase the proper hardware to deploy the Dell Red Hat Cloud Solutions with Red Hat Enterprise Linux[™] OpenStack.

This hardware includes Dell R620, R720, and R720xd servers with Dell PowerEdge H710 disk controllers; and Dell Force10 S4810 and S55 network switches.

Please consult with your Dell sales representative to ensure proper preparation and submission of your hardware and software orders.

Pilot Bundle Bill of Materials - PowerEdge R620

Table 1: Bill of Materials - PowerEdge R620 Nodes

SKU	Description
210-ABVQ	PowerEdge R620, Intel Xeon E-26XX v2 Processors
591-BBBQ	PowerEdge R620 Motherboard, TPM
317-8730	Chassis with up to 4 Hard Drives and 3 PCIe Slots
331-4822	Cable for Mini PERC Cards in Chassis with up to 4 Hard Drives
331-4761	PowerEdge R620 Shipping - 4/8 Drive Chassis
317-8585	Intel Xeon E5-2665 2.40GHz, 20M Cache, 8.0GT/s QPI, Turbo,8C, 115W, Max Mem 1600MHz
317-8688	DIMM Blanks for Systems with2 Processors
331-4762	Heat Sink for PowerEdge R620(2)
317-8460	Intel Xeon E5-2665 2.40GHz, 20M Cache, 8.0GT/s QPI, Turbo,8C, 115W
331-4424	1600 MHz RDIMMS
331-4428	Performance Optimized
319-1812	16GB RDIMM, 1600MT/s, Low Volt, Dual Rank, x4 Data Width(Qty 8)
331-4234	RAID 1+RAID 1 for H710P/H710/H310 (2 + 2 HDDs)
342-3531	PERC H710P Integrated RAID Controller, 1GB NV Cache
342-5514	1.2TB 10K RPM SAS 6Gbps 2.5in Hot-plug Hard Drive(4)
421-5339	iDRAC7 Enterprise
430-4447	Intel Ethernet I350 QP 1Gb Network Daughter Card
430-4446	Intel X520 DP 10Gb DA/SFP+ Server Adapter, Low Profile(Qty 2)
332-0333	Dual, Hot-plug, Redundant Power Supply (1+1), 750W, Titanium, 200-240VAC
330-3151	Power Cord, C13 to C14, PDU Style, 12 Amps, 2 meter, (Qty 2)
330-5116	Power Saving Dell Active Power Controller
331-4766	331-4766 ReadyRails Sliding Rails Without Cable Management Arm

SKU	Description	
313-0869	No Bezel	
318-1392	No Internal Optical Drive	
331-4513	Electronic System Documentation and OpenManage DVD Kit	
421-4727	Red Hat Enterprise Linux NonFactory Install, x64,Reqs Subscription Selection	
421-6929	Red Hat Enterprise Linux for HPC, 1-2 Socket, 3yr Subscription and Licensing	
421-5737	Red Hat Enterprise Linux 6.4Media Only X86_64, No Subscription, Factory Install	
939-4668	Dell Hardware Limited Warranty Plus On Site Service Extended Year	
989-3439	Dell ProSupport. For tech support, visit http://www.dell.com/learn/us/en/19/services/support-services-prosupport-for-enterprise or call 1-800-945-3355	
936-9493	ProSupport: Next Business Day Onsite Service After ProblemDiagnosis, 2 Year Extended	
989-5221	ProSupport: Next Business Day Onsite Service After ProblemDiagnosis, Initial Year	
936-9503	ProSupport: 7x24 HW / SW Tech Support and Assistance, 3 Year	
936-1787	Dell Hardware Limited Warranty Plus On Site Service Initial Year	
900-9997	On-Site Installation Declined	
973-2426	Declined Remote Consulting Service	
926-2979	Proactive Maintenance Service Declined	

Pilot Bundle Bill of Materials PowerEdge - R720xd Storage Node

Table 2: Bill of Materials - PowerEdge R720xd Storage Nodes

SKU	Description	
91-BBBP	PowerEdge R720 Motherboard, TPM	
210-ABMY	PowerEdge R720xd, Intel XeonE-26XX Processors	
342-3567	Chassis with up to 12, 3.5" Hard Drives	
331-4437	PowerEdge R720 Shipping	
338-BDBD	Intel Xeon E5-2650v2 2.6GHz,20M Cache, 8.0GT/s QPI, Turbo, HT, 8C, 95W, Max Mem 1866MHz	
317-8688	DIMM Blanks for Systems with2 Processors	
331-4508	Heat Sink for PowerEdge R720and R720xd (Qty 2)	
338-BDBS	Intel Xeon E5-2650v2 2.6GHz,20M Cache, 8.0GT/s QPI, Turbo, HT, 8C, 95W, Max Mem 1866MHz,2nd Proc	
331-4424	1600 MHz RDIMMS	
331-4428	Performance Optimized	
319-1812	16GB RDIMM, 1600MT/s, Low Volt, Dual Rank, x4 Data Width (Qty 8)	
331-4590	RAID 6 for H710P/H710 (4-24 HDDs)	
342-3529	PERC H710 Integrated RAID Controller, 512MB NV Cache	
342-1865	2TB 7.2K RPM SATA 3Gbps 3.5in Hot-plug Hard Drive (Qty 12)	
421-5339	iDRAC7 Enterprise	
430-4447	Intel Ethernet I350 QP 1Gb Network Daughter Card	
430-4445	Intel X520 DP 10Gb DA/SFP+ Server Adapter (Qty 2)	
331-4605	Dual, Hot-plug, Redundant Power Supply (1+1), 750W	
330-3151	Power Cord, C13 to C14, PDU Style, 12 Amps, 2 meter, (Qty2)	
330-5116	Power Saving Dell Active Power Controller	
331-4434	ReadyRails Sliding Rails Without Cable Management Arm	
318-1375	Bezel	

SKU	Description
331-5914	Electronic System Documentation and OpenManage DVD Kit forR720 and R720xd
420-6320	No Operating System
421-5736	No Media Required
331-3765	UEFI BIOS Setting
989-2701	ProSupport: Next Business Day Onsite Service After ProblemDiagnosis, Initial Year
989-3439	Dell ProSupport. For tech support, visit http://www.dell.com/learn/us/en/19/services/support-services-prosupport-for-enterprise or call 1-800-945-3355
939-3398	Dell Hardware Limited Warranty Plus On Site Service Extended Year
936-7263	ProSupport: 7x24 HW / SW Tech Support and Assistance, 3 Year
936-0967	Dell Hardware Limited Warranty Plus On Site Service Initial Year
936-7243	ProSupport: Next Business Day Onsite Service After ProblemDiagnosis, 2 Year Extended
900-9997	On-Site Installation Declined
926-2979	Proactive Maintenance Service Declined

Bill of Materials - Networking Force10 S4810 and S55

Table 3: Bill of Materials - Networking Force10 S4810 and S55

SKU	Description
Force10 S4810	
225-2479	Force10, S4810P, 1RU, 48 x 10GbE SFP+, 4 x 40GbE QSFP+, 1 x AC PSU, 2 x FM, PSU to IO Panels (Reverse) (Qty 2)
331-9233	No Returns Allowed on Dell Networking Switches (Qty 2)
331-6279	Force10, User Documentation for S4810, DAO/ BCC (Qty 2)
935-0143	ProSupport: 7x24 HW / SW Tech Support and Assistance, 3 Years (Qty 2)
989-3439	Dell ProSupport. For tech support, visit http://www.dell.com/learn/us/en/19/services/support-services-prosupport-for-enterprise or call 1-800-945-3355 (Qty 2)
996-2670	Dell Hardware Limited Warranty Initial Year (Qty 2)
996-2760	Dell Hardware Limited Warranty Extended Year(s) (Qty 2)
936-9034	ProSupport: Next Business Day Onsite Service After ProblemDiagnosis, 2 Year Extended
935-0103	SW Support,Force10 Software ,3 Years (Qty 2)
936-9014	ProSupport: Next Business Day Onsite Service After ProblemDiagnosis, Initial Year (Qty 2)
900-9997	On-Site Installation Declined (Qty 2)
973-2426	Declined Remote Consulting Service (Qty 2)
331-5105	Force10, S4810P, AC Power Supply, PSU to IO Panels (Reverse) (Qty 2)
470-AAFE	Dell Networking, Cable, QSFP+ to QSFP+, 40GbE Passive Copper Direct Attach Cable, 1 Meter (Qty 2)
470-AAGP	Dell Networking, Cable, SFP+to SFP+, 10GbE, Copper TwinaxDirect Attach Cable, 3 Meter (Qty 48)
450-AASX	Power Cord, 250V, 12A, 2 Meters, C13/C14 (Qty 4)
332-0139	Force10 Customer not deploying this switch in iSCSI or FCOE environment. (Qty 2)
331-5393	Force10, Rear Rack Mounting Bracket, 4 Post, S4810 (Qty 2)

SKU	Description
Force10 S55	
225-2504	Force10, S55, 1RU, 44 x 10/100/1000 BASE-T, 4 x 1GbE SFP, 1 x AC PSU, 2 x FM, PSU to IO Panels (Reverse)
331-5392	Force10, Adapter, Card, 10 GbE, 2 Port, SFP+, S55
331-5244	Force10, S55, AC Power Supply, PSU to IO Panels (Reverse)
450-AASX	Power Cord, 250V, 12A, 2 Meters, C13/C14 (Qty 2)
331-5252	Force10, Rear Rack Mounting Bracket, 4 Post, S55
331-6271	Force10, User Documentation for S55/S60, DAO/BCC
995-0622	ProSupport: 7x24 HW / SW Tech Support and Assistance, 3 Years
936-8714	ProSupport: Next Business Day Onsite Service After ProblemDiagnosis, Initial Year
936-8734	ProSupport: Next Business Day Onsite Service After ProblemDiagnosis, 2 Year Extended
995-9649	SW Support,Force10 Software ,5 Years
989-3439	Dell ProSupport. For tech support, visit http://support.dell.com/ProSupport or call 1-800-945-3355
935-1367	Dell Hardware Limited Warranty Initial Year
938-7578	Dell Hardware Limited Warranty Extended Year(s)
996-0540	Force10, 5 Year Return To Depot Service, Base Warranty
923-2669	Remote Implementation of a Layer 2 Ethernet Switch
973-2426	Declined Remote Consulting Service
331-9233	No Returns Allowed on Dell Networking Switches
	ļ.

Server Racks and Power

Table 1 and Table 2 above do not include racks or power distribution units, as they are generally site specific. The physical dimensions and power requirements need to be reviewed. The R720 and R720xd both require rear cable management and power distribution.

Networking Equipment

Table 3 includes switches that have specific air flow options.

There are both I/O to PSU SKU numbers and PSU to I/O side options available for reverse air flow. Redundant FANs (other than the minimum supplied with chassis) should also be same direction as the base switch. The airflow cannot be reversed in the field at this time



Note: The networking SKUs lists show the AC power supplies only. All switch models are available in DC as well.

Table 3 includes the necessary cables for the connections between the switches for uplinks and interconnects.

The BOMs include the cables required for connecting the individual servers into the cluster, since the exact cables required depend on the final chosen rack layout, and choice of cable is often based on customer preference. The following tables summarize the cable counts required, including BMC connections:

Table 4: Network Cables Required – Pilot Bundle and 10GbE Configurations

Description	1GbE Cables Required	10GbE Cables Required
All Nodes	2 x number of nodes	4 x number of nodes

References Page 13

References

Additional information can be obtained at http://www.dell.com/openstack or by e-mailing openstack@dell.com.

If you need additional services or implementation help, please contact your Dell sales representative.

To Learn More

For more information on the Dell Red Hat Cloud Solutions with Red Hat Enterprise Linux $^{\text{\tiny M}}$ OpenStack Platform visit $\frac{http://www.dell.com/openstack}{}$.

© 2014 Dell Inc. All rights reserved. Trademarks and trade names may be used in this document to refer to either the entities claiming the marks and names or their products. Specifications are correct at date of publication but are subject to availability or change without notice at any time. Dell and its affiliates cannot be responsible for errors or omissions in typography or photography. Dell's Terms and Conditions of Sales and Service apply and are available on request. Dell service offerings do not affect consumer's statutory rights.

Dell, the DELL logo, and the DELL badge, PowerConnect, and PowerVault are trademarks of Dell Inc.