## Establish parameter variables and geometry to duplicate

You will create a proxy object for the assembly. Use the proxy object to indicate the characteristics that you want to reuse.

In this example, you will create a proxy object without assigning a physics variable to it. You will use this proxy object to create multiple instances of a joint.

1. Choose **Home** tab→**Mechanical** group→**Proxy Object** 

2. In the graphics window, select **Solid Body in mcd01\_motor**.



3. In the Name group, type proxy base, and then click Apply.
In the Physics Navigator, under the Basic Physics group, the proxy object is displayed.

4. In the Rename dialog box, click Yes