

EXPRESS DIAGNOSTICS

Advanced Vehicle Diagnostic & ADAS Analysis Report

Report Type	DTC Analysis & ADAS Operations Review
DTCs Found	6
Generated By	Express Diagnostics

Scan Summary

The scan report was processed and 6 Diagnostic Trouble Code(s) were identified for review.

Detected DTCs & Analysis

DTC	U0140:00-08
Description	Lost Communication With Body Control Module CMDTCs
What This Means	This code indicates a detected fault in the related vehicle system or module.
Possible Causes	Wiring issue, connector damage, low voltage event, module fault, sensor fault, or communication
Recommended Action	Perform pinpoint diagnostics, inspect related wiring/connectors, repair the root cause, clear code

DTC	B1445:15-48
Description	Rear park lamps output CMDTCs
What This Means	This code indicates a detected fault in the related vehicle system or module.
Possible Causes	Wiring issue, connector damage, low voltage event, module fault, sensor fault, or communication
Recommended Action	Perform pinpoint diagnostics, inspect related wiring/connectors, repair the root cause, clear code

DTC	B153E:08-08
Description	Trailer Hitch Light Output CMDTCs
What This Means	This code indicates a detected fault in the related vehicle system or module.
Possible Causes	Wiring issue, connector damage, low voltage event, module fault, sensor fault, or communication
Recommended Action	Perform pinpoint diagnostics, inspect related wiring/connectors, repair the root cause, clear code

DTC	B115E:08-08
Description	Camera Module CMDTCs
What This Means	This code indicates a detected fault in the related vehicle system or module.
Possible Causes	Wiring issue, connector damage, low voltage event, module fault, sensor fault, or communication
Recommended Action	Perform pinpoint diagnostics, inspect related wiring/connectors, repair the root cause, clear code

DTC	U0140:00-08
Description	Lost Communication With Body Control Module CMDTCs
What This Means	This code indicates a detected fault in the related vehicle system or module.

Possible Causes	Wiring issue, connector damage, low voltage event, module fault, sensor fault, or communication
Recommended Action	Perform pinpoint diagnostics, inspect related wiring/connectors, repair the root cause, clear code

DTC	U0146:00-08
Description	Lost Communication With Serial Data Gateway A CMDTCs
What This Means	This code indicates a detected fault in the related vehicle system or module.
Possible Causes	Wiring issue, connector damage, low voltage event, module fault, sensor fault, or communication
Recommended Action	Perform pinpoint diagnostics, inspect related wiring/connectors, repair the root cause, clear code

ADAS Operations & Verification

- 1 Pre-scan and post-scan documentation
- 2 ADAS module verification
- 3 Camera/radar calibration if required by OEM procedures
- 4 Network communication verification
- 5 Road test and functional validation after repairs

Final Note: ADAS calibration requirements must be verified using OEM repair procedures based on the vehicle, repair area, affected modules, and scan results.

EXPRESS DIAGNOSTICS — Precision. Safety. Confidence.