

80-BUS NEWS

NOVEMBER-DECEMBER 1983

VOL. 2 ISSUE 6

- NASPAS REVIEW
- ACCESSING PRETEL
- NUMBER CRUNCHER BENCHMARKS



The Magazine for
NASCOM & GEMINI USERS

£1.50

CONTENTS

Page 3	Editorial
Page 3	Classified Advertisements
Page 5	Dave Hunt on: Disk Reliability
Page 8	Drive Care
Page 9	Keyboard Reliability
Page 11	Letters - Polydos, Naspen, SYS
Page 12	Review - Naspas
Page 14	Disk Drive Compatibility
Page 15	Doctor Dark's Diary - 19
Page 20	Letter to the Editor
Page 21	Accessing Prestel
Page 29	Installing an 8" Disk Drive
Page 31	NASCOM BASIC Disassembled - Part 4
Page 39	Book Reviews
Page 42	Forthcoming Pascal Review
Page 43	Aunt Agatha's Agony Column
Page 48	Addendum to the Belectra Review
Page 49	Dave Hunt Again on: Animal Antics
Page 50	Impending Doom
Page 51	Modems
Page 53	HDLC & Packet Radio
Page 56	Nascom News
Page 56	Letters - Programs
Page 60	COMAL-80, Disks, Naspen
Page 61	More Happy Talk - computer communications
Page 63	Three Simple Nascom 2 Modifications
Page 65	Random Rumours (& Truths?)
Pages 14,48,66,67	Advertisements

All material copyright (c) 1984 by Interface Data Ltd. No part of this issue may be reproduced in any form without the prior consent in writing of the publisher except short excerpts quoted for the purposes of review and duly credited. The publishers do not necessarily agree with the views expressed by contributors, and assume no responsibility for errors in reproduction or interpretation in the subject matter of this magazine or from any results arising therefrom. The Editor welcomes articles and listings submitted for publication. Material is accepted on an all rights basis unless otherwise agreed. Published by Interface Data Ltd. and printed by Kensons Ltd., High Wycombe.

SUBSCRIPTIONS

Annual Rates (6 issues)	UK £9	Rest of World Surface £12
	Europe £12	Rest of World Air Mail £20

Subscriptions to 'Subscriptions' at the address below.

EDITORIAL

Editor : Paul Greenhalgh Associate Editor : David Hunt

Material for consideration to 'The Editor' at the address below.

ADVERTISING

Rates on application to 'The Advertising Manager' at the address below.

ADDRESS: 80-BUS News,
Interface Data Ltd.,
Woodside Road,
Amersham, Bucks, HP6 5EW.

EDITORIAL

An apology

Sorry; a little late again. My fault. Too much working and socialising and not enough editing. Anyway, this is the latest effort and I trust that you enjoy reading it and find a number of useful items in it.

Future issues

I have recently received a number of conflicting letters concerning the type of article that we publish. Some say "I now find very little of interest in the magazine" whilst others say "80-BUS News is invaluable - there is so much useful information in every issue that is just not available elsewhere" - both of these are actual quotes, both are probably right, but I'm pleased to say that the latter is the more frequent. It obviously depends on your individual interests, and there is no doubt that there is a fairly wide cross-section of readership. Really all I can do is repeat, for newcomers, what has been said before. All articles published in 80-BUS News are non-commissioned items received from readers. From these potential articles I select a cross-section of items to cover as wide a range of topics that I believe will be of reasonably wide interest. In the main this seems to be very successful, but starting with the next issue I will also start to include the occasional article that, in my own opinion, is aimed at a much more specialised area than normal. I await any feedback with interest. Incidentally, this means that if you have submitted an article that has not yet materialised, you are now in with a chance!

Money

Owing to a little internal problem there are a couple of contributors to this esteemed publication who have not been remunerated for their efforts, and with whom we have lost contact. If this is you then please drop us a line stating the article for which payment is required. We will then try to oblige!

And finally

A belated Happy New Year to all our readers!

CLASSIFIED ADS

Nascom 1, 3 amp PSU, Cottis Blandford cassette interface, NAS-GRA graphics ROM, Space Invaders/Defender graphics ROM, NAS A/N in EPROM, NAS-SYS 3, Assemblers, Disassemblers, Debug, BASIC, 9 slot motherboard (4 fitted), also Nascom bufferboard and Micropower 64K RAM/buffer/programmable graphics (RAM and both buffers faulty but diagnosed). All documentation, many other goodies. Purchase of N2 forces sale. £130. Phone Canterbury (0227) 710720.

Nascom 1, 48K, ZEAP, Nas-Sys 3, Hobbit micro-cassette drive and tapes, EPROM programmer, I/O board. Make me an offer. Phone Paul on Macclesfield (0625) 72988 evenings.

Nascom 1 with 32K RAM, B-BUG monitor in ROM. High speed cassette interface, teletype interface, floppy disk control card and drive unit. All built into a Harris VDU terminal, plus Teletype printer. Software - BASIC & assembler on disk and all documentation. £400 the lot, or prepared to split up. Tel. Mr Taylor, Boldon 362165.

Nascom 2 with 48K RAM, Nas-Sys 3 Monitor, BASIC Toolkit, Graphics EPROM, assembled in case with manuals and 9 spare 416 -2 memories. Offers around £100. D. Parkinson, 104 Sompting Road, Lancing, West Sussex. (0903) 765714.

Nascom 2 with 48K RAM B board in Vero rack. Manuals, games, 80-BUS News and Tandy monitor. £130 ono. AVT Monitor, as new. £65. 08675 3750 (Oxford).

Nascom 2, 48K, spare RAM A board, Holmes colour graphics PCB + ROMs (unpopulated), all documentation, a few games. £220 or offers. Tel. Eastleigh (Hants) 617214.

Nascom 2, 48K, Nas-Sys 3, ZEAP, Nas-Dis & Debug, BASIC toolkit, 6800 cross compiler, parallel printer cable etc. £250. Ian Doble, St. Agnes (087255) 2121

Nascom 2 in Kenilworth case with fan; 40K RAM, I/O board with Uart + 1 PIO, display monitor. Nas-Sys 3, BASIC toolkit, Hullforth, Wordease, V&T Assembler and games. Manuals and large number of Nascom related magazines. All above + IMP printer & IMPRINT that needs attention for £350. Taylor - 029668 651 evngs

Nascom 2, RAM B 48K, Sound board and sound programs, 12K Pascal, ZEAP, Nas-Dis, Debug, Naspen & lots of games. Monitors Nas-Sys 1 & 3. Including all manuals & newsletters - £400. Also RAM A memory board £25. U. Soni, 32 Downs Rd., Lower Clapton, London E5.

Nascom 2 + RAM B board giving 48K RAM, Toolkit, Nas-Gra, Soundbox, Castle Interface, IMP printer, Naspen, Imprint, spare printer ribbon, tape recorder, all cased as a compact system. User manuals. £500 the lot. T. R. Kirby-Smith, San Cass, 22 Pantiles Close, St Johns, Woking, Surrey, GU21 1PT. Woking 72739.

Nascom 2 cased with 48K RAM B, AVC, ZEAP, Naspen, Nasprint 80, Nas-Dis/Debug, Pascal. Offers over £550. Waterlooville (Hants) 52314.

Nascom 2, 32K RAM, I/O board, Kenilworth case, GM805 disk system, software - Pascal, ZEAP, Naspen, Nas-Dis/Debug. £650. Ring Steve for details 0969 23459.

Micropolis 400K floppy disk drive, second drive, hardly used, upgrading to a RAM-DISK system. £180 ono. Roy Ward, Macclesfield 610678.

Nas-Sys 1 (ROM) - £6; ZEAP (4x2708) - £22; Bits & PCs Programmers Aid (Nas-Sys 1) - £10; Naspen - £10. Also: Easicomp sound generator (AY-3-8910 type) on 80-BUS board - £30, and IMP printer (+ IMPRINT) - £140 ono. Ring Plymouth 709722 (evenings).

O level standard multiple choice examination program. Basic program - insert your own data £3.00. Full program with data £5.00. SAE for details of subjects. Robert Wood, The Limes, Druidstone Road, St. Mellows, Cardiff, CF3 9XD. Phone (0222) 791435

WANTED - The buffer board section of a Micropower 64K RAM, P.C.G., buffer board. Any reasonable price considered. D.G.Richards, 29 Martin Crescent, Tonyrefail, Mid. Glam., CF39 8NT. Tel. Tonyrefail (0443) 676676 (after 12 noon).

DH's ODD MUSINGS AND LETTERS**By D. R. Hunt**Disk reliability

Now all those with disk systems will be aware that those square 5" (and 8") black plastic things known as disks are relatively expensive, and that even though disks are fast, prolific code or text writers, or itinerant software lifters will be fully aware that their capacity is limited and that new disks will be required sooner or later. Those blessed with high capacity disk drives, 400K - 800K per drive, et al, will be in the fortunate position of having to purchase fewer disks than those who only have, say, 70K per drive. However, if you believe the propaganda, those with high capacity drives will have to pay more for their disks anyway. Well, I propose to have a brief look at disks, and from my own experience, dispel a few old wives tales, and probably create a few heresies in the eyes of the manufacturers.

Firstly, let's have a look at the different breeds of disks, they are available from about £15.00 per ten to about £50.00 per ten, so what has one manufacturer got over another for the price? Well firstly, there are a lot fewer disk manufacturers than there are brands of disk. A lot of badge engineering goes on, not only sticking a particular computer manufacturers' name on the disk and shoving the price up accordingly, but also producing the same disk with different labels to sell in different markets at different prices.

Disk Oxides

Now on to the oxides used on the disks: once upon a time I used to read everything I could on the various types of chemistry that went into the manufacture of magnetic oxides for recording purposes, and the ground rules laid down for audio recording are in many ways the same for digital data recording.

Without being in the least technical, and committing my first heresy by making the broadest of generalisations, there are two types of oxide, the dull brown stuff and the shiny black stuff. In general the brown stuff is softer (physically) than the black stuff and slightly more prone to wear than the black stuff. However, the brown stuff requires considerably less recording head current to reach magnetic saturation, and so is more suited to drives which have low head currents. The reverse is true of the black stuff, it is (physically) harder and requires considerably more head current to saturate the media.

Ignoring the wearing capabilities of the disks, which in normal home use are minimal anyway, it seems the choice of magnetic material is down to the head recording currents of the drives, in other words, those drives with lower head currents would prefer disks coated in the brown pudding, whilst those with higher head currents would prefer those with the black pudding but will work equally as well on the brown pudding. So how do you know which type of drive you have? Unfortunately this is the sort of information that manufacturers of drives don't tell you as the information is contained in the OEM (Original Equipment Manufacturers) technical manual, and you usually aren't privy to these. Apart from that, how would you know whether the head current given in the manual to create a saturation of X mWebers is high, low or indifferent without samples of all the drives around? Fortunately, the solution is easier than this, if somewhat empirical. If the drive was designed (designed, not necessarily manufactured) more than about 5 years ago, it is almost certainly more suited to the brown pudding. More recent designs keep step with improving media technology (lovely buzz phrase that, media technology) and would be suitable for both the brown and black puddings.

Testing Disk Suitability

One way to test the suitability of a disk is to do a bit of software twiddling, not so easy as you have to understand the disk drive primitives, but consists of counting disk read failures. Not many people will be prepared to try this as an idea, and it does require a lot of disks to produce a valid statistical sample, so the only way is to gain experience over a period of time. I've noted, long term, that certain make of drive X will always be less reliable with disk brand Y than with disk brand Z.

Temperature and Humidity

Finding media errors this way may suggest that it is the magnetic coating which is unsuitable, again not necessarily true, as this assumes that all other things are equal. We have discounted temperature and humidity. Temperature first. If we take the worst case, double sided 96 track per inch drives, the track width is about 7 thou. Now at the outer edge of the disk this means that the head mechanism has to move the head to a known position +/- about 2 thou, not a difficult engineering job provided expansion is ignored. Taking expansion into account lifts drive and disk design from the mundane to the extremely difficult. The base material of the disk is usually mylar, a plastic of well defined characteristics, but one which non-the-less expands with temperature. Likewise, the drive head cantilever (or whatever type of support mechanism is used) also expands with temperature, and being made of different materials, like as not at a different rate. Shugart, in some of their earlier drives took the logical step of making the head support mechanism of the same material as the disk, unfortunately, one of the properties of mylar is flexibility so what they gained by matching the coefficient of expansion, they lost by the head wobbling all over the place. These days nylon head supports are usual, and the shape and length of the support, coupled with the length and material of the lead screw or cam used to move the head are combined to ensure that the head moves with expansion at a uniform and equal rate to the expansion of the disk, OVER A LIMITED TEMPERATURE RANGE. So knowing this temperature range is important, it's certainly between 15 and 35 C, and most drives are better. If the computer is cased and ventilation is inadequate, it's surprising how high the temperature can rise within the box. This wouldn't be the first time I've heard of obstinate media/drive faults causing disk misreads being entirely cured by cleaning out six months accumulated muck from the fan filter!!! Another 'aside' on the subject of temperature, why are diskettes always black? I'll let you work that one out yourselves.

Humidity. Now that's one I didn't expect. During the hottest and stickiest two weeks of summer a couple of years ago, we experienced a complete and utter failure of the works Gemini Galaxy to 'boot'. Once we'd got it booted, then the number of disk errors which were recovered by the retry logic were out of all proportion to those previously experienced or experienced later. We tried the lot, cleaned the filters, ran the thing with the lid off to keep it cooler, changed the drives, everything. Still no better. We noted that the disks read more easily towards the middle of the disk than the outer tracks, and if we PIPed to a newly formatted disk (preferably an old one) everthing was Ok. It all pointed to the disks being in trouble, but why? This situation went on for some days until a wandering disk rep. happened to drop by. After greeting him with my usual banter specially reserved for getting rid of people trying to sell me things, I told him his blankety-blank disks were useless anyway as we couldn't get them to boot. His cool reply was that, 'What did I expect when the temperature was in the eighties, and the humidity was 99%!!' It turns out (quite logically) that disks absorb atmospheric moisture

and swell. The mechanical temperature compensation of the drives was coping quite well with the high temperatures as proved by the fact that disks could be formatted and used normally; what it couldn't cope with was disks, which having drunk most of the atmospheric moisture around them and swollen up, became a few thousandth of an inch larger in diameter than usual. Of course the greatest affect of this swelling would be at the outer edges of the disk, and guess where the boot and system tracks are.

So what was the cure. Well we did nothing, we managed to copy the old disks to new disks prepared under the elevated temperature and humidity and used those for the duration. We didn't chuck the old disks, because as soon as the weather returned to normal (sub-zero and rain), we updated the old disks from the new, and went back to using the old disks with no further trouble. However, one fact did emerge from that episode, and that was that Dysan disks were not affected anything like as badly as the others. I have since learned that Dysan lacquer their disks to stop them absorbing moisture and to improve their wearing capabilities, the only trouble with Dysan is that they are twice the price of the competition.

Different disk prices

Now on to the differences in price of double and single sided disks, and quad, double and single density disks. It is my opinion that all disks (except those coated on one side only for single sided use) are created equal, that is double sided, double density, 80 track (96 t.p.i.) disks. In the process of manufacture, they are tested and those which pass the 80 track test become quad disks, those which fail the 80 track test are rechecked at 40 track (48 t.p.i.), those which pass becoming double density disks, and then the failures are checked as single density disks. Those that fail then end up in the bin. By this time most, if not all, of the disks have been accepted. Now the vagaries of disk production are not likely to bow to the dictates of the marketing boys whose market profile shows that the majority of disks required are the 40 track double sided breed. In fact, if the production process is going well and not too many lumps are in the pudding before coating, then the majority of disks that fall off the end of the production line are going to be of the double sided 80 track breed and not what is required for sale. So I guess a fair proportion of 80 track disks are diverted and labelled as 40 track disks, simply because the disks being made are better than specification.

So what is this all leading up to? Well we've stopped selling 80 track verified disks for a start. We sell (and use ourselves) only 40 track disks for the 80 track machines. This saves about 70p per disk with no apparent difference of performance whatever. We still get about 1% of duff disks, be they 80 track or 40 track, so as duff disks are sent back for exchange I know we would rather have the 70p's and so would you. All this is borne out by the fact that the original box of 'single sided single density' disks I bought for testing the original Henelec disk controller at the time when it was fitted with single sided Shugart SA400's are still seeing useful daily life on my present machine as 'quad density double sided'; and not one of them shows any signs of either wearing out or giving verify errors.

My Advice

So my advice? Find out what brands of disk suit your machine, and when you've found that out, find out how cheap you can get them. Never buy 80 track verified disks just because you've got an 80 track machine, it seems a waste of money to me. The only exception I make is Dysan, they certainly behave better in high humidity environments and because of the lacquer, should wear

better, so if the disks are being used for business and the firm is paying, then use them, otherwise, anything that goes will do. Personally, I keep my eyes open for secondhand disks, they're usually the best bet and dirt cheap (if not actually given away).

Stubborn Disks

Now on to another couple of tips. If you've got a disk that resolutely refuses to format in one or two places, don't necessarily assume that it is scratched and therefore useless. Before you ditch it (or take it back from whence it came), try an old 'speaker magnet' on it. Needless to say, keep the magnet away from your other disks, but by giving the disk a good stir up with a powerful magnet, even the crudiest disks seem to spring into life. Don't ask me why, but they do!!!

Another point is formatting disks. Always allow time for the disk temperature to stabilize within the drive. It's no good formatting a stone cold disk and then expecting it to work on a hot day when the machine has been on for a couple of hours, as the originally formatted tracks are likely to be in entirely different positions under warms conditions. Shove the disk in the hole and wait for 30 - 40 seconds to allow the disk to warm up before formatting.

The final answer with Verbatim disks was revealed to me in a letter from Rory O'Farrell. A little while ago I gave him a disk on which he found no less than 65 duff sectors, Rory concludes as follows, "It might be due to some unkind person having put fingerprints all over the back of it, but as it was a Verbatim disk, made in Ireland, it is more probably due to their cutting down the Fairy Thorn tree that once stood on their site at Raheen, Co. Limerick. As I'm sure you realise, immeasurable bad luck always accompanies interference with the fairies." So if all else fails, go to the bottom of your garden and talk to the fairies.

Drive care (or lack of)

I hear a lot of waffle about cleaning disk drive heads. Again, if the propaganda is to be believed, disk drive heads should be cleaned weekly with the brand X disk cleaning kit for only £25.00. Now I can't answer for the public as a whole, but I've found that our customers fall over backwards with mirth at the thought that I was daft enough to buy some of these kits for stock in the hope that some customer would be equally as daft as to pay the asking price. In fact, the couple of disk cleaning kits the glib, smooth tongued rep. managed to flog me remain untouched, not even I can afford to use them.

Now I have had access to disk based machines for about 3 years now, and during that time I have dismantled and examined a number of drives for various reasons. (Don't you try it or you'll be along for the rip-off £25.00 disk drive alignment disk the same rep. talked me into. Realigning drive heads is something for masochists and loonies only, I know I qualify.) Anyway, to the point, I have not yet seen a drive head that warranted cleaning. Not even the drives out of the Galaxy we had in recently which seemed to live in the bottom of a cement works. This instance doesn't say much for the fan filters, as the whole thing was potted under a quarter inch layer of cement dust, but at least the heads were pristine clean.

It's not that I'm saying that drive heads never need cleaning, all I'm saying is that I have yet to see one that DOES need cleaning. So don't get talked into expensive disk head cleaning kits when any faults are more likely down to something else.

A Strange Drive Fault

Thinking about faults you don't see, try this one. A brand new Galaxy straight out of its box was being fitted with the Winchester Technology colour card for Prestel compatibility. There it was on the bench with its lid off, monitor alongside, being tested. At this stage, had we put the lid back on, then, of course, a certain immutable law would have guaranteed that the colour card would not work. Anyway, everything worked fine except, try as we might, we could not get drive B: to give us anything else but disk read errors. Of course the obvious occurred to us - Gemini - God bless their little cotton socks - had supplied a duff drive. It could happen, especially if it was made on a Friday and if someone had had a particularly liquid lunch that day. So we put in a new drive, and guess what, it didn't work either. Well I have this little theory, it's been printed in these annals before, but repetition is good for the soul, so here goes:

One dead one is tough
 Two dead ones is coincidence
 Three dead ones and something else is wrong

So after the third drive failure, the drive card was changed - no difference. So the colour card was removed - no difference. So the processor card was changed (for no good reason, except desperation) - no difference. We even thought about changing the box, but even Graham at his most pessimistic could not advance any valid theory as to how the box could affect drive B:. So what was it? Well I gave you the clue at the beginning, have you spotted it. "The lid was off and the monitor was along side." Now monitors have fairly powerful line timebase stages (after all that's how the man in the TV detector van knows you have the box on but no TV licence), and line timebases chuck out an awful lot of low frequency RF muck, about the right sort of frequencies disk drives are wanting to look at, so guess what. Move the monitor, put the steel lid on the Galaxy, and that was the answer to another wasted afternoon.

Keyboard reliability

And so on to another tale of woe concerning, this time, the Rotec function keyboards used on the Gemini Galaxy machines. Apart from my not liking the layout of the cursor keys, a certain amount of trouble has been experienced with the earlier ones. To put it baldly, the early keyboards are unreliable.

One of the causes of unreliability is the egress of muck, and the failures all stem from the way in which the keyboard works. Now I haven't seen the circuits but it is obvious that the keyboard uses capacitive keys. The PCB has areas of track in the form of two pads under each key, which are separated by about 2 - 3mm. When a key is pushed a metal pad on the bottom of the key is pushed down so that the pad on the key covers the two pads on the PCB. The PCB is heavily lacquered so that there can be no electrical connection between the pads when the key is pushed. The coupling between the two pads is therefore affected capacitively, the keypad joining the two pads on the PCB with a capacitance of a few picoFarads. I understand that the key sense lines have 2pF capacitors in series so that the few additional pF's caused by the key closing cause a change of between 0 and something a bit less than 2pF. The 2pF capacitors are there to minimize the reduction in capacitance caused by muck under the keys, but read on. Now I guess the on-board processor (yes the keyboard has a processor all to itself) must be scanning the pads by sending sharp pulses across the keys to check for coupling between them. When it finds a couple of pads joined capacitively, it does the rest, works out what key it

is and generates the appropriate ASCII code and a strobe. Fine, it sounds good in theory, and given good close proximity of the pad on the key and the pads on the pcb, it works.

How does muck affect the keyboard? Where does it go wrong? The lacquer on the pcb is quite thick as far as pcb lacquers go, but is still only about 0.05mm. I haven't worked out the capacitance involved, but the capacitance is proportional to the area of the pads, and inversely proportional to the distance between them. This is also multiplied by the permittivity (dielectric constant) of the lacquer, which I will assume to be about 3 - 4 (air has a dielectric constant of 1). Muck under the keys holds the keypad off the pad, and the chunks of stuff I've found under the keypads is at least as thick as the laquer. So the muck halves the coupling capacitance for a start, next, because the keypad no longer makes contact with the lacquer (except for a small area) the dielectric is now air and not the lacquer, let's be generous and assume that this only reduces the permittivity by half. The capacitive coupling between the keys and the pads is now only a quarter of what it was, so the capacitive change detected by the CPU is now between 0 and some rather less than the 2pF (minus) which was present before.

Now this has puzzled Rotec, as the keyboards were designed with a certain amount of muck in mind, after all that's why the sense lines have 2pF in series, to minimize the affects of the muck. After much poking around, they have discovered that a whole batch of keyboards were made with a 10nF ceramic capacitor which was marked as 10% tolerance component (to their spec) which was in fact a wrongly marked -40/+100% component intended for use as a decoupling capacitor. This of course degraded the sharpness of the scanning pulses, with the predictable result that when the coupling capacitance was reduced by muck, then the key failed to work.

Two further things compound the liability of key failure through muck egress, the first batch of keyboards made no attempt to keep muck out, the next and subsequent batches have rubber strips round the edges between the pcb and the keyframe to stop muck getting in, and between the keys to stop any muck that does get in from moving around (and also to cut down noise). All well and good, except there are 16 unfilled keyholes on the top of the keyboard frame covered with sticky tape (not really tape, it's quite thick). Sad to say, this can peel off after a few months use leaving half inch square holes on the top of the keyboard for the odd passing brick to drop through. Secondly, the pads on the bottoms of the keys seem to be slightly sticky and any muck that gets under a key promptly attaches itself to the keypad and stays put.

So onto the cure. Sling the thing back at your Gemini dealer, who in turn will sling it back at Rotec, via Gemini, and shout at them. Actually, I understand Rotec have been very good over this and all faulty keyboards returned have been sorted out. That of course is the legal recourse and you would be entitled to do just that, (provided that it is till under warranty) unfortunately, it's not a lot of help if you have just written a couple of hours rubbish using PEN (not having backed up of course) and then discover a passing brick has got under the CONTROL key, and all PEN does is print ZZZZZZ instead of breaking out of the insert mode (^Z, for those who don't know PEN). That's what happened to me once, which is the reason for this bit. The well tried cure is to turn the keyboard on its end and 'thumping it one' (known in the trade as a technical tap) in the hope that the muck will get dislodged and the key will become functional. Needless to say this didn't work. So in my wisdom I decided to take the keyboard apart. When I'd fixed the keyboard, I found that the action of removing or replacing the keyboard had crashed the video card, and using RESET to clear it lost about half of what I had written.

What did I do to the keyboard whilst I had it apart? I'm sure what follows voids any guarantees, so you have been warned. I removed the keyboard from the case. It was then I saw that the sticky over the unused keys had curled and peeled off and that was where the muck was getting in and, to not overemphasise it, the sticky side of the tape was filthy. I undid the 8 or so screws on the pcb side of the keyboard, noting that 3 of them had nylon insulating washers under them although I couldn't see why, and separated the pcb from the keyframe, paying careful attention to the positions of the rubber sealing strips. The true horror of what had been going on was then revealed. The rubber strips are also slightly sticky and were far from clean, the keypads had a lot of little bits sticking to them, but the pcb appeared clean. The topside of the pcb was cleaned with a soft cloth dampened with pure acetone (chemist, 20p) and the end of each keypad was also cleaned using a cotton wool bud, again just dampened with acetone. When all was bright and clean, the rubber strips were wiped to remove the adhering muck and the keyframe blown out to remove any more muck floating about. The keyboard was then reassembled being very careful to see that the rubber strips were seated square. What was left of the sticky patches over the spare key holes was removed and replaced with heavy duty packing tape which has both a stronger adhesive and being thinner, less tendency to curl. Everything was replaced in the case and tested, all keys were working, and all seems well. Sometime, when I find out which is the offending 1OnF, I'll change it. In the mean time it remains to be seen how well it will continue to work, I am now happy that the only place muck can get in is down the key stems, so we shall see what we shall see. The whole job took about 45 minutes, but didn't improve my temper any. A further late extra from Gemini is that a certain manufacture of chips has been found to less satisfactory than others, being loaded capacitively by the nice curly cable now fitted to the Galaxy machines. Don't try to change this chip yourself. Return the keyboard to your dealer.

The letters

Some time ago Paul passed a large envelope to me and said, "That's your lot, see if anything is useful.", so I did as I usually do, shoved the envelope in my cupboard to see light next time I got round to sorting out letters. Well they've just reemerged, and I've found three letters and five articles. The articles I'll read tonight, the letters, well here goes.

Polydos

The first from Mr. Toler of Cheshire, admonishes me for not having heard of Polydos, and for mucking Mr. Trim's database about (see volume 2 issue 1). Well as I said before, sorry, we can't know everything, can we? Anyway, Mr. Toler goes on to praise the virtues of Polydos, and suggests to Chris Blackmore (Dr. Dark) that, "He includes Polydos in his 'Circle of Iron'". I hope Mr. Toler means to include programs for use under Polydos, rather than Polydos on the disks, as Polydos is copyright of the boys in Denmark, and any infringements would probably mean a reinvasion by the Vikings. Anyway, there you are Chris, I don't know whether you could cater for it in the 'Circle of Iron', but perhaps you should think about it as Polydos has quite a following.

Naspen

Naspen is still alive and kicking although I know that Lucas only managed to sell a grand total of three last quarter. Anyway Steve Stubbs of Inverurie has come up with a little mod. I quote:

"One of the more obvious omissions in Naspen is the ability to print multiple copies of the same thing without having to press 'P' each time. I use a small

piece of relocatable code which loads the B register with the number of copies to be printed, calls the Naspen print command, and loops until the B register is zero. The code can go anywhere except the Naspen workspace. I use OC80H.

OC80 06 3A	LD	B,3AH	; 58 copies wanted
OC82 CD BAC2	CALL	BAC2H	; Naspen print routine
OC85 10 FB	DJNZ	OC82	; Loop 58 times
OC87 C3 B806	JP	B806	; Return to Naspen

Load the text into Naspen and leave the cursor pointing at the first character to be printed. Exit from Naspen using the 'N' command. Enter the above code, setting the second byte for the number of copies required (in HEX) and execute at the address loaded. As Naspen prints each copy, the word 'complete' will be displayed on the screen, this is because this is in the Naspen print command."

SYS

Lastly, from Mr Hill of Newhaven a little tweek to SYSN7, the last of the series of SYS for the Henelec/Gemini G805 disk sysेत्म. Mr. Hill uses the system under CP/M 1.4 with a Gemini GM812 video card:

"The modification allows me to use ^X to switch between the two keyboard options. Each successive use of ^X flips between the alternative options. The control can be used inside all the CP/M packages that I possess, although there may be some exceptions to this. The listing below shows my modification to the CP/M 1.4 version of SYS.

CICRT1	LD	HL,CHCD	; Existing program
	CP	(HL)	
	JR	NZ,CICRTX	; Jump to new section
	LD	A,BS	; Existing program
	LD	(BOPT),A	
	JR	CONIN9	
			; NEW CODE
CICRTX	LD	HL,KOPT	; Point to new keyboard option flag
	CP	18H	; Is it ^X
	JR	NZ,CICRT2	; Skip if not
	LD	A,1	
	XOR	1	; Flip the keyboard option flag ..
	LD	(HL),A	; .. and put it back
	JR	CONIN9	; Done
CICRT2		; Continue with SYS"

Looking at the code, something seems a little wrong, where does the contents of register A come from at CICRTX? I've just rechecked what I have typed in and that's correct, but as I don't have a copy of SYSN7 to hand I hope the code works.

NASPAS Review

Here endeth the letters and, lastly, on to a mini review of the Nascom NASPAS sent in some time ago by Mr. Pennell who doesn't live a million miles away from me, in Pinner Middlesex, although we've never met except perhaps unknowingly over a pile of bean cans in the local Safeways.

"I first purchased the tape version of NASPAS, but later exchanged it for the EPROM version as my Nascom 1 has acres of EPROM space being fitted with two EPROM cards. My Nascom is also fitted with 64K of RAM, an I/O board and an external CUTS tape interface.

Both tape and EPROM versions of NASPAS are supplied with two booklets, a programming manual and an operating manual. The operating manual contains information on getting the system going and details on running the editor, the compiler and other miscellaneous information. The details in both manuals are quite sufficient and well written, but the programming manual, whilst accurate, is rather formal and could be rather heavy going for a novice to Pascal. The programming manual describes the format of Pascal, including data types, declaration expressions, statements, procedures, functions, parameters, etc, all very carefully. But I found the lack of examples made it somewhat difficult to define problems and sort out syntax errors when I got going. A good book on Pascal programming would seem to be a great help as well as the information supplied.

The tape version was supplied on a high quality cassette and loaded easily at 1200 BAUD. The EPROM version is supplied as six 2716 and runs from D000H to FFFFH, and is started in the same way as the Nascom Basic, that is, typing 'J' for cold start, plus the memory space to be allocated, otherwise NASPAS defaults to all available memory allocated. 'Z' warm starts NASPAS.

I had some difficulty with the EPROM version, as the title on the screen and the keyboard input routines appeared to be corrupt. As a listing is not supplied, I was unable to check the code myself, so the chips were returned, only to be sent back with 'no fault found'. As the fault was still apparent, I resorted to checksumming the EPROMS and found that one would occasionally give a different result. I made a copy of the chip to tape, and then erased and reblew the EPROM. After that my troubles disappeared. The fault seeming to be poor programming of the chip in question.

A good selection of functions are available including trig. functions, string functions, some graphics functions and port I/O. Also external machine code routines can be called, and external printer patches are provided to allow listings to be made from the editor.

In use, programs are written with the NASPAS editor which uses screen editing facilities similar to NAS-SYS with the exception that a line may be up to 80 characters long, the text scrolling sideways to the left off the screen as text is added to the right. When first used, the effect can be a little disconcerting. Editing of lines which 'wrap round' the screen can also be achieved by moving the cursor to the correct position on the screen, editing, and then pressing the ENTER key.

Once a program is written, it may be compiled and the error codes are displayed one at a time on the top line of the screen with the cursor pointing to the approximate place of error within the text. The meanings of the error codes are listed in the back of the manual. When a successful compile is achieved, then a message is displayed giving the memory locations of the source code, and the also of the machine code program produced.

Both the source code and the machine code produced can be loaded to and from tape, with or without file names. The machine code program produced can be reloaded and run 'stand alone' so long as the run-time program in NASPAS is present at the same time.

It appears to be very versatile and very fast. A comparison drawn with Nascom Basic indicates truly remarkable speed, and programs containing masses of 'IF' statements and the like cause no problems at all. Most of my programs are written for amateur RTTY operation and in the past have been mostly machine code; the Pascal versions appear to run with almost machine code speed.

Overall NASPAS appears to be a very versatile package as supplied, and is an excellent addition and alternative to the Nascom ROM Basic."

DISK DRIVE COMPATIBILITY**By Richard Beal**

As floppy disk technology has developed, more and more data can be stored on each mini-floppy disk. One of the biggest steps was the change from 48 tracks per inch (tpi) to 96 tpi. This was achieved first by Micropolis, who developed a narrower disk head. Other manufacturers such as Teac and Mitsubishi have followed, and the 48 tpi units can be regarded as obsolete, as they offer poorer value for money. Of course the advantage of obsolete items is that it may be possible to get hold of them at a low price, so 48 tpi units are still useful. Incidentally, the IBM Personal Computer at present uses 48 tpi drives!

This article answers the following question:-

"If you have 96 tpi drives, is it possible to process disks from a 48 tpi system?"

The first problem is to make the 96 tpi drives double step, so that only alternate tracks are processed. This can be done through software in the BIOS, or the drive manufacturer may have incorporated this in the design. For example a switch can be added to the Teac 55F which selects normal or double stepping. I believe the Mitsubishi drives can be sent a command by the disk controller specifying this option. In some cases drives may have this feature but it is undocumented.

If you try this you will find that 96 tpi drives have no trouble reading or rewriting disks from a 48 tpi drive, and I have found that rewritten tracks can be read without difficulty on a 48 tpi drive. This is lucky, as the 48 tpi drive is picking up noise as it is reading a wider track than that written. This works with both single and double density.

However I have also tried formatting disks for 48 tpi use using a 96 tpi drive, and this does not work reliably. The 48 tpi drive has trouble finding sector headers and RNF and CRC errors are likely. I have tried erasing the disk to be formatted using a large magnet, then formatting and writing using a 96 tpi drive. This seemed to considerably improve the ability of a 48 tpi drive to read the disk, because the inter-track noise is reduced.

So the answer is that disks can easily be exchanged between users with 96 and 48 tpi drives, provided that the disks are always formatted by the person with the 48 tpi drives. In emergency the 96 tpi drives can be used for formatting, using the magnet method. If you use a magnet, keep it far away from other disks, disk drives, and televisions or monitors, since all of these can suffer damage from magnetic fields. A bulk eraser would be an alternative to a magnet.

It is beyond the scope of this article to describe how to write a BIOS which can process both 48 and 96 tpi disks. This is left as an exercise for the reader!

**REVENGE
OF THE
DROSOPHILA**
order it at the post office!

Trans Girobank account number
cash 30-729-4609

There's a multistorey warehouse full of fruit, and it's the Runner's job to go in and save the fruit from an impending swarm of mutant Drosophila. Doing this requires some tactical skill as well as fast reflexes.

Features: Fast Synchronised Animation, Scrolling Maze, 5 Different Maze's to survive and 8 Game Variations.

Revenge of the Drosophila is monitor independent and is supplied with a tape reader for loading under monitor's other than NASSYS. Requires 16K Nascom 1,2 or 3 with NASGRA ROM (Ver.3). Specify CUTS or NI format on order.

Incredible Value at just £8 post free.
Available only by mail order from:

GARRY ROWLAND, 24 PARSLOES AVENUE, DAGENHAM RM9 5NX

DOCTOR DARK'S DIARY – EPISODE 19.**By C. Blackmore**

My regular reader has probably already noticed that I am constantly extending and improving the noble Marvin, in an effort to build up the biggest and best computer in town. After all, it is very well known that without such a machine available to flash lights and spin great big empty tape reels round and round, the best laid world domination plans are doomed to failure...

My latest addition to the amazing Marvin is the HSA-88B arithmetic processor board from Belectra. The board was originally advertised in this magazine, at £199. However, you will be sad to hear, this price no longer applies. I quote from a letter Belectra sent me - "Since our advertisement in 80-BUS News, we have reviewed our marketing policy (which used to be direct sales to the public) and are now selling also via computer retailers. The price of the HSA-88B has therefore been increased to include dealer margins and other factors associated with selling to trade customers, to £253 plus VAT." So, if you rushed out and ordered one as soon as you saw the advertisement, you are now feeling pretty pleased with yourself, I expect.

There was going to be a great deal of talk about the hardware you get for the money, here, but a certain David Parkinson stole my thunder in the last issue, so I am frantically re-editing this article to save wasting space by going over old ground. So if it reads as though I have done a rush job, you will know why. I don't really feel bitter about this, David, honest! (Your article doesn't say how much you paid for your board, was it a freebie?) [Ed.- it was on loan for review and has now been returned to Belectra.]

As processor chips go, the 9511 is fairly odd (though it is by no means as unbelievably bizarre as the old SC/MP chip in Sinclair's original computer, the amazing MK14) as it does not fetch opcodes and data from memory for itself. Instead, your main processor loads data into the chip, followed by an instruction opcode. When the 9511's status line indicates that the processing has been done, the main processor can read out the answer. The 9511 has an eight bit bus system for communication with the outside world. Since it deals with either 16 or 32 bit quantities, data has to be sent in two or four byte blocks, and the fast Z80 block output instructions can be used. The chip has five distinct groups of instruction codes, which are for 16 bit fixed point operations (integers), 32 bit fixed point operations (enormous integers!), 32 bit floating point primary and derived operations, and data and stack manipulation operations. The 16 bit and 32 bit fixed point operations that can be performed are addition, subtraction, multiplication and division. The same four operations can also be done in 32 bit floating point format, and these are referred to as the primary operations. The derived operations consist of those that can be built up using the primary operations in various combinations, and are square roots, sines, cosines, tangents, inverse sines, inverse cosines, inverse tangents, common logarithms, natural logarithms, "e" raised to a given power, and any number raised to a given power. If you didn't understand that sentence, I suggest you try the Open University course, M101, that I recently finished (I am not claiming to have passed, as I don't believe in tempting providence!) The data and stack manipulation commands are mainly concerned with matters such as changing to and from floating point format, changing sign and so on, but also allow you to load pi into the processor in an amazing 16 clock cycles. If you are into that sort of thing, you might like to work out how many clock cycles it would take to load pi from the main processor to the chip, assuming you know the 32 bit floating point value of pi, which I seem to have forgotten...

Some of the above I got from Belectra's part of the documentation, which is clear, if rather brief; much of the rest of the information about the 9511 came from "Modern Microprocessor System Design" by Daniel R McGlynn. Also included in the information Belectra give you are details of the ports used by the board, but there is no need to repeat them here. If you do reconfigure the board to other ports, you can easily patch the Pascal compiler's run time routines to take account of this, as the address of the data port is stored at £0103, and the address of the control port is at £0104. (Quoted from Hisoft's "Functional Differences between Hisoft Pascal 5D and Hisoft Pascal 4D", which comes with the Pascal manual.)

Belectra's documentation gives brief but very clear examples of how to program the board using Z80 assembly language, and it is clear that this is quite an easy job, when compared with writing your own set of floating point routines. The thing is, the rest of the program is going to be a bit of a pig, if it uses the calculations the board can do, to any great extent. I once wrote a biorhythm program in 1K of Z80 code (and I hasten to point out that I do not believe in biorhythms!), and it was no fun at all, especially the bit that drew the sine waves. So I will move hurriedly on to the sensible way of doing things, namely with high level languages, pausing only to note that if you do program the board in assembler, then there is no reason why the Z80 can not get on with something else while the HSA-88B is working. For instance, it could be preparing the next data to be worked on. It could just as easily be controlling another HSA-88B, if you have the money to run more than one of them! Then you would need to write some nice queue handling routines, especially if there was another board that also ran independantly, like the Pluto. I think you had better forget that sort of programming style, unless you are a real masochist. After all, you are supplied with Hisoft Pascal 5 along with the board, and Hisoft's compilers are renowned for the speed of the code they produce. HP5 uses the HSA-88B for all its arithmetical work, which means that as well as compiling programs that run faster, it also needs a lot less memory space for its completely rewritten run-time routines. (Sometimes you can have your cake and eat it too!) If you want to use some other compiler with the board, or even an interpreter, this is possible, as long as you know how to do things like modifying the run-time routines the compiler churns out, or finding the bit of the interpreter you need to change. Belectra give brief notes about what is required, but also say "The only remaining consideration is whether a particular compiler or interpreter is worth modifying; some generate code which is so inefficient that even if the HSA-88B performed its function in zero time there would not be any noticeable difference in overall program execution speed." I haven't tried the patch to MBASIC from the last issue, as I can't afford MBASIC...

Hisoft Pascal 5D is supplied with the manual for the earlier 4D version, and six pages of notes concerning the differences between the two compilers, marked "provisional" on my copy. The major change, obviously, is the use of the HSA-88B for all arithmetic. This includes integers, all of which are now to 32 bit precision. As a result of this, MAXINT is now 2,147,483,647, which is a big number! I am not at all bothered by the compiler's inability to handle recursive WITH statements, though there is bound to be someone, somewhere who thinks this is a fatal flaw! Instead of RANDOM, you now put RANDOM(X), where X is either zero, or a seed for the random number routine. If you use 0, the value returned is between 0 and 65535 inclusive, rather than the old 0 to 255. GOTO (whatever that is) can not transfer execution to another block. I haven't written a GOTO in Pascal yet, and if I ever need to, I will be quite surprised. The provisional manual gives the addresses in the

run-time routines which have to be changed (presumably using POKE once your program is running) if the HSA-88B is not at ports 80,81H. Another change allows underline characters to be used in identifiers, to help with legibility. In order to comply with the ISO standard, a variable used as a loop control variable must be declared in the block the loop is in, rather than globally. This seems quite a good idea. If you are using my "explain" utility, you will need to add a line to the CASE statement, to add error message number 74, which says "FOR statement control variable must be declared in the closest enclosing block." If you are not using "explain", I bet you spend a lot of time looking in the manual! The new procedures PRON and PROFF have the effect of switching output between the printer and the screen, which is handy, but far from ISO standard, as are the new functions ARCSIN(X), ARCCOS(X) and POWER(X,Y). I expect you can tell what they do, and won't use them in programs you want to be portable...

That brings us to the question I always used to ask when confronted with a new sports car or huge motor cycle, namely "Wot'll it do, mister?" (Nowadays, I don't ask about cars at all, and given the bike, will find out by experimental means!) Just for you, I looked up, typed in, compiled and ran the Pascal benchmarks suggested by Personal Computer World. The timings were done with an aged Post Office hand operated stop watch, so the accuracy is very much dependant on the accuracy or otherwise of my own reaction times. I was sadly out of home-brew at the time, so the results should be accurate to within say half a second (I'm older than the stop watch!) As you will see, I compiled them with HP4, HP5 and Compas. With HP4, I used the compiler options O-,C-,S-,A-,I-to cut out all the checks that slow down a program, and with HP5 I used O-,C-,S-,A-. (HP5 has no "I-"). I couldn't find the page about compiler options in the Compas manual, so I compiled the programs without the benefit of any such options. Here are the results, which are not entirely as I would have expected them to be, at first sight.

Program	HP4	HP5	Compas
-----	---	---	-----
Magnifier	.2	.6	.6
Forloop	2.4	8.8	8.8
Whileloop	4.2	16.4	7.4
Repeatloop	3.6	15.2	6.6
Literalassign	3.4	10.2	3.6
Memoryaccess	3.6	10.6	3.8
Realarithmetic	14.6	11.2	52.2
Realalgebra	15.0	16.8	41.6
Vector	8.0	22.0	14.8
Equalif	6.0	19.2	8.2
Unequalif	5.6	19.6	8.0
Noparameters	3.0	3.6	.8 *
Value	3.4	5.0	7.0
Reference	3.6	4.2	7.2
Maths	6.2	5.2	47.8

You should be able to spot some obvious and some surprising trends in the table. The surprise is that the programs sometimes take longer in HP5 than in HP4. This is in fact not so very surprising, because the integers used by HP5 are twice the length, which probably more than doubles the time taken to handle them, even though actually working things out with them will be faster. Thus, Program Magnifier, which is just an empty loop, takes .6 seconds instead of .2 seconds (bearing in mind what I said about timing accuracy). Compas does

```

PROGRAM PROGRAM MAGNTITER;
VAR K : INTEGER;
BEGIN
  WRITELN('S');
  FOR K := 1 TO 10000 DO
    WRITELN('E')
  END.
END.

PROGRAM PROGRAM FORLOOP;
VAR J, K : INTEGER;
BEGIN
  WRITELN('S');
  FOR K := 1 TO 10000 DO
    FOR J := 1 TO 10 DO L := J;
    WRITELN('E')
  END.
END.

PROGRAM PROGRAM WHILELOOP;
VAR J, K : INTEGER;
BEGIN
  WRITELN('S');
  FOR K := 1 TO 10000 DO
    FOR J := 1 TO 10 DO ;
    WRITELN('E')
  END.
END.

PROGRAM PROGRAM WHILELOOP;
VAR J, K : INTEGER;
BEGIN
  WRITELN('S');
  FOR K := 1 TO 10000 DO
    BEGIN
      J := 1;
      WHILE J <= 10 DO J := J+1
      END;
    WRITELN('E')
  END.
END.

PROGRAM PROGRAM REPEATLOOP;
VAR J, K : INTEGER;
BEGIN
  WRITELN('S');
  FOR K := 1 TO 10000 DO
    BEGIN
      J := 1;
      REPEAT
        J := J+1
      UNTIL J > 10
    END;
  WRITELN('E')
  END.
END.

PROGRAM PROGRAM EQUALIF;
VAR J, K, L : INTEGER;
BEGIN
  WRITELN('S');
  FOR K := 1 TO 10000 DO
    BEGIN
      J := 1;
      REPEAT
        J := J+1
      UNTIL J < 10
    END;
  WRITELN('E')
  END.
END.

PROGRAM PROGRAM LITERASSIGN;
VAR J, K, L : INTEGER;
BEGIN
  WRITELN('S');
  FOR K := 1 TO 10000 DO
    FOR J := 1 TO 10 DO
      IF J < 6 THEN L := 1
      ELSE L := 0;
    WRITELN('E')
  END.
END.

PROGRAM PROGRAM MATHS;
VAR X, Y : REAL;
BEGIN
  WRITE(1, 'X := ');
  READ(X);
  VALUE1 := X;
  WRITE(1, 'Y := ');
  READ(Y);
  VALUE2 := Y;
  PROGRAM REFERENCE;
  VAR J, K : INTEGER;
  BEGIN
    PROCEDURE REFER1(VAR I : INTEGER);
    BEGIN
      I := 1;
      FOR K := 1 TO 10000 DO
        VALUE1(J);
        WRITELN('E');
    END.
  END.
  PROGRAM NOPARAMETERS;
  VAR J, K : INTEGER;
  BEGIN
    PROCEDURE REFER2(VAR I : INTEGER);
    BEGIN
      I := 1;
      FOR K := 1 TO 10000 DO
        I := I+1;
        VALUE2(K);
        WRITELN('E');
    END.
  END.
  PROGRAM NONE1;
  BEGIN
    PROCEDURE REFER3(VAR I : INTEGER);
    BEGIN
      I := 1;
      FOR K := 1 TO 10000 DO
        I := I+1;
        I := I+1;
        VALUE1(K);
        WRITELN('E');
    END.
  END.
  PROGRAM NONE2;
  BEGIN
    PROCEDURE REFER4(VAR I : INTEGER);
    BEGIN
      I := 1;
      FOR K := 1 TO 10000 DO
        I := I+1;
        I := I+1;
        I := I+1;
        VALUE2(K);
        WRITELN('E');
    END.
  END.
  PROGRAM NONE3;
  BEGIN
    PROCEDURE REFER5(VAR I : INTEGER);
    BEGIN
      I := 1;
      FOR K := 1 TO 10000 DO
        I := I+1;
        I := I+1;
        I := I+1;
        I := I+1;
        VALUE1(K);
        WRITELN('E');
    END.
  END.
  PROGRAM NONE4;
  BEGIN
    PROCEDURE REFER6(VAR I : INTEGER);
    BEGIN
      I := 1;
      FOR K := 1 TO 10000 DO
        I := I+1;
        VALUE2(K);
        WRITELN('E');
    END.
  END.
  PROGRAM NONE5;
  BEGIN
    PROCEDURE REFER7(VAR I : INTEGER);
    BEGIN
      I := 1;
      FOR K := 1 TO 10000 DO
        I := I+1;
        VALUE1(K);
        WRITELN('E');
    END.
  END.
  PROGRAM NONE6;
  BEGIN
    PROCEDURE REFER8(VAR I : INTEGER);
    BEGIN
      I := 1;
      FOR K := 1 TO 10000 DO
        I := I+1;
        VALUE2(K);
        WRITELN('E');
    END.
  END.
  PROGRAM NONE7;
  BEGIN
    PROCEDURE REFER9(VAR I : INTEGER);
    BEGIN
      I := 1;
      FOR K := 1 TO 10000 DO
        I := I+1;
        VALUE1(K);
        WRITELN('E');
    END.
  END.
  PROGRAM NONE8;
  BEGIN
    PROCEDURE REFER10(VAR I : INTEGER);
    BEGIN
      I := 1;
      FOR K := 1 TO 10000 DO
        I := I+1;
        VALUE2(K);
        WRITELN('E');
    END.
  END.
  PROGRAM MATHS;
  BEGIN
    WRITELN('S');
    FOR K := 1 TO 10000 DO
      BEGIN
        VALUE5 := K;
        VALUE4 := SIN(K);
        VALUE3 := EXP(K);
        WRITELN('E');
      END;
    END;
  END.

```

not use quite such big integers, so it seems to be producing less efficient code for this benchmark. It is not easy to be sure about this, however, on account of the stopwatch and its operator... All the routines using just integers suffer from the same "negative improvement", but look what happens with Realarithmetic! HP5 cuts the time down quite well, while Compas is nowhere near even HP4. And when it comes to the (number) crunch, in Program Maths, HP5 is probably about 20% faster than HP4, even though it is doing a lot more work in the loop counting part of the program. The "*" mark indicates that I didn't believe the timing I got for Program Value, using Compas. Either the compiler is very efficient at calling procedures when there are no parameters, or this is a result of the fact that Compas procedures are not recursive unless you tell it they should be. (In other words, it does not normally set up a new local workspace every time a procedure begins, which proper Pascal compilers have to do.) Or perhaps I compiled it wrong...

Since writing that paragraph, I have read Polydata's remarks in the last issue, and appreciate that much of what I have just said about their compiler may well be hopelessly wrong, when applied to version 2. It would be nice if they could let us know how fast the new version runs the benchmarks. I was pleased to see that they are now taking a much more sensible line over royalties on your programs, too...

Anyway, the bottom line of the table is the one you are buying, and the HSA-88B is clearly pulling its weight there. By comparison, the Sage II, with its 68000 processor, using the well known p-system, and costing rather a lot more than my system, takes 7.6 seconds to run Program Maths. And if you run this:

```

1000 PRINT "S"
1010 FOR K% = 1 TO 1000
1020 X = SIN(K%)
1030 Y = EXP(X)
1040 NEXT K%
1050 PRINT "E"
1060 END

```

using MBASIC, you will find it takes about 25 seconds, running at 4MHz, even though it is using K%, which is faster than plain K. I have also written some other test programs which lean more heavily on the maths processor than the benchmarks do, because they don't really probe very deeply into the realms of number crunching, and there is an even more noticeable improvement, but space does not permit the inclusion of these programs. They don't actually do anything useful, anyway, unless anyone wants a list of all the prime numbers lower than MAXINT...

If you want the answers to your sums faster, or just want to be the envy of all the people with slow computers, then the HSA-88B has to be a good buy. As soon as I have taken my Open University exam for this year, and have some time to myself and Marvin, I am hoping to write some fancy stuff, using Pluto, HSA-88B (pity they couldn't have given it a nice name - what does the 88B bit refer to?) and HP5. Real 3D programs need fast matrix calculating routines to make them work. See in particular the article in December PCW for an idea of what can be done. Perhaps I need an array of HSA-88B's, say four of them, running in parallel...

References:

Pascal Benchmark programs from Personal Computer World, Dec 1980, pages 59-61.

Corrections to the above, Personal Computer World, March 1981, pages 116-117.

Sage II benchmarks, Personal Computer World, February 1983, page 174.

"Modern Microprocessor System Design" by Daniel R McGlynn, published by John Wiley and Sons, ISBN 0-471-06492-0.

Late extra bits!

Prompted by my unusually rude remarks, several people have stopped being apathetic, and volunteered to set up and organise software circulation systems for systems like theirs. Incidentally, would whoever is hanging onto the original Circle disc please put it back into circulation. It is an Inmac lifetime one, and the owner must be wishing he had used a cheap one!

Nascom users running Nas-Dos with Nascom double density drives should contact Roger Dowling, at 11 Westbrooke Road, Welling, Kent, DA16 1PR.

Users compatible with G805 using DCS-DOS and/or CP/M (but I don't know what drives - Pertec, I assume?) should write to Ray Cutler, 6 Bearmore Road, Cradley Heath, Warley, West Midlands, B64 6DX. He says if you have a text editor to spare, it would help, as he is writing letters in the form of BASIC programs at present! No piracy, please...

I have been sent (by our generous editor) a huge pile of Nascom related items, which I hope to be able to get to work on soon. If you have been wondering what happened to your masterpiece for ages, I think I have it. Don't worry, if it gets printed, you get paid, not me!

END

Letter to the Editor**Selectra Arithmetic Board**

Dear Sir,

We wish to clarify the following points regarding the review of our Arithmetic processor board in Vol. 2 Issue 5 of 80-BUS News:

- 1) The Programming Manual is now printed on a printer with desenders.
- 2) Because Mr Parkinson received our review board directly from Gemini Microcomputers, who borrowed it for an exhibition, while some parts of the documentation came directly from us, he did not receive the complete documentation set. The HP5 Pascal compiler is a substantially enhanced version of HP4 and the Manual sent out with each board clearly lists all the differences and enhancements.
- 3) We have not tested our board with the Am9512 processor but we can see no reason why it should not work. Anyone requiring this alternative processor is welcome to contact us.

Yours faithfully
P.Holy, Director, Selectra Ltd.

ACCESSING PRETEL with a NASCOM 2**By Robin Luxford**

Although Prestel was originally designed to reach the home via the television receiver and an adaptor with a numeric keypad, this method seems to have severe limitations; unless you buy a special printer you cannot have hard copy and any form of magnetic storage comes even more expensive.

However, with the availability of surplus Post Office approved modem cards, and the 300 baud service now being run by Prestel, it becomes a fairly straight forward matter to access Prestel with your home computer.

The three programs PREST, SAVEPRES and PRINPRES were written for a Nascom 2 running CP/M 2.2 with a Gemini IVC card, using the N2 keyboard, although the principles are applicable to any system.

PREST makes your computer run as a dumb terminal storing incoming data until all the RAM up to the start of the BDOS is full. When you are up to your last page of RAM the screen inverts as a warning but in practice you have to be connected to Prestel for a very long time to get that far. When you hit CTL/C to exit, the program sends the sign-off string to Prestel then waits a few seconds to see if there is a mailbox message for you before warm-booting. Because the mailbox facility is only available at present on the Enterprise computer and the 300 baud service is only available on the Kipling and Dryden computers, I have not yet been able to develop any routines to handle mailbox messages. At the start of each new page Prestel sends a string of 40 DELs; in order to save buffer space and also to simplify subsequent handling of files by GEMOPEN, the first DEL is converted to 07H and the rest of the string is suppressed.

After exiting from PREST you can make a disk file from the buffer by running SAVEPRES or print it on CP/M List device by running PRINPRES.

If you are connecting to a telephone jack via a unit such as the GEC LTU 11 line coupler (also available on the surplus market), you can have the added convenience of being able to dial the Prestel number automatically. The PREST program has routines for doing this, also for sending your Customer Identity number automatically when the Prestel computer replies.

The only hardware mod. to the Nascom required is to connect the uart rx clock to the tx clock so that when the tx clock is switched to 300 baud, the rx clock will also be switched to it. The 300 baud "cassette" position of the rx clock will not work. The simplest way of achieving this is to connect the end of R19 nearest to IC29 to TP5 and switch LSW2/6 to EXT. LSW2/5 must be in the EXT/TTY position of course and LSW2/7 must be in the TTY position to receive from the modem.

Acknowledgement is due to the author of the DUMBERTERM program published in this magazine some time ago, who I think was David Parkinson. Some of his program appears in the source code of PREST, mostly the upper case lines.

```

title PRESTEL for Nascom 2 & Gemini IVC
subtitle PRESTEL VB, PRESTEL terminal program. RL.
22/11/83

        *880

        false equ 0
        true  equ not false

        ; Autodial, set true if connecting to line via barrier
        ; unit such as LMU 11, false if using acoustic coupler
        autodl equ false

        ASEG
        ORG 100H

        ; UART type - 6402
        ; Ports for UART to host/modem
        uartd equ 01H          ; Data
        uarts equ uartd+1       ; Status

        ; IVC Ports
        IVCD EQU OB1H
        IVCS EQU OB2H

        ; Port for dialling, (Skt. A)
        dialpd equ 04h          ; Data
        dialps equ dialpd+2     ; Status

        ; Socket A bit allocation
        ; b4 Select line relay
        ; 5 Dial relay

        ; Characters
        conc equ 03h
        cr   equ 0dh
        bell  equ 07h

        ; CP/M routines
        condir equ 6
        petrng equ 9
        jboot  equ 0
        jbdos equ 0005H

        ; Buffer - also used by utilities subsequently loaded
        buffer equ 500h

        JP START

        ; Insert phone number & Customer identity no. which
        ; Prestel supply when you enrol
        ; may be more than 7
        ; digits, must be
        ; followed by null

        0000 FFFF
        0001
        0002
        00B1
        00B2
        0004
        0006
        0003
        000D
        0007
        0006
        0009
        0000
        0005
        C100 C3 0524
        0103 31 32 33 34
        0107 35 36 37 00

```

```

; Customer identity number
; circum: defb "1234567890"
010B 31 32 33 34
010F 35 36 37 38
0113 39 30

0115 2A 39 30 25 ; Sign off string
0119 20 2A 39 30 ; signoff: defb "*902 *902"
011D 25

011E 03
0000

0121 00

0122 1A
0123 09 50 52 45
0127 53 54 45 4C
012B 20 43 4F 4D
012F 50 55 54 45
0133 52 20 43 41
0137 4C 4C 49 4E
013B 47 20 50 52
013F 4F 47 52 41
0143 4D
0144 0A 0A 0D
0148 43 68 65 63
014C 63 20 74 68
0150 61 74 20 6D
0154 6F 64 65 6D
0158 20 69 73 20
015C 73 77 69 74
0160 63 68 65 64
0164 20 4F 4E 2C
0168 20 69 6E 20
016C 4E 6F 72 6D
0170 61 6C 2C OD
0A
0174
0175
0177
0179
69 6E 61 74
017D
65 20 61 6E
0181
64 20 46 75
0185
6C 6C 20 64
0189
75 70 6C 65
0191
78 20 6D 6F
0193
64 65 20 61
0195
6B 64 20 62
0199
61 75 64 2D
019D
0A 0D
019F
72 61 74 65
01A3
20 73 77 69
01A7
74 63 68 65
01AB
73 20 69 6E
01AF
70 63 6P 6D

; Exit jump, can be patched
jconc: defb Och
defw jwboot

; Working storage
delrig: defb 0
; Flag for suppressing DEL
strings

; Messages output to screen
msgint: defb 1ah,"PRESTEL COMPUTER CALLING PROGRAM"

```

```

PRESTEL for Naocom 2 & Gemini IVC          M-80      5 Dec 1983   22:22 PAGE  1-2
PREST V8, PRESTEL terminal program. RL. 22/11/83

01B3      70 75 74 65
01B7      72 20 61 72
01BB      65 20 73 65
01BF      74 20 61 73
01C3      20 66 6F 6C
01C7      6C 6F 77 73
01CB      3A 2D 0A OA
01CF      OD
01D0      09 31 20 3C
01D4      2D 2D OA OD
01D8      09 32 20 3C
01DC      2D 2D OA OD
01E0      09 33 20 3C
01E4      2D 2D OA OD
01EB      09 34 20 3C
01EC      2D 2D OA OD
01FO      09 35 20 3C
01F4      2D 2D OA OD
01FS      09 36 20 20
01FC      2D 2D 3E 09
0200      61 6E 79 20
0204      6B 65 79 20
0208      74 6F 20 70
020C      72 6F 63 65
0210      65 64 2C OA
0214      OD
0215      09 37 20 20
0219      2D 2D 3E
021C      09 61 66 74
0220      65 72 20 64
0224      69 61 6C 6C
0228      69 6E 67 20
022C      50 52 45 53
022O      54 45 4C 20
0234      6E 6F 2E
0237      OA OA OD 24
023B      OA OD 57 61
023F      msgwdt: defb Oah,Odh,"Waiting for dial tone$"
0245      69 74 69 6E
0247      67 20 66 6F
024B      72 20 64 69
024F      61 6C 20 74
0245      6F 6E 65 74
0253      OA OD 44 69
0257      61 6C 6C 69
025B      6E 67 20 6E
025F      6F 77 24
0262      1C 1C 6C 63
0266      6F 6D 70 6C
026A      65 74 65 64
026E      24

```



```

        LD  FF          ; poll for ^C
03B7 03B9 00 05      LD  OFTH
03BB 0005          LD  C,CONDIR
03BE CALL JBDOS
03BF B7          OR  A
03C0 28 05      JR  Z,DE10
03C2 FE 03      OP CONC
03C4 CA 0374      JP Z,EXIT
03C7 3A 03D3      LD  A,(MS)
03CA B3          EX  (SP),HL
03CB E3          EX  (SP),HL
03CC 3D          DEC A
03CD 20 FB          JR  NZ,DE11
03CF 10 F6          DJNZ DE10
03D1 C1          POP BC
03D2 C9          POP BC
03D3 4B          RET
03D4 3E 10          LD  A,10H      ; open dial relay
03D6 D3 04          OUT (DIALPD),A
03D8 CD 03AE      CALL DLJ66
03DB 3E 30          LD  A,30H      ; close dial relay
03DD D3 04          OUT (DIALPD),A
03DF 0D 03B2      CALL DLJ33
03E2 C9          RET

; Connect line and on to term routine
; - from "T" command
CONLIN: LD  A,70H
         OUT (DIALPD),A

; Clear screen, and set limit:
; DTERM: LD  A,1AH
;         CALL PUTVID
;         LD  A,(7)
;         DEC A
;         LD  (LIMIT),A

; Start of main processing loop
; Uses a FIFO buffer to handle the data
; <DE> = Input pointer  <HL> = Output pointer
LOOP1: LD  DE,BUFFER+2
       LD  HL,BUFFER+2
       LOOP1: CALL CONST
              CALL NZ,SEROUT
              PUSH HL
              OR A
              SBC HL,DE
              POP HL
              JR Z,LOOP1 ; original (non-store)
              LD A,(HL) ; version is JR Z,LOCN
              INC HL
              CALL PUTVID
              JR LOOP1

```

```

040D DB 02 ; POLLU - waits the UARTR and moves any
040F 17 ; waiting character to DE (DE)
0410 DO ; 1st of a DEL string is converted to 07h and
0411 3A 0121 ; rest of string is suppressed. Simplifies subsequent
0414 B7 ; handling by GEMPFEN and saves buffer space.
0415 28 OF
0417 DB 01
0419 E6 7F
041B FE 7F
041D C8
041E F5
041F AF
0420 32 0121
0423 F1
0424 18 OD

POLLU1: IN A,(UARTR)
RLA RET NC
LD A,(DEFLG)
OR A
JR Z,POLLU1
LD A,(UARTD)
AND TFFH
CP 7FH
JR NZ,POLLU2
LD (DEFLG),A ; set flg & convert..
LD A,07H ;..to bell symbol
POLLU2: LD (DE),A
INC DE
LD A,D
CP 2
LIMIT EQU $-1 ; modified on init
RET C
JR Z,SWITCH
DEC DE
RET

043D 00 ; switch: nop ; only pass once
043E 3E C9
0440 32 043D
0443 3E 1B
0445 CD 045F
0448 3E 49
044A CD 045F
044D C9

045D 00
045E 3E C9
045F 32 043D
0460 3E 1B
0461 CD 045F
0462 3E 49
0463 CD 045F

; SEROUT - Outputs the character in <A> to
; the serial port.

SEROUT: PUSH AF
SEROO: IN A,(UARTS)
        AND 40H
        JR Z,SERROO

```

PRINPRES M-80 5 Dec 1983 23:18 PAGE 1 PRESTEL for Nascom 2 & Gemini IVC
PRESTEL V8, PRESTEL terminal program. RL. 22/11/83

```

Title PRINPRES
subtl V1 1357 23/11/83
; Prints PRESTEL buffer to CP/M List device

* 280
asig 0RG 100H

; CP/M equates
jbdos equ 5
; PRES equates
buffer equ 500H

0000' 05 017A      jp start
0100 05 52 49 4E  defb "PRINTRES V1 23/11/83"
0107 50 52 45 55
010B 20 56 31 20
010F 32 33 2F 31
0113 31 2F 38 35
0117 1A             stack:    ; overrides little
0118 2A 2A 20 43  mesbr:   defb 1ah   ; Clear screen
011C 68 65 63 63    defb "*** Check that baud-rate switches"
0120 20 74 68 61
0124 74 20 62 61
0128 75 64 2D 72
012C 61 74 65 20
0130 73 77 69 74
0134 65 68 65 73
0138 20 61 72 65
013C 20 73 65 74
0140 20 66 6F 72
0144 20 70 72 69
0148 6E 74 65 72
014C 20 2A 2A
014P 0D 0A, 20 2D
0153 20 61 6B 79
0157 20 6B 65 79
015B 20 74 6F 20
015P 70 72 6F 63
0163 65 65 64 24
0167 0D 0A 42 75
016B 66 66 65 72
016P 20 63 6F 72
0173 72 75 70 74
0177 65 64 24

0005' 0455 F1           start: ld sp,stack
0456 B7           ld de,mesbr
0457 BA 045C       ld c,9
045A F6 80          or soh
045C D5 01          sero1: out (UARTD),A
045E C9           ret

; PUTVID - sends a character in <A> to the IVC
; Polls the serial port whilst waiting.

045F P5           PUTVID: push af
0460 CD 040D       pvo: call POLLU
0463 DB B2           tn a,(IVCS)
0465 OF             rrca
0466 38 F8           jr c,pvo
0468 F1             pop af
0469 D3 B1           out (IVCD),A
046B C9           ret

; Get a character from the keyboard
; Returns NZ if a character is read.

046C CD 040D       CONST: call POLLU
046F D9           exx
0470 1E FF           ld e,ofh
0472 0E 06           ld c,condir
0474 CD 0005         call jbdos
0477 D9           exx
0478 B7           or a
0479 C8           ret z
047A FE 03           cp conc
047C CA 0374         jp z,exit
047F C9           ret
ret

END

```

SAVEPRES	M-80	5 Dec 1983	23:33	PAGE	1
PRINPPRES V1-1357 23/11/83 M-80 5 Dec 1983 23:18 PAGE 1-1					
<pre> Title SAVEPRES subtitl v 1 1511 18/11/83 ; Makes file from PRESTEL buffer. .z80 org 100H aset org 100H 0100 C3 0157 jp start 0103 53 41 56 45 defb "SAVEPRES V1 18/11/83" 010B 50 52 45 53 010F 20 56 31 20 0113 31 38 2F 31 0117 31 2F 38 33 stack: ; overwrites title ; Workspace ; from: defw buffer+2 ; ebuf: defb 2 0119 0D 0A 46 69 mesfs: defb Odh,Oah,"File saved\$" 011B 6C 65 20 73 011F 61 76 65 64 0123 24 0127 24 0128 0D 0A 4E 6F means: defb Odh,Oah,"No disk space\$" 012C 20 64 69 73 0130 6B 20 73 70 0134 61 63 65 24 0138 0D 0A 42 75 msgbc: defb Odh,Oah,"Buffer corrupted\$" 013C 66 66 72 0140 20 63 6F 72 0144 72 75 70 74 0148 65 64 24 014B 00 24 24 24 deflt: defb 0,"\$\$\$ PRS" 014F 20 20 20 20 0153 20 50 52 53 ; CP/M ; jbdos ; equates ; feb ; equ 5ch ; buff ; equ 80h 0005 000C 0080 0500 0157 31 0117 start: ld sp,stack 015A 21 0500 ld hl,buffer 015D 5E 015E 23 015F 56 0160 BB 0161 E5 0162 B7 0163 ED 0165 52 0166 B1 ; PRES equates ; buffer ; equ 500H end ; PRES equates ; buffer ; equ 500H end 0190 C3 0157 jp start 0193 23 0194 56 0195 EB 0196 E5 0197 B7 0198 13 0199 13 019A ED 52 019C 44 019D 4D 019E E1 019F 30 09 01A1 11 0167 01A4 0E 09 01A6 CD 0005 01A9 C7 prn: exx ld c,6 ld e,0ffh call jbdos cp 0fh jp z,0 exx ld a,(de) exx ld c,5 ld e,a call jbdos exx inc de dec bc ld a,b or c jr nc,prn ret ; warm boot 01C1 13 01C2 0B 01C3 78 01C4 B1 01C5 20 01C7 E3 01C8 07 end </pre>					

SAVEPRES M-80
V 1 1511 18/11/83

5 Dec 1983 23:33 PAGE 1-1

```

jr nc,chn
ld de,msgbc
ld c,9
call jbdos
rst 0 ; warm boot

```

5 Dec 1983 23:33 PAGE 1-2

SAVEPRES M-80
V 1 1511 18/11/83

```

jr nc,chn
ld de,msgbc
ld c,9
call jbdos
rst 0 ; warm boot
inc hl
ld (hl),1ah ; add EOF
ld (ebuf),hl
ld hl,fcb+1 ; Filename present?
ld a,20h
op (hl)
jr nz,open ; yes
ld hl,deflt
ld de,fcb
ld bc,12
ldir
ld b,21 ; Fill up fcb with nulls
xor a
ld (de),a
inc de
dinz $-2
ld de,fcb
ld c,15 ; open file
call jbdos
cp -1
jr z,make
ld de,fcb
ld c,19 ; delete file
call jbdos
cp -1
jr z,nods
ld de,fcb
ld c,15 ; make file
call jbdos
cp -1
jr z,nods
ld hl,(from) ; check end
push hl
ld de,(ebuf)
xor a
ex de,hl
sbc hl,de
pop hl
jr c,exit
ld de,tbuff
ld bc,$0h
ldir
ld (from),hl
ld de,fcb
ld c,21 ; write next rec
call jbdos

```

INSTALLING AN EIGHT INCH DISK DRIVE**By Richard Beal**

I recently added an eight inch drive to my Gemini system. This article describes the various problems I encountered and how to overcome them. My system has a Gemini GM829 disk controller card, with Teac 5.25 inch drives which have the same interface as the 48 tpi Pertec drives that Gemini used to supply. The eight inch drive is a double density double sided Pertec FD650, but experiences with any other eight inch drives would probably be similar.

I powered up the drive with a separate power supply and obtained a cable to connect it to the disk card from Henry's Radio. I generated a version of SYS to support the drive (as a standard single density single sided drive) and booted up the system. To my satisfaction it worked first time, and I started to use it. [Ed. - certain Gemini CP/Ms also have 8" support already incorporated. If the CP/M sign-on message has an 'E' in its version number (e.g. BIOS Vers 2.4 2-SME) then it means that the drive following the 2 Single sided Micropolis drives is an Eight inch one - SSSD. If you want 8" support and have not got the support contact your dealer for BIOS upgrade details.]

I started doing some text processing work and as the drive and fan were a bit noisy I turned it off when I wasn't using it. When I started trying to read the files I had written on the Teac drives, I found that whole tracks had CRC errors that were permanent, although other parts of the disk were all right. Since this happened on both Teacs, I realised that the problem must lie not with the disks or the controller, or the software, but must be something to do with the 8" drive, which wasn't even switched on.

The problem is caused by noise of some sort coming from the cable leading to the 8" drive. This happens only when there is no power to the PCB in the 8" drive, and is also intermittent. This explained why the errors were CRC errors not RNF, as the data written was corrupted and could never be read back, but the sector headers were unaffected. The solution was to rewire the power supply connections and the switch in the 8" drive case so that the switch controlled the drive motor and fan, while the transformer and drive PCB are always live when the entire unit is plugged in.

While doing the rewiring I was uncertain about one of the connections and tried to pull off the insulating cover with a pair of pliers. The next moment there was a terrible sensation through my whole body and then I found myself at the other side of the room, with bits of furniture hurled around. The metal connector had been bent through 90 degrees, which I would not normally have had the strength to do. When I had recovered I found that the 3 amp mains fuse had blown, which probably saved me. Remember that 250V is rather more than the usual 5V we get used to handling, and that it is sensible to unplug everything from the wall before starting work!

The system then worked reliably, but still had one annoying problem. If no disk was in the drive, or if the door wasn't closed, the system would simply hang up indefinitely. This was disastrous when there was no disk in the drive but the door was shut, as the door locks when the drive is selected. Since I couldn't open the door to insert a disk, the only answer was to reset the system. The software is designed to detect the status of the Ready line, but this was not connected. On the 5.25 inch drives, the software times out when the motor stops, but on 8" drives the motor runs continuously.

On studying the 829 manual, it became apparent that it was impossible to configure the card for both 8" with Ready line, and 5.25 inch without Ready line. If the 5.25 inch drives had been Micropolis there would not have been a problem. Therefore I consulted the designer of the 829, who kindly advised a simple modification to the card which enhances it so that it can support this combination of drives.

For Pertec interface 5.25 inch drives, link 3 is normally removed, and this disables the Ready line input. This link should now be reinserted. Link 1 is left as before, linking B to C only. At this point the system will not work, since the 1797 will not operate without a Ready signal, and when the 5.25 inch drives are selected, no signal is provided. Therefore two diodes are added so that when drive 0 or 1 is selected, a Ready signal is provided. When drive 2 is selected, the 8 inch drive Ready signal operates as normal. Insert a diode between pin 22 and pin 26, also pin 22 to pin 28 underneath the 8 inch connector on the card. A hole in the card running from pin 22 to link 1 (A) can conveniently be used for one end of the diodes. The marked end (the cathode) must be at the pin 26 and pin 28 ends. In addition it is essential to alter the value of R18 from 150 to 3K3 (or rather more if you prefer) as otherwise the diodes cannot pull down the Ready line enough to activate it.

Summary of Modification

Applies to GM829 with Pertec or Teac 5.25 inch drives at addresses 0 and 1, and 8 inch drive(s) at addresses 2 and optionally 3.

Link 1: B to C only.

Link 3: Inserted.

Diode from PL3 pin 22 to PL3 pin 26 (cathode end at pin 26).

Diode from PL3 pin 22 to PL3 pin 28 (cathode end at pin 28).

R18 changed from 150 to 3K3 or rather more.

Further Difficulty

One further problem was encountered. When PIPing files to the 8 inch drive, it would sometimes fail to give the drive ready signal. It was being used as a single sided drive with a single sided disk. The drive can tell whether a single or double sided disk has been inserted, because 8 inch disks have the index hole in different places to allow this to be distinguished. Although the software was attempting only to use the first side (side 0), since the Teac drives were double sided and the file was on the second side, the BIOS was first selecting the drive, then selecting the side and doing the I/O operation. Therefore the drive was selected with the second side active. The drive immediately signalled that it was not ready (showing its lack of intelligence). This could be corrected by modifying the BIOS to select the side before the disk, but an easier method was to disable this option on the drive itself. This modification is documented in the Pertec FD650 manual, and is easily carried out. Another advantage of making this modification is that single sided disks may be used as if they are double sided, without the drive objecting. This generally works perfectly, just as 5.25 inch single sided diskettes generally work perfectly when used as double sided.

```

EB1F 2B      MRPNT: DEC    HL      GETCHR   ; DEC 'cos GETCHR INCs
EB20 CD36E8   CALL   JP      Z,PRNTCR ; Get next character
EB23 CA81EB   PRINT:  RET    Z        ; CRLF if just PRINT
EB26 C8      PRNTLP: RET    ZTAB    ; End of list - Exit
EB27 FEA5    ZTAB    CP      Z,DOTAB ; "TAB(" token?
EB29 CA97EB   CP      ZSPC   ; Yes - Do TAB routine
EB2C FEA8    CP      ZSPC   ; "SRC(" token?
EB2E CA9FEB   JP      Z,DOTAB ; Yes - Do SPC routine
EB31 E5      PUSH   HL      "      ; Save code string address
EB32 FE2C    CP      "      ; Comma?
EB34 CA99EB   CP      Z,DOCOM ; Yes - Move to next zone
EB37 FE3B    CP      "      ; Semi-colon?
EB39 CA2E2B   JP      Z,NEXITM; Do semi-colon routine
EB3C C1      POP    BC      ; Code string address to BC
EB5D CD5AED   CALL   EVAL   ; Evaluate expression
EB40 E5      PUSH   HL      ; Save code string address
EB41 3AAD10  LD     A,(TYPE) ; Get variable type
EB44 B7      OR     A       ; Is it a string variable?
EB45 C26DEB   JP      NZ,PRNTST; Yes - Output string contents
EB48 CDB8F9    CALL   NUMASC; Convert number to text
EB4B CDCFF1   CALL   CRTST; Create temporary string
EB4E 3620    LD     (HL), " " ; Followed by a space
EB50 2AE110  LD     HL, FPREG; Get length of output
EB53 34      INC    (HL); Plus 1 for the space
EB54 2AE110  LD     HL, FPREG; < Not needed >
EB57 3AA110  LD     A,(LWIDH); Get width of line
EB5A 47      LD     B,A    ; To B
EB5B 04      INC    B      ; Width 255 (No limit)?
EB5C CA69EB   JP      Z,PRNTNB; Yes - Output number string
EB5F 04      INC    B      ; Adjust it
EB60 3AA110  LD     A,(CURPOS); Get cursor position
EB63 86      ADD    A,(HL); Add length of string
EB64 3D      DEC    A      ; Adjust it
EB65 BB      CP      B      ; Will output fit on this line?
EB66 D481EB   CALL   NC,PRNTCR; No - CRLF first
EB69 C013F2   PRNTNB: CALL  PRS1  ; Output string at (HL)
EB6C AF      XOR    A      ; Skip CALL by setting "Z" flag
EB6D C413F2   PRNTST: CALL  NZ,PRS1; Output string at (HL)
EB70 E1      POP    HL      ; Restore code string address
EB71 C31FEB   JP      MRPNT; See if more to PRINT
EB74 3AAB10  STMLIN: LD    A,(CURPOS); Make sure on new line
EB77 B7      OR     A      ; Already at start?
EB78 C8      RET    Z      ; Yes - Do nothing
EB79 C391EB   PRNTCR JP      ; Start a new line

```

NASCOM ROM

BASIC DIS-ASSEMBLED

PART 4

BY CARL LLOYD-PARKER

Dis-assembly of NASCOM ROM BASIC Ver 4.7

PAGE 40 PAGE 41

Dis-assembly of NASCOM ROM BASIC Ver 4.7

EB7C 3600. ENDINP: LD (HL),0 ; Mark end of buffer
 EB7E 216010 HL,BUFFER-1 ; Point to buffer
 EB81 3ED0 PRNTCR: LD A,CR ; Load a CR
 OUTC CALL ; Output character
 EB82 C9BEE6 DONULL: XOR A ; Set to position 0
 EB86 AF (CURPOS),A ; Store it
 EB87 32CB10 LD A,(NULLS) ; Get number of nulls
 EB8A 3A4110 LD A,0 ; Count them
 EBBD 3D NULLP: DEC A ; Return if done
 RET Z ; Save count
 EB8F F5 PUSH AF ; Load a null
 EB90 AF XOR A ; Output it
 CALL OUTC ; Restore count
 EB91 CDBE6 POP AF ; Keep counting
 EB94 F1 NULLP JP ;

EB98 3A5310 DOCOM: LD A,(COMMAND) ; Get comma width
 EB99 47 LD B,A ; Save in B
 EB9C 3AAB10 LD A,(CURPOS) ; Get current position
 EB9F B8 CP ; Within the limit?
 EBAA D4B1EB CALL NC,PRNTCR ; No - output CRLF
 EBAA D2D2EB JP NC,NEXTIM ; Get next item
 EBAD D60E ZONELP: SUB 14 ; Next zone of 14 characters
 EBAB D2AE CPL ; Repeat if more zones
 EBAB 2F JP ASPOS ; Number of spaces to output
 EBAC C3C7EB JP ; Output them

EBAF F5 DOTAB: PUSH AF ; Save token
 EBB0 CD81F4 CALL FNNDUM ; Evaluate expression
 EBB3 CD90E6 CALL CHKSYN ; Make sure ")" follows
 EBB6 29 DEC HL ; Back space on to ")"
 EBB7 2F POP AF ; Restore token
 EBB8 F1 SUB ZSPC ; Was it "SRC(" ?
 EBB9 D6A8 PUSH HL ; Save code string address
 EBBB E5 Z,DOSPC ; Yes - Do "Y" spaces
 EBBC CAC2EB LD A,(CURPOS) ; Get current position
 EBBF 3AAB10 DOSPC: CPL ; Number of spaces to print to
 EBC2 2F ADD A,E ; Total number to print
 EBC3 83 INC A,NC,NEXTIM ; TAB < Current POS(X)
 EBC4 D2D2EB ASPCS: INC A ; Output A spaces
 EBC8 47 LD B,A ; Save number to print
 EBC9 3E20 LD A," " ; Space
 EBCB CD9BEG SPCLP: CALL OUTC ; Output character in A
 EBCE 05 DEC B ; Count them
 EBCF C2CBBB NZ,SPCLP ; Repeat if more
 EBD2 E1 NEXITM: POP HL ; Restore code string address
 EBD3 CD36EB GETCHR: CALL GETCHR ; Get next character
 EBD6 0326BB PRNTLP JP ; More to print

EBD9 3F526564 REDO: DEFB "?Redo from start",CR,LF,O ; READ or INPUT?
 EBEC 3AC1D0 BADINP: LD A,(READFG) ; READ - ?SN Error
 EBFF B7 OR NZ,DATSNR ; Throw array code string addr
 EBFO C2A7E3 POP BC ; "Redo from start" message
 EBFB C1 LD HI,REDO ; Output string
 EBFA 21D9ER CALL PRS ; Do last INPUT again
 EBFF CD10F2 JP DOAGN ; Test for illegal direct
 EBFA C3FBE4 INPUT: CALL IDTEST ; Get character after "INPUT"
 EC00 7E LD A,(HL) ; Is there a prompt string?
 EC01 FE22 CP ; Clear A and leave flags
 EC05 3E00 LD A,O ; Enable output
 EC05 324510 LD (CPL,FG),A ; No prompt - get input
 EC08 C217EC LD NZ,NOPART ; Get string terminated by ""
 EC0B CDCFF1 CALL QNSTR ; Check for "", after prompt
 EC11 CD90E6 CALL CHKSIN ; Save code string address
 EC12 E5 PUSH HL ; Output prompt string
 EC13 CD13F2 CALL (LD A,n) ; Skip "PUSH HL"
 EC16 5E NOPMPT: PUSH HL ; Save code string address
 EC17 E5 CALL PROMPT ; Get input with "?" prompt
 EC18 C0DCE4 POP BC ; Restore code string address
 EC1B C1 INC C,INPBKR ; Break pressed - Exit
 EC1C DA77E8 INC HL ; Next byte
 EC1F 23 LD A,(HL) ; Get it
 EC20 7E OR A ; End of line?
 EC21 B7 DEC HL ; Back again
 EC22 2B PUSH BC ; Re-save code string address
 EC23 C5 JP Z,NXTDATA ; Yes - Find next DATA stmt
 EC24 C2FEA LD (HL)," " ; Store comma as separator
 EC27 362C INC NXTIM ; Get next item

EC29 C331EC READ: PUSH HL,(NXTDAT) ; Save code string address
 EC2C E5 LD HL,(NXTDAT) ; Next DATA statement
 EC2D 2ADC10 DEFB (OR n) ; Flag "READ"
 EC30 F6 PUSH A ; Flag "INPUT"
 EC31 AF NXITM: XOR A ; Save "READ"/"INPUT" flag
 EC32 32CD10 LD (SP),A ; Get code str' , Save pointer
 EC35 E3 EX GTVLTUS ; Get values

Dis-assembly of NASCOM ROM BASIC Ver 4.7

PAGE 42

PAGE 43

Dis-assembly of NASCOM ROM BASIC Ver 4.7

EC59 CD90E6 NEWMOR: CALL CHKSYN ; Check for comma between items
 EC5C 2C GETVAR: DEFB " , " ; Get variable name
 EC5D CD2DEF GTVLUS: CALL GETVAR ; Save code str", Get pointer
 EC40 E3 EX (SP),HL ; Save variable address
 EC41 D5 PUSH DE ; Get next "INPUT"/"DATA" byte
 EC42 7E LD A,(HL) ; Commas?
 EC43 FE00 CP Z,ANTVLU ; Yes - Get another value
 EC45 CA5SEC JP A,(READRG) ; Is it READ?
 EC48 3ACD10 LD A, (READRG)
 EC4B B7 OR A ; Yes - Find next DATA stmt
 EC4C C2D2EC NZ,FDTLP JP NZ,FDTLP ; More INPUT needed
 EC4F 3E5F LD A,"?" ; Output character
 EC51 CD98E6 CALL OUTC ; Get INPUT with prompt
 EC54 CD9CE4 PROMPT POP DE ; Variable address
 EC57 D1 POP BC ; Code string address
 EC58 C1 INC HL ; Point to next DATA byte
 EC59 DA77E8 INC A,(HL) ; Get byte
 EC5C 23 OR A ; Is it zero (No input) ?
 EC5D 7E DEC HL ; Back space INPUT pointer
 EC5E B7 PUSH BC ; Save code string address
 EC5F 2B DEC HL ; End of buffer
 EC60 C5 PUSH Z,NXTDTA ; Save variable address
 EC61 CA5FEA A,(TYPE) PUSH DE ; Check data type
 EC64 D5 ANTVLU: LD A, (TYPE) ; Is it numeric?
 EC65 3AAD10 OR A ; Yes - Convert to binary
 EC68 B7 Z,INPBIN CALL GETCHR ; Get next character
 EC69 CABEBC JP Z,INPBIN ; Save input character
 EC6C CD35E8 CALL GETCHR ; Again
 EC6F 57 LD D,A ; Start of literal string?
 EC70 47 LD B,A ; Yes - Create string entry
 EC71 FE22 CP A,(READRG) ; "READ" or "INPUT" ?
 EC73 CABEBC JP Z,SPRENT ; Save 00 if "INPUT"
 EC76 3ACD10 LD D,A ; "INPUT" - End with 00
 EC79 B7 OR A ; "DATA" - End with 00 or ":"
 EC7A 57 LD Z,IMSEP ; Item separator
 EC7B CABEBC JP D,;" ; Back space for DTSTR
 EC7E 163A ITMSEP: LD B," ; Get string terminated by D
 EC80 062C DEC HL ; String address to DE
 EC82 2B STRENT: CALL DE,HL ; Where to go after LETSTR
 EC83 CDD2F1 LETSTR: CALL HL,LSTND ; Save HL , get input pointer
 EC86 EB EX (SP),HL ; Save address of string
 EC87 219AEC PUSH DE ; Assign string to variable
 EC8A E3 JP LETSTR ; Set line of current DATA item

EC8B D5 PUSH JP ; Get next character
 EC8C C3AEEA JP ; No "DATA" - Keep looking
 EC8D F000 CALL CP ; Found - Convert input
 EC8E F003 CALL CP ; ANTVLU JP ; MSB of line number
 EC8F C2D2EC CALL CP ; LSB of line number
 EC90 C36SEC CALL CP ; Set line of current DATA item
 EC91 F003 FANDT: CALL CP ; Get next character
 EC92 CD1A1F9 INPBIN: CALL CP ; No "DATA" - Keep looking
 EC93 E3 ASCTFP CALL EX ; Found - Convert input
 EC94 CD6BFB3 CALL CALL ; MSB of line number
 EC95 E1 LTSTND: CALL POP ; LSB of line number
 EC96 CD36E8 CALL CALL ; Set line of current DATA item
 EC97 E1 Z,MORDT JP ; Get next character
 EC98 CD36E8 CALL CALL ; End of line - More needed?
 EC99 E1 Z,MORDT JP ; Another value?
 EC9A 2B LTSTND: CALL CALL ; More needed - Get it
 EC9B CD36E8 CALL CALL ; Restore DATA pointer
 EC9C CAA6EC CALL CALL ; "READ" or "INPUT" ?
 EC9D FE2C CALL CALL ; "READ" or "INPUT" ?
 EC9E CCECEB CALL CALL ; "READ" or "INPUT" ?
 EC9F E3 MORDT: CALL EX ; Get code string address
 ECAT 2B DEC CALL HL ; DEC 'cos GETCHR INCS
 ECAB CD36E8 CALL GETCHR ; Get next character
 ECAC C259EC CALL NZ,NEWMOR ; More needed - Get it
 ECAD D1 POP DE ; Restore DATA pointer
 ECAB 5ACD10 LD A,(READFG) ; "READ" or "INPUT" ?
 ECBB B7 OR A ; DATA pointer to HL
 ECBC 2B EX DE,HL ; Update DATA pointer if "READ"
 ECBD EB INC NZ,UPDATE ; Save code string address
 ECBCA C25CE8 PUSH DE ; More input given?
 ECBCB 21C1EC OR (HL) ; "Extra ignored" message
 ECBCD C410F2 LD HL,EXTIG ; Output string if extra given
 ECBCF E1 CALL NZ,PRS ; Restore code string address
 ECCE C9 RET ;

ECCE 3F457874 EXTIG: DEFB "?Extra ignored",CR,LF,0 ;

ECDD CD70EA FDTLIP: CALL DATA ; Get next statement
 ECDS 23 INC NZ,FANDT ; End of line?
 ECDS C2EBEC CALL OR ; No - See if DATA statement
 ECDD 23 INC HL ; End of program?
 ECDC B6 OR (HL) ; OO OO Ends program
 ECDD 1B06 LD E,OD ; ?OD Error
 ECDF CAC1E3 JP Z,ERROR ; Yes - Out of DATA
 ECDE 23 INC HL ; LS8 of line number
 ECDE 25 INC HL ; MSB of line number
 ECDF EB LD (DATLIN),HL ; Set line of current DATA item
 ECFA 22C910 EX DE,HL ; Get next character
 ECFB EB CALL GETCHR ; "DATA" token
 ECFC C2D2EC JP NZ,FDTLP ; Found - Convert input

Dis-assembly of NASCOM ROM BASIC Ver 4.7

PAGE 44

PAGE 45

```

ECE6 110000 NEXT: LD DE,O ; In case no index given
ECF9 C42DEF NZ,GETVAR ; Get index address
NEXT: CALL (BRKLIN),HL ; Save code string address
      LD BAKSTK ; Look for "FOR" block
      CALL NZ,NFERR ; No "FOR" - NNF Error
      JP SP,HL ; Clear nested loops
      LD PUSH ; Set parity
      DE A,(HL) ; Save index address
      INC HL ; Get sign of STEP
      PUSH AF ; Save sign of STEP
      PUSH DE ; Save index address
      CALL PHLPFP ; Move index value to FPREG
      EX (SP),HL ; Save address of TO value
      PUSH HL ; Save address of index
      CALL ADDPHL ; Add STEP to index value
      ED13 E1 POP HL ; Restore address of index
      CALL FPTHL ; Move value to index variable
      POP HL ; Restore address of TO value
      CALL LOADEP ; Move TO value to BCDE
      ED18 CD62FB ED1B E5 PUSH HL ; Save address of line of FOR
      CALL CMPNUM ; Compare index with TO value
      POP HL ; Restore address of line num
      POP BC ; Address of sign of STEP
      ED20 C1 SUB B ; Compare with expected sign
      ED21 90 CALL LOADEP ; BC = Loop stmt, DE = Line num
      ED22 CD62FB Z,KLIFOR ; Loop finished - Terminate it
      ED25 CA31ED JP DE,HL ; Loop statement line number
      ED28 EB EX (LINEAT),HL ; Set loop line number
      ED29 225C10 LD I,C ; Set code string to loop
      ED2C 69 LD H,B ; Put back "FOR" and continue
      ED2D 60 JP PUTFD ; Put code string to loop

      KLFOR: LD SP,HL ; Remove "FOR" block
      HL,(BRKLIN) ; Code string after "NEXT"
      LD A,(HL) ; Get next byte in code string
      ED32 2ACE10 ED35 7E " ; More NEXTs ?
      ED36 FE2C JP NZ,RUNCNT ; No - Do next statement
      ED38 C2F2E7 CALL GETCHR ; Position to index name
      ED3B CD3688 CALL NEXT1 ; Re-enter NEXT routine
      ED3E CDF9BC ; < will not RETURN to here , Exit to RUNCNT or Loop >

      ED41 CD5AED GETNUM: CALL EVAL ; Get a numeric expression
      ED44 F6 TSTRM: DFB (OR n) ; Clear carry (numeric)
      ED45 37 TSTRR: SCF ; Set carry (string)
      ED46 3AA10 CHKTP: LD A,(TYPE) ; Check types match
      ED49 8F ADC A,A ; Expected + actual
      ED4A B7 OR A ; Clear carry , set parity
      ED4B EB RET PE ; Even parity - Types match
      ED4C C3BFE3 JP TMERR ; Different types - Error?

      ; <<< NO REFERENCE TO HERE >>>
      ED4F CD90E6 CALL CHKSYN ; Make sure "=" follows
      ED52 B4 DEFB ZEQUAL ; "="
      ED53 C35AED JP EVAL ; Evaluate expression
      ED56 CD90E6 OPNPAR: CALL CHKSYN ; Make sure "(" follows
      ED59 28 DEFB "(" ; Evaluate expression & save
      ED5A 2B EVAL: DEC HL ; Precedence value
      ED5B 1600 LD D,O ; Save precedence
      ED5D D5 EVAL: PUSH DE ; Save precedence
      ED5E 0E01 LD C,1 ; Check for 1 level of stack
      ED60 CDBAEB CALL CHKSINK ; Get next expression value
      ED63 CDD1ED CALL OPRND ; Save address of next operator
      ED66 22D010 EVAL: LD (NXTOPR),HL ; Restore address of next opr
      ED69 2AD010 ED6C C1 POP BC ; Precedence value and operator
      ED6D 78 LD A,B ; Get precedence value
      ED6E FE78 CP 78H ; "AND" or "OR" ?
      NC,TSTNUM ; No - Make sure it's a number
      ED70 D444ED CALL A,(HL) ; Get next operator / function
      ED73 7E LD D,O ; Clear Last relation
      ED76 D635 RLTP: SUB ZGTR ; ">" Token
      ED78 DA32ED JP C,POPRND ; "+ / * AND OR - Test it
      ED7B FE05 CP ZLTH+1-ZGTR ; "< = >" Function - Call it
      ED7D D232ED CP ZEQUAL-ZGTR ; "="
      ED80 FE01 D ; Test for legal
      ED82 17 XOR D ; combinations of < = >
      ED83 AA CP D ; by combining last token
      ED84 BA LD A ; with current one
      ED85 57 C,SNERR ; Error if "<<" "" or ">>""
      ED86 DADE3 JP (CUREPR),HL ; Save address of current token
      ED89 22D510 LD CALL GECHR ; Get next character
      ED8C CD3688 JP RLTP ; Treat the two as one
      ED8F C376D

```

Dis-assembly of NASCOM ROM BASIC Ver 4.7

PAGE 47

```

EDD1 AF          OPRND: XOR A,(TYPE),A      ; Get operand routine
EDD2 3AAD10      LD    A, (TYPE),A      ; Set numeric expected
EDD5 C036EB      CALL GETCHR             ; Get next character
EDD8 1E24         LD    E, MO              ; ?MO Error
EDD9 CAC1E3       JP    Z, ERROR          ; No operand - Error
EDDD DA4F9        JP    C, ASCTPP         ; Number - Get value
EDDE CD7E9        CALL CHKTR             ; See if a letter
EDF5 D22EE        JP    NC, CONVAR        ; Letter - Find variable
EDF6 FE0C        CP    ZPLUS              ; Get next character
EDF9 CAD1ED      JP    Z, OPRND           ; ?MO Error
EDFB FE0C        CP    ","                 ; No operand - Error
EDFC FE0C        CP    Z, ASCTPP         ; See if a letter
EDFD CAFA9        CALL CHKTR             ; Letter - Find variable
EDFE FE0C        CP    NC, CONVAR        ; ?MO Error
EDFF FE0C        CP    ZMINUS            ; Yes - Look for operand
EDF2 CA11EE      JP    Z, OPRND           ; ?MO Error
EDF5 FE22         CP    ","                 ; No operand - Error
EDF7 CAFF1        JP    Z, QSTR             ; Get string terminated by """
EDFA FEAA         CP    ZNOT               ; Yes - Create FP number
EDFC CA0EF        JP    Z, ZMINUS          ; "-" Token ?
EDFF FE07         CP    Z, MINUS           ; Yes - Do minus
EDF2 CA55F1      JP    Z, DORN             ; Literal string ?
EDF4 D6B5         SUB   Z$GN              ; Is it a function?
EDF6 D253EE      JP    NC, PROST           ; Yes - Evaluate function
EDF9 CD56ED      EVLPAR: CALL OPENPAR        ; Evaluate expression in "("
EDFB CD90E6      CALL CHKSTN           ; Make sure ")" follows
EDFB 29          RET               ; Make sure ")" follows
EB10 C9          RET               ; Make sure ")" follows

```

35

Dis-assembly of NASCOM ROM BASIC Ver 4.7

PAGE 46

```

ED92 7A          FOPRND: LD    A,D      ; < = > found ?
ED93 B7          OR    A, (TYPE)        ; Set < = > found ?
ED94 C2ABEE      OR    NZ, NSTRED      ; Yes - Test for reduction
ED97 TE          LD    A, (HL)           ; Get operator token
ED98 22C510      LD    (CUROPR), HL  ; Save operator address
ED9B D6AC         SUB   C, ZPLUS          ; Operator or function?
ED9D DB          RET               ; Neither - Exit
ED9E FE07         EDGE FE07          ; Is it + - * / ^ AND OR ?
EDAO DO          EDAA DO             ; No - Exit
EDA1 5F          LD    E, (TYPE)        ; Coded operator
EDA2 3AAD10      LD    A, (TYPE)        ; Get data type
EDA5 3D          DEC               ; FF = numeric , 00 = string
EDA6 B3          CP    ZOR+1-ZPLUS     ; Combine with coded operator
EDA7 TB          EDAB 07             ; Get coded operator
EDA8 CA05E3      LD    Z, CONCAT        ; String concatenation
EDA9 07          ADD               ; Times 2
EDAD 5F          LD    A,E              ; To DE (D is 0)
EDAE 21A4E2      LD    HL, PRITAB       ; Precedence table
EDB1 19          ADD               ; To the operator concerned
EDB2 78          LD    A,B              ; Last operator precedence
EDB3 56          LD    D, (HL)           ; Get evaluation precedence
EDB4 BA          CP    D, (HL)           ; Compare with eval precedence
EDB5 DO          RET               ; Exit if higher precedence
EDB6 23          INC    NC              ; Point to routine address
EDB7 CD44ED      CALL HL             ; Make sure it's a number

```

SMTKHS:

```

EDBA 05          PUSH  BC             ; Save last precedence & token
EDBB 0169ED      LD    BC, EVAL3        ; Where to go on prec' break
EDBE 05          PUSH  BC             ; Save on stack for return
EDBF 43          LD    B, E             ; Save operator
EDC0 4A          LD    C, D             ; Save precedence
EDC1 CD44FB      CALL STAKFP        ; Move value to stack
EDC4 5B          LD    E, B             ; Restore operator
EDC5 51          LD    D, C             ; Restore precedence
EDC6 4B          LD    C, (HL)           ; Get LSB of routine address
EDC7 23          INC    HL             ; Get MSB of routine address
EDC8 46          INC    B, (HL)           ; Save routine address
EDC9 23          EDCA C5             ; Save routine address
EDCB 2AC510      LD    BC, (CHROPR)    ; Address of current operator
EDCE C35DED      JP    EVAL1          ; Loop until prec' break

```

Dis-assembly of NASCOM ROM BASIC Ver 4.7

PAGE 48

EE33 0600 PROFST: LD B,O ; Get address of function
 EE35 07 RLCA ; Double function offset
 EE36 4F LD C,A ; BC = Offset in function table
 EE37 C5 PUSH BC ; Save adjusted token value
 GETCHR CALL
 EE38 C136E8 LD A,C ; Get next character
 EE39 79 CALL ; Get adjusted token value
 EE3C F22 CP 2*ZPOINT-ZSGN) ; Adjusted "POINT" token?
 EE3E CA79FF JP Z,POINTB ; Yes - Do "POINT" (not POINTB)
 EE41 F2D CP 2*(ZLEFT-ZSGN)-1 ; Adj' LEFT\$ RIGHTS\$ or MID\$?
 C,ENVAL JP ; No - Do function
 EE45 D5FEE CALL OPNPAR ; Evaluate expression (X,...
 EE46 C56ED CALL CHKSIN ; Make sure "", follows
 EE49 C0D0E6 CALL ""
 EE4C 2C DEFB ;
 EE4D CD45ED TSISTR CALL
 EE50 EB EX DE,HL ; Make sure it's a string
 EE51 2A5410 LD HL,(FPREG) ; Save code string address
 EE54 E3 EX (SP),HL ; Get address of string
 EE55 E5 PUSH HL ; Save address of string
 EE56 EB EX DE,HL ; Save adjusted token value
 EE57 CD84F4 CALL GETINT ; Restore code string address
 EE5A EB EX DE,HL ; Get integer 0-255
 EE5B E3 EX (SP),HL ; Save code string address
 EE5C C367EE JP GOFINC ; Save integer,HL = adj', token
 ; Jump to string function

EE5F C09EE FNVAL: CALL EVALPAR ; Evaluate expression
 EX (SP),HL ; HL = Adjusted token value
 EE63 111DEE LD DE,RETNUM ; Return number from function
 EE66 D5 PUSH DE ; Save on stack
 EE67 010F01 GOFUNC: LD BC,FNCTAB ; Function routine addresses
 EE6A 09 ADD HL,BC ; Point to right address
 EE6B 4E INC C,(HL) ; Get LSB of address
 EE6D 66 LD H,(HL) ; Get MSB of address
 EE6E 66 LD L,C ; Address to HL
 EE6F E9 JP (HL) ; Jump to function

EE70 15 SGNEXP: DEC D ; Dec to flag negative exponent
 ZMINUS CP ; "-" token?
 RET Z ; Yes - Return
 EE71 READ CP ; "-" ASCII ?
 EE73 C8 RET Z ; Yes - Return
 EE74 FE2D INC D ; Inc to flag positive exponent
 EE77 14 INC CP ; "+" ASCII ?
 EE78 FE2B RET Z ; Yes - Return
 EE7B FEAC CP ; "+" token?
 EE7D 08 RET Z ; Yes - Return
 EE7E 2B DEC HL ; DEC 'cos GNTCHR INCs
 EE7F C9 RET ; Return "NZ"

PAGE 49

Dis-assembly of NASCOM ROM BASIC Ver 4.7

EE80 F6 POR: (OR n) ; Flag "OR"
 EE81 AF PAND: XOR A ; Flag "AND"
 EE82 F5 PUSH AF ; Save "AND" / "OR" flag
 EE83 CD44ED CALL TSTNUM ; Make sure it's a number
 EE86 CD8BE9 CALL DEINT ; Get integer "22768 to 32767
 EE89 F1 POP AF ; Restore "AND" / "OR" flag
 EE8A EB EX DE,HL ; <- Get last value
 EE8B C1 POP BC ; <- value
 EE8C E5 EX (SP),HL ; <- from
 EE8D EB EX DE,HL ; <- stack
 EE8E CD54F8 CALL FPBCDE ; Move last value to FPREG
 EE91 F5 PUSH AF ; Save "AND" / "OR" flag
 EE92 CD8BE9 CALL DEINT ; Get integer "22768 to 32767
 EE95 F1 POP AF ; Restore "AND" / "OR" flag
 EE96 C1 POP BC ; Get value
 EE98 21F,FO LD A,C ; Get LSB
 EE9B C2A?EE LD HL,ACPASS ; Address of save AC as current
 EE9E A5 AND NZ,POR1 ; Jump if OR
 EE9F 4F LD C,A ; "AND" LSBS
 EEAO 78 LD A,B ; Save LSB
 EEA1 A2 AND D ; Get MBS
 EEA2 E9 JP (HL) ; "AND" MSBs
 EEA3 B3 OR E ; Save AC as current (ACPASS)

EEA4 4F LD C,A ; "OR" LSBS
 EEA5 78 OR D ; Save LSB
 EEA6 B2 OR (HL) ; Get MSB
 EEA7 E9 JP ; Save AC as current (ACPASS)

EEA8 21BAE0 TSTDRED: LD HL,CMPLOG ; Logical compare routine
 EEAB 3AAD0 LD A,(TYPE) ; Get data type
 EEAE 1F RRA ; Carry set = string
 EEAF 7A LD A,D ; Get last precedence value
 EEBO 17 RLA ; Times 2 plus carry

EEB1 5F LD E,A ; To E
 EEB2 1664 LD D,64H ; Relational precedence
 EEBA 78 LD A,B ; Get current precedence
 EEBC BA CP D ; Compare with last
 EEBD DO RET NC ; Eval if last was rel' or log'
 EEBF C2BAED JP STKTHS ; Stack this one and get next

Dis-assembly of NASCOM ROM BASIC Ver 4.7

PAGE 50

```

        CMPLOG: DEFW    ; Compare two values / strings
        CMPLOG1: LD A,C   ; Get data type
        OR A
        RRA
        POP BC
        DE POP
        PUSH AF
        ; Save status
        ; Check that types match
        ; Result to comparison
        ; Save for RETURN
        ; Compare values if numeric
        ; Compare two strings
        ; Set type to numeric
        ; Save string name
        ; Get current string
        ; Get length of string
        ; Get length of address
        ; Get LSB of address
        ; Get MSB of address
        ; Restore string name
        ; Restore address of string
        ; Save length of string
        ; Save length of string
        ; Get second string
        ; Get address of second string
        ; Restore length of string 1
        ; Restore address of string 1
        ; Bytes of string 2 to do
        ; Bytes of string 1 to do
        ; Exit if all bytes compared
        ; Length to D
        ; POP HL
        ; LD A,E
        ; LD A,E
        ; OR D
        ; RET Z
        ; LD A,D
        ; SUB C
        ; RET A
        ; XOR E
        ; LD A
        ; INC A
        ; RET NC
        ; DEC D
        ; LD E
        ; INC A,(BC)
        ; INC HL
        ; INC BC
        ; INC CC
        ; JP C31ERB
        ; CMPSTR: INC A,A
        ; ADC A,A
        ; POP BC
        ; AND B
        ; ADD A,-1
        ; A,A
        ; SBC BC
        ; JP FIGREL
        ; Set current value & continue
    
```

37

Dis-assembly of NASCOM ROM BASIC Ver 4.7

PAGE 51

```

        EFB08 165A      BNNOT: LD D,5AH   ; Precedence value for "NOT"
        EFB0A CD55ED      CALL EVAL1
        EFB0D CD44ED      CALL TSTNUM
        EFB10 CD88B9      CALL DEINT
        EFB13 7B          LD A,E
        EFB14 2F          CPL
        EFB15 4F          LD C,A
        EFB16 7A          LD A,D
        EFB17 2F          CPL
        EFB18 CDF1FO      CALL ACPASS
        EFB1B C1          POP BC
        EFB1C C369ED      JP EVAL3
        ; Eval until precedence break
        ; Make sure it's a number
        ; Get integer -32768 - 32767
        ; Invert LSB
        ; Save "NOT" of LSB
        ; Get MSB
        ; Invert MSB
        ; Save AC as current
        ; Clean up stack
        ; Continue evaluation
        ; DEC 'cos GETCHR INCS
        ; Get next character
        ; End of DIM statement
        ; Make sure "", follows
        ; Return to "DIMRET"
        ; Save on stack
        ; End of DIM statement
        ; Find variable address, to DE
        ; Set locate / create flag
        ; Get First byte of name
        ; Flag "Create" variable
        ; See if a letter
        ; $SN Error if not a letter
        ; Clear second byte of name
        ; Set type to numeric
        ; Get next character
        ; Numeric - Save in name
        ; See if a letter
        ; Letter - Get another
        ; String variable?
        ; No - Numeric variable
        ; A = 1 (string type)
        ; Set type to string
        ; A = 80H , Flag for string
        ; Add byte of name has bit 7 on
        ; Reserve second byte on name
        ; Get next character
        ; Array name needed?
        ; Yes - Get array name
        ; No array with "FOR" or "FN"
        ; Get value again
        ; Subscripted variable?
        ; Subscript
        ; Yes - Sort out subscript
    
```

```

EF75 AF NSCFOR: XOR A          ; Simple variable
EF76 32CB10 LD (FORFLG),A      ; Clear "FOR" flag
EF77 E5 PUSH HL                 ; Save code string address
EF78 D,B LD DE,FMREV             ; DE = Variable name to find
EF79 E,C LD HL,(VNRGM)          ; FN argument name
EF7A 59 LD HL,(PWRGM)           ; Is it the FN argument?
EF7B 2ADE10 CALL CPDEHL        ; Point to argument value
EF7C 2AD610 LD DE,FMARG          ; Yes - Return FN argument value
EF7D 2AF77 JP HL,(VAREN)         ; End of variables
EF7E 2AD810 LD DE,HL             ; Address of end of search
EF7F EB EX HL,(PROGRD)          ; Start of variables address
EF80 2AD610 LD DE,CPDEHL        ; End of variable list table?
EF81 CA8EF FNDVAR: CALL JP Z,CFEVAL   ; Yes - Called from EVAL?
EF82 11E010 LD A,C              ; Get second byte of name
EF83 C54F7 SUB (HL)             ; Compare with name in list
EF84 96 INC HL                 ; Move on to first byte
EF85 23 NZ,FNTHR               ; Different - Find another
EF86 C2D9EF LD A,B              ; Get first byte of name
EF87 78 SUB (HL)               ; Compare with name in list
EF88 96 FNTHR: INC HL            ; More on to LSB of value
EF89 C4DEF Z,RETADR             ; Found - Return address
EF90 CADCEF TNC HL              ; <- Skip
EF91 25 INC HL                 ; <- over
EF92 25 INC HL                 ; <- F.P.
EF93 25 INC HL                 ; <- value
EF94 25 FNDVAR                ; Keep looking
EF95 C8F8EF POP HL              ; Restore code string address
EF96 CFEVAL: EX (SP),HL          ; Get return address
EF97 E5 PUSH DE,FMREV             ; Save address of variable
EF98 D5 LD DE,CPDEHL             ; Return address in EVAL
EF99 1125EE CALL DE,CPDEHL        ; Called from EVAL ?
EF9A E6 C9AE6 POP JP             ; Restore address of variable
EF9B D1 ADD (SP),HL              ; Yes - Return null variable
EF9C E5 ADD BC,HL                ; Put back return
EF9D E5 PUSH BC                 ; Save code string address
EF9E C5 PUSH BC                 ; Save variable name
EF9F C5 LD BC,6                  ; 2 byte name plus 4 byte data
EF9G 010600 LD HL,(ARREND)        ; End of arrays
EF9H 2ADA10 PUSH HL              ; Save end of arrays
EF9I E5 ADD HL,BC                ; Move up 6 bytes
EF9J 09 POP BC                  ; Source address in BC
EF9K C1 FFCO CALL HL              ; Save new end address
EF9L E5 PUSH HL,MOVUP             ; Move arrays up
EF9M C5 POP HL,(ARREND)          ; Restore new end address
EF9N 60 LD H,B,(ARREND),HL        ; Set new end address
EF9O 69 LD L,C,(ARREND),HL        ; Set new end address
EF9P 22D810 LD (ARREND),HL          ; Set new end address

EFCE 2B ZEROLP: DEC HL          ; Back through to zero variable
EFCF 3600 LD (HL),0               ; Zero byte in variable
EFDF 1 CD8AE6 CALL CPDEHL        ; Done them all?
EFDF 4 C2C8EF JP NZ,ZEROLP       ; No - Keep on going
EFDF 7 D1 POP DE                ; Get variable name
EFDF 8 73 LD (HL),E               ; Store second character
EFDF 9 23 INC HL,D               ; Store first character
EFDF 10 72 LD INC HL,D           ; Address of variable in DE
EFDF 11 23 RETADR: EX DE,HL      ; Restore code string address
EFDF 12 71 POP HL                ; Set result to zero
EFDF 13 70 (FPEXP),A             ; Also set a null string
EFDF 14 71 HL,ZERBYN             ; Save for EVAL
EFDF 15 72 (FPREG),HL            ; Restore code string address
EFDF 16 73 HL                   ; Save code string address
EFDF 17 74 (LCRFLG)              ; Locate/Create and Type
EFDF 18 75 (SP),HL                ; Save and get code string
EFDF 19 76 D,A                  ; Zero number of dimensions
EFDF 20 77 HL,ZERFLG             ; Save number of dimensions
EFDF 21 78 HL,ZERNAME            ; Save array name
EFDF 22 79 CP7T67                ; Get subscript (0-32767)
EFDF 23 7A CALL FPPINT            ; Restore array name
EFDF 24 7B POP BC                ; Get number of dimensions
EFDF 25 7C POP AF                ; Save in D
EFDF 26 7D EX (SP),HL              ; Save subscript value
EFDF 27 7E PUSH HL,DE             ; Save LCRFLG and TYPE
EFDF 28 7F CALL CHKSYN            ; Count dimensions
EFDF 29 7G INC A,D,A              ; Save in D
EFDF 30 7H LD A,(HL)              ; Get next byte in code string
EFDF 31 7I PUSH HL,DE,HL            ; Comma (more to come)?
EFDF 32 7J CP Z,SCPFLP            ; Yes - More subscripts
EFDF 33 7K JP Z,SCPFLP            ; Make sure ")" follows
EFDF 34 7L CALL DEFBL             ; Save code string address
EFDF 35 7M LD (NXTOPR),HL          ; Get LCRFLG and TYPE
EFDF 36 7N POP HL,(LCRFLG),HL        ; Restore Locate/Create & type
EFDF 37 7O E,O                  ; Flag not CSANE* or CLOAD*
EFDF 38 7P PUSH DE,DE,mn            ; Save number of dimensions (D)
EFDF 39 7Q LD DE,mn                ; Skip "PUSH HL" and "PUSH AF"

```

BOOK REVIEWS**By Rory O'Farrell**

The short interval between the arrival of the last two 80-BUS Newses, and the assumed deadline for the Christmas issue means that the following notes are thrown together in somewhat of a hurry to get the disc in the post. As most microcomputer enthusiasts, I now find it difficult to use an ordinary typewriter (even, dare I say it, an IBM). These notes are prepared using a text editor, in this case WordStar, and a disc with the files on it posted off to the Editor. The editorial discretion is exercised, the disc output is fed through his Qume, and camera ready copy is produced from what is substantially my original typing.

The tools to do this are Word processor or text Editor programs. Nearly every vendor of software can supply at least one of these, sometimes a number of different programs. Each such program has its adherents and as the numbers of adherents grow, so the book publishers reflect this by publishing books on particular word processing programs.

WordStar is one of the most widely used text editors. This can clearly be seen in the number of books available for it. Two of these have recently come to my attention.

WordStar Made Easy by Walter Ettlin, published Osborne/McGraw-Hill is an easy to read "how to use it" manual on WordStar. It is certainly streets ahead of the manual supplied with the program itself. [Ed. - I wonder if Rory is referring to WordStar 3.0, as the 3.3 manual is considerably better and is also typeset?] This book is typeset, and well laid out. The subject is broken up into 18 sections, which conduct the reader logically from turning on the computer and getting WS running to complicated formatting and printing using files of data.

An example of this might be the preparation of circular letters to clients, including a reference by name within the body of the letter to their wife. The phrase "and we look forward to seeing you and your wife nnnnn at our Christmas party" will force a line to different lengths, depending on the length of the name. The line with "Ann" in it will be much shorter than the line with "Theodora". If the body of the letter is right justified, then it will be rare for the right margin of the line with the insertion to come to the correct place on the paper. WS has an optional program called MailMerge, which will print such a letter, extracting the variables from a separate file. It will also reformat the body of the letter to accomodate different length insertions, so that the above discussed problem does not arise. Having read Ettlin, one would be well able to start work on such a project, even had one never used a Word processor program before.

Another WordStar book is "**WordStar and CP/M made Easy**" by Lee, published John Wiley and Sons.

This book has been written and typeset using WordStar, the typesetting having been done on what appears to be a daisy-wheel typewriter. In consequence, it is tiring to read, both as the typestyle is typewriterish, and also quite small (about 7pt. according to my measurement). The typewriter is all right for short documents, but most book publishers nowadays seem to think that it will do for longer ones as well. They loose sight of the vast amount of thought and effort that has gone into the design of typefaces, and the contribution to legibility that these make. As the source file of the book is on disk, why don't they feed it into a compositor rather than a typewriter?

That said, this book is more a advanced and fuller treatment of WordStar than the foregoing. For most users, it will not be relevant, but if you are trying to do something really tricky, then I think this is the book for you. I would not suggest that you set any great store by his treatment of CP/M. He deals with CP/M in three chapters at the end of the book, discussing the syntax of the commands, the use of the intrinsic commands and of the supplied transient commands. It is very much an introduction - aimed, I imagine at the person who wishes to use WordStar, and doesn't want to do much more on the computer than that.

So there they are: Ettlin if you have never used a text editor before, Lee if you have and want to get really tricky with WordStar.

If you are one of the many contemplating the plunge into CP/M, then you might do worse than invest in "**CP/M and the Personal Computer**" by Dwyer and Critchfield, published Addison Wesley.

This 490 page quarto book is an easy to read introduction to CP/M, both to the intricacies of CP/M itself and to many of the major programs which run on it. It gives a readable introduction to CP/M, ultimately getting deeply involved, writing on assembly language programming for interfacing with CP/M, and discussing the CP/M supplied transients in detail. It goes further, surveying some Word processing programs, a data base management system (dBASE II), an accounting package (Peachtree), and spreadsheets. Its survey of these might be sufficient justification for you to purchase it, although I stress that the surveys are not (and do not purport to be) encyclopediac. They consist of a general introduction to the area, and a more detailed discussion/example of the use of one of the typical programs of the area.

There is an interesting discussion on MBASIC and BASCOM, and another on C, which might whet your appetite to go further down that road. I for one intend to stick to Pascal! The section on Assembly language suffers from 3080 mnemonics, but is advanced enough to deal with adding customised I/O drivers to the BIOS. See it, particularly if you are not yet into CP/M - it might be just what you need.

Another book on the same lines is **CP/M - The Software Bus** by Clarke, Eaton and Powys-Lybbe, published Sigma Technical Press (dist. John Wiley).

This book is written by three long time members of the UK CP/M User Group. That is good and bad. Good in that they are well acquainted with CP/M and its intricacies, bad in that they often overlook, through utter familiarity, little matters which would prove awkward for the tyro. It surveys CP/M, comparing and contrasting versions 1.3 up to 3.0 and CP/M 86, dealing also with MP/M. It gives a good discussion of the usual CP/M transients, well illustrated with examples, but occasionally omitting a little nugget of information which I'm sure they knew, and which can be a lifesaver. For example, a SUBMIT file can have parameters \$1....\$9. Undocumented, but working nevertheless, is \$0, which refers to the name of the SUBMITted file itself. This can save a lot of trouble, and I'm surprised that these authors did not draw our attention to it.

Well described are the different assemblers, both from Digital Research and other sources, including the various User Group contributions. The high level languages get a good treatment, CBASIC, MBASIC and BASCOM, Pascal MT, CIS COBOL and FORTRAN all being covered in survey. More space is given to the more popular of these, so MBASIC and BASCOM are fairly fully covered. Similarly, the various editors/Word processors, including ED. I have been asked "if ED is so bad, why does every book on CP/M treat on it in detail?".

There are two reasons. First of all, it comes free with CP/M, and as yet DRI have not seen fit to supply a free WordStar or GEM PEN. Secondly, it is not slow, and (rarity of rareties) can be driven from a SUBMIT file for most of its functions. I know no other editor which will allow that. Unimpressed cries of "So?". Let me tell you a story.

It was a dark and stormy night - sorry, I forgot I wasn't Snoopy. Some time ago, I needed to transfer a suite of programs and data from an Osborne. This was due to the ridiculous disc capacity of that machine, making it unable to cope with the amount of information without major revision of the program. So, as a simple expedient, we thought, "Send it all down to Rory's GM813, which has 800k drives attached, and let it get on with it". We (naturally) did not have a modem transfer program, and even if we had, we could not at that time access the status port on the Osborne RS232 line, which modem programs always require. So we broke the programs and data up into 4k blocks, converted to Intel Hex format, and pipped them out through the PTP:. The GM813 received them through the RDR:. 25 files! We did the entire transmission under a SUBMIT file. Similarly at the receiving end, we used another SUBMIT file. We discovered that PIP and the PTP: add 40 nulls to the start of each transmission, and we had to get these off before LOADING the files back to using the [H] option will clear the nulls), we added a few lines to the SUBMIT file to call up ED, strip off 40 nulls from the file in question, exit ED and LOAD the file. Including transmission, the whole job took about one hour, which we spent watching 'Yes Minister' on TV, keeping an eye on the computers every ten minutes or so.

Anyway, enough of a digression. Back to our muttons. This book also deals with assembly language and CP/M. I should stress that it doesn't do this as fully as Miller (reviewed 80-BUS News, Vol 2, No. 4), nor for that matter does the last book, but well enough (apart from 8080 mnemonics) to get you started in the right direction. It has an interesting final chapter giving patches to cure some of the bugs in the standard CP/M transients (the patch for PIP is already available in the HR Utilities disc). If you know a bit about CP/M, and are a computer enthusiast, then this is probably the book for you.

Z80 Assembly Language Subroutines by Leventhal and Saville, published Osborne/McGraw-Hill is of the usual high standard of Leventhal's works. It treats Assembly language programming on the assumption that the reader will have had experience in some form of assembly language - it is by way of a conversion manual to the Z80 from other machines. The authors deal with methods of getting the addressing modes not supported in the Z80, which makes for very interesting reading. They include a discussion of common programming errors, and 58 fully commented listings of useful subroutines such as HEX/ASCII conversion, array addressing etc. These are fully commented, with details of the calling conventions, registers used, and times taken. If only we had had this book four years ago! As an added bonus, it uses Z80 mnemonics!

SuperCalc! The Book by D.H. Beil, published Reston (distr. Prentice-Hall) is concerned with taking the reader through the facilities of SuperCalc. It is very clear and easy to follow, although you have to follow the route the author maps out, for easiest reading. It contains a full description of the SuperCalc commands, with detailed examples. I'm using it in conjunction with SC - SC has a good help level, but often one needs the explanation expanded somewhat. For this I refer to Beil. It also contains a full bibliography of articles and books on SuperCalc and other spreadsheets.

The editor, when he's not exercising his discretion, keeps the mailing list for this learned Journal on dBASE II. How this was ever managed is a matter for considerable conjecture, as the dBASE II manual must win prizes for being THE MOST DIFFICULT manual to read of all application programs. It consists of some ten or eleven sections, all in indexed tabs. It starts off with a section telling you all the new facilities and alterations added to this version, completely forgetting that you have just purchased it and don't know anything about the old features. The actual start of the manual seems to be down some four or five sections. It needs a map, or better still, a large label saying "The Secrets of dBASE II revealed! START HERE"

If you look at the software pricelists, you will notice that there are two entries for dBASE II. One is approximately £20 dearer than the other. This is a version supplied with the standard manual, and a further manual called **Everyman's Database Primer** by Robert Byers, published Ashton-Tate (dist. Prentice-Hall, I think) at £12. This book is 300 pages, quarto sized, and typeset (thank God). It is a very readable book, taking all its examples from dBASE II usage. Using a fairly simple example, it proceeds to show how a database can access information, and manipulate it into a desired form. Having read it, I began to feel that I might achieve something with dBASE II at last.

A slightly more advanced book on the same subject is **dBASE II User's Guide** by Adam Green, published Prentice-Hall at £24.65.

This is another book in the "get your own daisywheel to do the typesetting" school. It is spiral bound, consisting of 150 pages, quarto. It is not as readable as Byers, though there is a slightly fuller treatment of dBASE II in it. Its layout does not help easy reading - it could do with the pages of type being shrunk some 10-15% before printing, to compact them slightly. Better yet, it could be properly typeset.

Of the two of these books, I feel that Byers is the easier to read, and the better value. Neither of these books does away with the need to consult the dBASE II manual for elaboration, and neither of them is the last word on this program. What it really needs is a patch to call up a well written HELP facility, such as exists in WordStar and SuperCalc. Why don't more software authors use such a method? [Ed. - again, I wonder if Rory has not got the latest dBASE as 2.4 does have a HELP facility.]

PASCAL

By Rory O'Farrell

Of recent months, my mantle as advocate of Pascal seems to have been assumed by Dr. Dark, who has been prolix in his advocacy of it. I've recently purchased a copy of ProPascal, a full native code compiler for the Z80, and have seen and used a copy of the JRT Pascal V3. In the next issue of the 80-BUS news, I hope to review the ProPascal in detail. I do not intend to review the JRT Pascal, as coming to terms with the full facilities of an ISO standard Pascal is quite sufficient work for anyone who has not previously used one, but I will attempt to persuade a friend who has the JRT Pascal to review it. Perhaps we will be able to work on a joint article to describe these two programs.

AUNT AGATHA'S AGONY COLUMN**By David Parkinson****EPROM PROGRAMMERS**

This issue I start with a few comments about the Bits & PCs EPROM programmer that appeared as the Gemini G808. I bought one shortly after they first appeared, and have used it quite a bit since then. Some time ago I started to have trouble programming some of my 2716s, (I never used it for 2708s), and even after overprogramming them several times some bytes were still not programmed. I put this down to old-age on the part of the EPROMs, after all they had been through the program/erase cycle many times, and so I marked them as suspect and put them on one side. Some months later I happened to check the programming voltage on an EPROM as it was being programmed, and found it was only 21v rather than the required 25v. Off load the programmer produced the correct 25v. This made me dig out the 2716 data sheet, and a quick glance showed that a maximum current of 25ma could be drawn from the 25v supply during programming. I removed the 2716 from the programmer, and replaced it by a 1k resistor from pin 21 to ground. (25v across 1k gives a current of 25mA). I then started "programming" and measured the programming voltage that appeared across the 1k resistor - 18v. Bingo, there was my answer, the charge pump that generates the 25v supply for G808 was obviously rather short of breath, and unable to provide the necessary power. The 2716s I had had trouble with were obviously not programming because the programming voltage was too low. Perhaps with use the programming current actually taken by a 2716 slowly increases, and these had reached the stage where the on-board 25v supply was seriously overloaded.

The 25v is generated by a charge-pump circuit based round a 555 timer running as an oscillator. This runs off the +12v and -5v supplies, and theoretically adds another 17v onto the 12v line (ignoring all losses!), which is then regulated to 25v. I scrawled in the proverbial junk box and tried changing the 555 to no effect. Altering the values of various components around the 555 didn't help either. So I went to the drawer containing "projects started but never finished" and dug out the last of my EPROM programmer designs that had failed to see the light of day (until now). This particular one used a Texas Instruments TL497 switching regulator in a step-up mode to generate 25v from a 5v supply. This I connected in parallel with the existing voltage generator on G808, and there-after I had my 25v. The 2716s previously labelled "defunct" now programmed perfectly. As this fix worked I progressed no further.

My solution (of getting the 25V from elsewhere), is one way out, but if anyone with the same problem can come up with a suitable simple modification to the G808 circuit - send it in. Either as a few words which I can include in a later column, or as a short article in its own right (in which case you get paid!).

Generous offer THAT NO-ONE SHOULD REFUSE

Talking of articles for the NEWS, if an article is submitted on a Gemini-format CP/M disk then the odds of it being published shorten considerably. So, in order to help the balance of articles in favour of non-disk (or non-CP/M) systems, I am offering to accept articles on cassette tape (Nascom 2 or Gemini format - not Nascom 1 tapes I'm afraid) or disk (5.25" or 8" - any format). These I will transcribe and pass on to the Editor. Note: this offer applies only to machine readable media - I'm not offering to type anything in from paper! All I ask is that you include two things:

- 1) A few words telling me what to expect (e.g. Naspen file % 1200 baud, or 48tpi Poly-Dos disk). and
- 2) a stamped addressed label (or envelope) for the return of your media if so required.

So put your fingers to the keyboard and send the results to 80-BUS News.

VIDEO OUTPUT STAGES

I was recently doing some work with a video output stage, and, having a reasonable 'scope to hand as a result, I decided to look at the ouput stage of Gemini IVC. There were two points I wanted to deal with, a) the low level of output (< standard 1V p-p), and b) 'The marching sands of time'. (Background interference patterns that are noticeable when using large areas of inverse video).

The IVC output stage is shown in Fig 1. It consists of an emitter follower driven by the video signal from IC3a (via R5), and the mixed syncs from IC5f (via R1). The ideal output waveform is shown in Fig 2. This consists of a three level signal whose peak-to-peak amplitude is 1V (when driving into a 75 ohm load). The three levels of the signal are white, black, and sync, and their relative amplitudes are also given in Fig 2. Assuming a perfect emitter follower with an output impedance of 75 ohms, we want to aim for a 2v p-p signal at the base of the transistor. I started by selecting arbitrary voltage levels of White=3V, Black=1.6V, Sync=1V. Let us now consider how the three signals are generated: For the 'White' level the output of IC3a is high, (dot on), and the output of IC5f is high (no sync signal).




Fig 1

For the 'Black' level we have the output of IC3a low (dot off), and the output of IC5f is high (no sync signal). Finally for the 'Sync' level the outputs of both IC3a and IC5f are low. Armed with this information it is only a case of applying Ohm's Law and Kirchoff's Law to the circuit...or is it? One problem is that the high level output voltage from a TTL gate is not very well

defined, and it also has an appreciable output impedance. With the ICs fitted to my card the high level seemed to be around 3V, so, as I just happened to have picked 3V for my white level, I could conveniently ignore R1 and R5 and calculate a suitable value for R3. This then left me with two unknowns, and two equations (for the Black level and the Sync level). The result of the




Fig 2

calculations (followed by a small adjustment after an actual trial) is shown in Fig 2. (Compare the values against those of the IVC circuit diagram). These values resulted in a reasonable video signal driving out from the card.

One other small change I would recommend, especially if you use inverse video or occasionally have large white areas on your screen, is to short out C7. This should not have any harmful effect, as all monitors I have encountered have their own DC blocking capacitor. (They normally have a 75 ohm terminating resistor, the top-end of which is coupled via a small capacitor, - 10μF, into a high impedance input stage. I note also that the BBC Micro has no

output coupling capacitor). If you do short out C7, and your monitor does provide a 75 ohm termination, then you may also improve matters by raising the value of the emitter resistor (R6) to 1k or more.

(N.B. Nascom 2 owners who use a monitor rather than a TV and the on-board modulator may like to make similar modifications. I assume the current drive levels on the N2 are set up for the modulator, rather than the direct video output).

Moving on to 'The sands of time', this interference is obviously being caused by crosstalk from the logic on the IVC. (The patterns change depending on what job the Host is asking the IVC to perform). I started by decoupling the collector of TR1, the top end of the Base bias chain (R3), and adding diodes in series with R1 and R5 (the 'bar' towards the output of each gate). The thinking behind the latter is that it isolates the 'Hi' output level from the video drive, each gate now looking like an open collector driver. As a result R5 was changed to 470 ohms, and R1 to 220 ohms to get back to the correct video and sync levels. This didn't produce any significant change to the visible interference.

So finally I resorted to butchery. I cut the thick power track running to the collector of TR1, and the corresponding track running to the top end of R3. I connected these two isolated points together, and decoupled them with a 47uF tantalum capacitor. I finally added a 68 ohm resistor between this point and the positive supply. (A few turns of wire on a ferrite toroid would have been better, but I had no toroid to hand). This certainly reduced the background noise, although a little was still visible if you looked for it. At this point I stopped. The next step to try, (if you are seeking perfection), is to build a new output stage on a separate board, taking care over the layout and positioning of the board. As for me - I'm sticking with what I've got!

Mixed 5.25" and 8" drives on GM829

I suggest you read Richard Beal's article elsewhere in this issue as an introduction to the rest of this section.




Fig 3.

In the case of the 5.25" drives the lack of a ready line, though inconvenient from a software point of view, is not a total disaster. This is because the motor-on monostable will eventually time out and produce a 'not ready' signal. This immediately causes any 'hung-up' access to a 5.25" drive to abort. However, when 8" drives are selected, all the circuitry associated with the motor-on monostable is disabled because virtually all 8" drives use mains powered motors which run continually. As a result there is no abort signal unless the 8" ready line is connected through. The answer is to insert link 3 - to connect the ready signal through - and to 'fake' ready signals from those drives that do not provide them directly.

The suggestion made to Richard was to try adding diodes to do this, but the same effect can be achieved by using an open-collector AND gate (e.g. 74LS09), or even an open-collector buffer (e.g. 7417). The input(s) to the gate(s) are connected to the drive select lines that do not provide a ready line, and the output(s) are connected to the Ready line (see fig 3). So, as soon as a drive select line connected to one of these added gates goes low, the Ready line is also pulled low. N.B. The gate used must be an open-collector gate, otherwise it will interfere with the 8" drive when it attempts to drive the ready line. In the approach suggested to Richard the diodes provide the required isolation, but as they are passive devices there may be problems with voltage drops across various components (as he discovered). The 74LS09 approach avoids this.

How to find your feet on a Nascom 2

A letter from Mr Mathison of West Germany has brought the N2 out again. He's been chasing the feet of the little men in the N2 character generator, but, despite following the suggestions published recently, has had no success. I'll start by describing the action of the N2 video circuitry before running through the solutions. That way any of you who attempt the modifications should have some idea of what you're up to. You will need a copy of the N2 circuit diagram if you want to follow the description below.

How it works

A 1MHz character clock emerges from IC49/13 (IC43 pin 13). This is divided down in the six-bit counter formed by IC51/IC52. The outputs of the six-bit counter form the address of a character within a display line, and address the video RAM via multiplexors IC62/IC63. The address is also decoded by IC55/IC60 to provide the blanking signal that frames the active 48 characters of the display, out of the total of the 64 characters that make up a line. (Remember that the Nascom video RAM has 16 unused characters between the end of one display line and the start of the next one). The output of IC52/13 triggers the monostable IC57 to provide the horizontal sync pulse, and also clocks the four-bit counter IC53, whose outputs form the 'row address' to the character generator. The character generator ROM address lines are also decoded by IC44c which, when the 625 line option is selected, resets the row address counter to zero everytime row 14 is reached. Thus only rows 0-13 of the character generator are displayed. Every time IC53/11 returns to 0, the five-bit counter formed by IC68/IC13b is clocked. The outputs of IC68 address the video ram via multiplexor IC64 and form the 'character line' address. Finally the IC68/IC13b counter is decoded in the N2V PROM (IC59). There are two outputs from this PROM, D1 provides the vertical blanking signal, and the DO output is used to trigger the vertical sync signal (from IC57) and preset the five-bit counter IC68/IC13b to 11. (Check the hardwired inputs on IC68 to confirm this). The contents of the N2V PROM can be found in the Nascom 2 documentation, and from the listing you should be able to deduce the following, starting at the point where IC68/IC13b is reset to 11...

Counter	Action
11-14	Display is blanked.
15-30	Display is unblanked. Display lines go 15,0,1,2,3....13,14.
31	Display is blanked again
0	Display is blanked. (Counter wraps round to 0).
1	Vertical sync triggered & counter immediately reset to 11.

From this we can see that the weird order of the lines in the Nascom display was done with malice aforethought! (I've always assumed it was due to some quirk of the hardware implementation). By rotating the contents of the PROM by one location, and preloading IC68 with 12 instead of 11, the N2 can have a conventional video ram where the screen starts at the first address, and ends at the last address. If required, a non-scrolling top line can be implemented with a zero software overhead in this environment. Why did they do it the way they did? - I suppose an N1 circuit diagram may answer that.

However, returning to the matter in hand, it is a very easy matter to get all 16 lines out of the character generator. All that is necessary is to lift pin 1 of IC53. (If this is all you do, then this pin should be tied to +5v, either direct, or via a 1k resistor). This will prevent the row address counter being cleared on line 14, and it will now cycle round all the 16 lines of the character generator. There are two side-effects to this modification. i) The active display height will increase by 32 TV lines, which may require a picture height adjustment on your monitor or TV. ii) The frame rate will change. There will now be a total of 22x16 TV lines (=352) instead of the previous 308. (The 625 line standard actually requires 312.5). This will give a frame rate of 44Hz. When I made this modification to my N2 it did not disturb the frame hold on my monitor - you may not be so lucky.

NOTE The only effects of this modification will be an increase in screen height and a possible loss of vertical hold. The extra lines of the character generator can only appear in the correct place. Other symptoms may appear if you have disturbed dry joints, or other ICs.

Getting back into Sync

To get back to a 50Hz frame rate some more modifications are necessary. Somehow we need to take out about 40 TV lines from a frame. We can remove an integral number of 16 lines by changing the address initially loaded into IC68 at the start of every frame. However the effect of this is to move the display upwards on the screen. (The screen is unblanked sooner after the vertical sync pulse). It is also a simple matter to remove some lines from the end of the display, all you have to do is program a new N2V PROM(!). Ignoring the latter suggestion as it is impractical for most people, lift IC68/1 and connect it to IC68/8. Lift IC68/10 and connect it to IC68/16. This now arranges for the counter to start at a count of 13, rather than 11, and will thus remove 32 TV lines from the start of the frame.

This leaves us with a further 8 lines to get rid of if we want to hit a 50Hz frame rate. We can do this by including the row address counter IC53 in the 'frame reset' sequence, and preloading it to 8. Unfortunately the 'LS161 has a synchronous load although the clear is asynchronous, and the modification involves more than a simple strap. So, unless you're a perfectionist, I suggest you stop here.

(With the 'LS161 the load occurs synchronously with the clock. i.e. The load input has to be taken low, and held low until the clock input makes a low-to-high transition, at which point the data on the parallel inputs will be loaded into the counter. The clear input is asynchronous, which means that as soon as the clear input is taken low the counter is cleared immediately irrespective of the state of the input clock.)

Final tweak

For those who wish to persevere we are effectively going to invert the high order bit of the row address counter (IC53/11). This way we can use the asynchronous clear input as a 'set-to-eight' input rather than a 'set-to-zero'. Lift IC56/5 IC56/6 IC68/5 IC53/11. Connect IC53/11 to IC68/5. The row address counter now directly drives the line counter IC68 instead of being routed via the inverter IC56c. Connect IC53/11 to IC56/5, and IC56/6 to IC54/5 (or IC44/11 or IC66/5). This means that we have the inverse of the msb of IC53 driving RS3. Finally connect IC53/1, (after disconnecting it from +5V if you added that earlier), to the load line from the PROM. (IC59/1 or IC68/11 or IC13/13 or IC57/10). This connects the load signal to the clear of IC53. As the RS3 line is now inverted in IC56c, clearing IC53 is equivalent to setting RSO-RS3 to 8, thus removing a further 8 TV lines from the frame.

Try little steps

If you totally loose the top line(s) of your display, trying taking things a step at a time until you reach a point where you can lock your TV/Monitor. First try presetting IC68 to 11, then 12, then....

TRAILER

That's almost all for this issue, but just one final comment to confuse those of you who have read Richard Beal's article. I have a Shugart SA800 8" drive connected to my GM829, and currently it spends most of its time powered down. In this state it does not interfere in any way with my use of the 5.25" drives, so you may be lucky like me, or unlucky like RB, in which case I suggest you switch off and unplug before doing any rewiring!

Addendum to the Belectra HSA-88B Review

The above review just made it into the last issue by the narrowist of margins, and thus one correction and some updated information couldn't be included. First a minor point, the board size is 8"x4", not 8"x3" as stated. Secondly, as the review board and documentation reached me at different times and from different sources one document was left out. This was a seven-page addendum to the Hisoft Pascal manual, detailing the differences between versions 4 and 5. (Anyone who has bought the card will have received a copy).

As well as various enhancements to the compiler it points out that all integers in HP5 are 32-bit integers, giving a MAXINT of 2147483647! For the REAL precision and format it refers you to the AMD9511 documentation (see the review). The information on where to patch the run-time routines in order to use the HSA-88B at an alternative address is also given.

For a user's view of the HSA-88B see Dr Dark's column.

BASIC FUN & GAMES			
ON CASSETTE FOR THE OLD 1-2-3 AT A KNOCKOUT PRICE OF £1.75	Caterpillar Munch Avoid the growing tail. A fast favourite with chunky graphics.	War Web An original grid game with a novel scoring system.	All games will run in 8K and make excellent use of graphics. Nascom 1's will require NASSYS 1/3, ROM BASIC (or tape version) and NASGRA ROM (V3). Supplied on C64 or M1 cassette at the ridiculously low price of only £1.75 each including post and packing! (+40p outside UK - excl. duty & tax)
Handlee An original and humorous guessing game.	Mancala Traditional board game for 2 players or one player against the computer.		
Pay by cheque or through Tans cash Giro 30 729 4609 (ask at your post office for details) GARRY ROWLAND, 24 PARSLOES AVENUE, DAGENHAM RM9 5NX			

EVEN MORE RAMBLINGS**By David Hunt**Animal Antics

So Dr. Dark has had his moggie kipping in his computer; I can top that. In the spring some three or four years ago, I was building my Nascom 2 into a 19" rack, and making a decent job of it too. Proper laced wiring and all that. Well this was very boring for the rest of the family, who were entertained by the squirrels at the bottom of the garden collecting twigs and grass and stuff. Now what no-one bothered to tell me, was that the squirrels were running along the fence towards the house and disappearing in an upwards direction. The little so and so's were building a nice comfy nest in my chimneys. Incidental intelligence bit: squirrel nests are called dreys. Stuffed full of useless facts is this fellah!!

One morning, number two daughter runs in and says, "Daddy, daddy, there's a squirrel eating your computer!". Well at 7 a.m., what am I to think? Jokes I can take, but at that time of day I'm a little slow, and took the news very seriously. Half way down the stairs, the incongruity of the statement started to sink in. 'Squirrels?? Oh well, as I'm half way down stairs I might as well take a look see.' Sure enough, in the living room, sitting on the 19" rack is a small squirrel, grey variety, chomping through the Nascom wiring harness.

Now normally I'm the tolerant sort, squirrels are nice furry things which run around at the bottom of the garden doing me no harm and keeping the cat amused. Live and let live ... etc. But there's this one doing the Egon Ronay bit with my Nascom!!! Putting on my best impression of a Samurai, I entered the room. I'm not sure whether it was my entrance or the fact that I usually sleep in my birthday suit and had forgotten my dressing gown, which caused the strange look squirrel gave me. Anyway, a small grey flurry shot straight up the curtains and disappeared. At that moment it occurred to me that if squirrels like various thicknesses of pvc covered wire for breakfast, I was sadly unprotected against the teeth which could gnash their way through wires. I beat a hasty retreat and got dressed whilst considering the problem.

At last, armed with a small blanket borrowed from a dolls pram, I was ready to do battle. It wasn't easy, they move fast do squirrels, but in the end I caught it. If you've never caught a squirrel, I'll warn you. They can make the most unearthly screaming sound you've ever heard when caught, loud enough to make you drop it. But this lad is made of sterner stuff, wrapping the blanket firmly round the thing I dumped my squirming bundle at the bottom of the garden to be reclaimed by its parents. That, fortunately, is the last time any computer of mine has been attacked by anything other than me.

The missing DH bits.

Ardent fans of the DH series on databases (there is at least one fan, me) will notice the absence of an episode in this issue. Well this is not because I haven't written it, but that all the bits I was going to cover have been very nicely written for me by Clive Bowden in the last issue. His bit about random access methods using MBASIC just about sums up all I had to say on the matter, and so I must offer my thanks. However, I did find it annoying, from the point of view that I had already written half that bit for this issue and I didn't know that someone else had already done it. Never mind, I'll see to it that the boreing DH series starts again next issue and goes on and on and on ... [Ed. - ... and on ...]

The Spectre of Impending Doom

There are a lot of cowboys in the home computer business (if you hadn't already noticed) and these are about to get their 'come uppance'. Gazing into my crystal ball the other day, I noticed that over the months there has been a distinct downturn in the sales of the 'Mickey Mouse' computers (you don't expect me to name them do you?). Now a lot of this is due to the faddish buying profiles of the Great British public.

A few years back metal detectors were the thing, and a little later, a vast boom in dedicated TV games. Where are they now? I no longer know where to get a metal detector even if I wanted one, although in 1977 I could have had a choice of several in the local branch of one of the chain chemists. Last Christmas every kid, but every kid, expected a home computer in their Christmas stockings, and dad justified the expense by saying that he might as well get some use out of it and catch up on the 'New Technology' at the same time. How many of these computers are now kept at the back of a dark cupboard and are no longer in use because the users got bored with the games you could get, or 'Could never quite get the knack of this programming lark'.

No, it's my guess that this Christmas will ring the death knell for a number of familiar names; the Christmas spurt through newsagents, chemists, etc, will be the death throws of the home computer market. So where are the cowboys going to catch a cold? Well reliable information has it that there are thousands of Hong Kong and Taiwanese computers on the seas at this very moment, and the cowboys and GRQM's (Get Rich Quick Merchants, a mnemonic, courtesy of John Marshall) who have ordered them are going to be left with lots of machines and no market to sell them in. This means that those machines are going to be dumped at silly prices with no follow up support. This is bad news for those SERIOUSLY involved in the home computer business, as the word is going to spread that home computers are not worth touching as the: 'So called dealers can't support the machines, can't supply software, and are generally useless'. Whilst this may be true of many, the good machines and the good dealers (the minority in both instances) will get rolled in with the bad and that will do no one any good.

Which leads to an interesting development. Several of the manufacturers catering to the home computer market have been looking into the future and have seen the gloom approaching. So they think they will have a go at the economy end of the business machine market just to keep in business. Dragon have just introduced the Dragon 64 with a disk operating system called OS9, something I'm told is UNIX like. How far they expect to get with that with only three pieces of application software and a 57 x 24 screen I do not know. Lynx, because their machine is Z80 based have opted for CP/M. I've seen a sample with the most atrocious screen handling that can be imagined. Both manufacturers hope to sell systems at under a £1000. Best of luck in view of what follows.

The clouds are gathering over the business computer market. The big shake out is coming. Big names are going broke weekly and those who hoped to climb onto the bandwagon are having serious second thoughts. The 'el cheapo' business machines are in trouble, they seem to have saturated their own market, and it doesn't seem to make much difference how much free software you give away with the machine. IBM are now wagging the 'business machine' dog very firmly by the tail, so if you hope to sell a new business machine, it had better look like an IBM PC. All this despite the fact that large numbers of

IBMs and IBM 'look alikes' are being fitted with Z80 soft cards to enable the new 'all laughing dancing' 16 bit machines to run good old fashioned 8 bit software.

The same thing is happening with the computer industry magazines. Did you know that a recent advertising bureau audit showed over 160 computer magazines available to both the trade and the consumer. These same magazines are now scrambling all over each other for a shrinking advertising market and making 'four pages for the price of two' and similar type offers just to keep going.

Oh no, the computer market is in for one hell of a shake up, and I don't really need a crystal ball to predict the outcome, the pointers that I could see have been there since last March, and the mightier of the gloom pundits have probably seen this coming for far longer than I.

So what does this mean to the typical readership is this mag. Well the readership here is very mixed, still a large number of home users, a fair amount of lab and development types, and a lesser number of business users. Now we (I include myself) have never considered our machines as 'Mickey Mouse' machines, although my first Nascom 1 was definitely 'Mickey Mouse' compared with a Sinclair Spectrum (shudder). Most have graduated to more powerful systems which, whilst not all 'Bells and Whistles' as some of the offerings around, are used for the serious business of software development, hardware development, self education, or for running our businesses. Certainly not for entertainment, except of the most masochistic sort.

Fortunately, the few dealers who cater for our needs are not the 'cowboy' type. Nor, for that matter, are computers these companies only source of income. Some are general components suppliers, some are 'heavy' software suppliers. Either way, these companies seem well equipped to survive the forthcoming storm. Likewise, the machines which we use neither fall into the home computer category, nor the outright business machine end. The manufacturers supplying our needs look likely to survive because of the very diversity of the facilities offered by the machines we use. The sales profiles may change, more going to development and lab type people, less perhaps to the home user and, maybe, the business user, but companies we deal with will survive.

So amongst all this gloom, despondency, and more and more expensive and glossy advertising. Certain things are likely to remain, streamlined a little perhaps, a little more pricey perhaps, but I reckon our machines will remain around and supported this time next year. They'd better, 'I feel it in my bones, and my bones are never wrong', as Izzy Cohen said to the ships' captain, but then if you've never heard that story you'll never know how Izzy made his money.

Modems

I was intrigued by Dr. Dark's reason for buying a Sinclair Spectrum, to use it as modem for Micronet on the grounds that Marvin was too much of a heap of bits to gain the approval of British Telecom. Now this BT approval thing is something of an interesting problem, not that I claim to be an authority on the subject, but some of the bits I've read are nonsense and some of the things I've read make very sound sense.

Let's have a look at some of the things BT want, as I understand it. I'll only deal with a couple of the sensible things, I'm not sure about some of the things I've read, they seem daft, and I'm not sure whether they are serious or just 'hearsay'.

Firstly, they don't allow anything to be connected directly across the telephone line unless it's been approved. Now this is sound sense. Despite all the precautions a home constructor could take, a few are careless. I know, I've seen power supplies with no earths, I've seen power supplies with the neutral connected to the system ground (I admit I haven't seen one with the live connected to system ground yet). Now BT aren't interested in the ways in which you set out to kill yourself, but despite your personal opinions of BT engineers, imagine what would happen to an unsuspecting guy checking the wiring down at the exchange when he finds a very live wire. Live, not because of the red hot conversation taking place, but live because it's connected to the mains at your end. That's why any gear approved for direct connection is equipped with an isolating transformer.

Now a second thing that seems a bit odd at first sight is that you're not allowed to indirectly connect anything to the phone unless it's been approved. Indirect connection means amongst other things, acoustically. Now I was under the impression that acoustic couplers (home brew or otherwise) were Ok. Not so. The answer is signal levels. In this case BT are worried about excessive signals causing crosstalk between cables and so annoying other subscribers. (They're probably also a bit leary about excessive levels upsetting some of their tone controlled switching networks, but they don't say that.) Anyway that's my guess at the reason they don't like the relatively cheap kit modem supplied by a large company in Southend.

So it seems that legally you can't connect anything directly or indirectly to your telephone unless it's been approved; approval costs a bomb and takes a long time, and in the case of a kit modem, they'd want to approve each one individually before it's used.

Now about Micronet, it is a Prestel utility and contains a billboard and lots of useful software. But for Micronet you need access to Prestel. Prestel itself is odd in computer terms in that its data rates are peculiar, being 75 BAUD for transmit and 1200 BAUD for receive. Prestel modems are all directly connected, I don't know of any acoustic modems capable of going at those speeds. Most acoustic modems run bidirectionally at 300 BAUD. However, what is not widely publicised is that Prestel do have a 300 BAUD service on the Kipling computer, although only admittedly in the London area, try 01-248-5747. This service is primarily for business use, where business computers already have the usual 300 BAUD I/O.

So it seems from the guy at Micronet that Dr. Dark's Marvin couldn't be connected to the public telephone network, or could he? Well a new approved acoustic modem could be purchased for about twice the price of a Spectrum and its approved modem; or --- not that I would condone such a thing --- something else could be connected to the telephone network which satisfied the rules. In this instance, if BT actually detected it (indiscriminate phone tapping is still illegal, and a warrant is needed for discriminate phone tapping), it would appear to be an approved device and therefore wouldn't give rise to questions.

When using acoustic (or direct connected) 300 BAUD modems with Prestel, there have to be snags of course, firstly, the 300 BAUD service is restricted to only one computer, with a limited number of ports for its modems. This means that it is often engaged during the day, but evenings are a different story. I've no way of knowing, but I would guess that out of business hours, the 300 BAUD service is the quietest of the lot on the grounds that no-one knows it's there. Another nasty is that BT don't offer preferential rates for that number. If you live outside London, then dialing that number will get charged at trunk call rates, worse, because the data rate is one quarter of the normal Prestel data rate, everything takes four times as long to receive. The last flaw in the scheme is gaining access to Prestel, you require an individual access code which is many characters long. I'm not saying how many characters, just in case someone tries a bit of code cracking and hits my code by sheer good/bad luck; mind you that could be expensive, because if you get the access code wrong a couple of times, Prestel tells you you are an idiot, and disconnects the line. You get your access code when you apply for the Prestel service. They ask you what device you intend to use. You reply, "Personal computer". They ask you what. You say, "BBC", or "Spectrum", or "Oric" or some other approved device depending upon the computer you are using, or if you are using a 300 BAUD modem, you must make sure you get logged onto the Kipling computer, then you say "300 BAUD modem.". Typically the person taking the logging details knows nothing about the 300 BAUD service so you'll have to tell them. After a while, you get your access code, and given suitable software, away you go.

Now to suitable software, I'm writing a bit to make the Climax card look like a Prestel display, 'cos it's got colour and all that. But David Parkinson's dumb terminal routine works well enough to extract textual data and Ward Christensen's MODEM 7 works well for textual data with the advantage that you can store the incoming data and use it for testing Climax colour routines, etc. If you've got a Winchester Technology colour card collecting dust, you're laughing, just plug it in and with the simplest of dumb terminal type software, you're away.

Apart from Prestel with Micronet, which costs, there are a lot of telephone numbers with modems and active computers on the end. There are billboards, companies advertising, all sorts of things, most of which allow access for nothing. A whole bunch were published in PCW a couple of months back and some of these can provide hours of endless fun (providing someone else is paying the phone bill). One person I know tried the Swedish number published, hoping that the Swedes with their liberated views had something interesting to say. Unfortunately the computer replied in Swedish, so he's none the wiser.

HDLC and Packet Radio

On the subject of serial communications, I have recently come across references to a subject called 'Packet Radio' which has raised some interest in the States. On first reading this was pretty meaningless due to the sketchy nature of the odd paragraphs that appeared over here. However, Practical Wireless has seen fit to reprint the whole of one American explanatory article, and with a sigh (Oh no, not another protocol!), I sat down to read it. Now it turns out that 'Packet Radio' is not 'just another protocol', but a radio adaptation of an old enemy, HDLC. Now I say old enemy, as not so long ago one of the 80BUS board manufacturers asked me to look into high speed synchronous serial communications, in other words, making micros talk to

mainframes at speeds that make the mind boggle, like 250K to 1M BAUD. Not a bad thing in itself, but it made my brain ache by having to learn about things like HDLC. Anyway HDLC, which stands for High-level Data Link Communication, although a bit nasty to get to grips with, is rather clever when it clicks. Not only is it efficient, but it can be used at very high speeds.

The real sneaky with HDLC is in the way the data is packaged up (hence the term Packet Radio). Instead of sending serial data in the form we are familiar with, that is, a start bit, a byte of data and a stop bit, each byte being sent and received asynchronously with separate clocks; whole chunks of stuff are sent at once (typically 128 or 256 bytes at a time) with the clock signal as part of the data, in other words synchronously. To make this possible an HDLC packet consists of six fields like this:

-----	FLAG	Address	Control	DATA.....	DATA	CRC	FLAG	-----
-------	------	---------	---------	-----------	------	-----	------	-------

The first flag is a unique signal, usually 0111110, now that's not unique you will think, but we'll come to the way it is unique in a moment. Anyway, the flag says 'Get ready, here comes the packet'.

The next thing to follow is the address, now the address length is not defined by the protocol, except that it must not be less than one byte long. Typically the address is two bytes long, and in that 16 bits, it may contain the coded address of the sending device within a network, and the coded address of the receiver within the same network; it may also contain routing instructions through the network. Overall, the address is the code which allows the packet to reach its correct destination.

The control is again a minimum one byte code, typically two bytes, and contains supervisory information, things like the current packet number, the length of the following packet, an acknowledgement of the correct receipt of the last packet, or a request to resend the last packet, or end of message, or anything else of a control nature defined and understood by the other end.

Next comes the data. This may be as many bytes as has been decided, it could be a standard number, 128 or 256, or it could be a number that has been decided by the control byte. Again the minimum is one byte

The CRC is a two byte Cyclic Redundancy Check (or checksum) which is computed from all the preceding data bits back to the first flag, so it encompasses the address and the control as well as the data. CRC's are lot better than simple checksums, but whatever it is, it forms a check on the validity of the preceding data.

Lastly comes the end of packet flag, again the unique code 0111110. This signals the end of the packet and also that the preceding two bytes were the CRC.

So to the uniqueness of the flags. All data is sent as a continual bit stream, it starts 0111110.....and finishes.....0111110. There are no start bits, no stop bits, nothing to indicate the bytes at all, just a continual bit stream from first to last. So what happens if we send a stream of FF's or 00's, apart from the flags there will be no low-high transitions and no high-

low transitions, just a continual high or low to the end of the data block. This is an invitation to lost sync, particularly if the clock is an integral part of the signal, how can this be overcome? The answer is what is called bit stuffing, which gives rise to a highly efficient data transmission system known as NRZI.

First a look at NRZI, it stands for Non Return to Zero Inverted (it is actually used on our disk systems but no-one shouts about it). It's not a case of high means a 1 and low means a 0. It is a case of change of input state means a change of output data state. Lets assume that the input signal is low, and the output data state is currently 0. The next input signal transition from low to high will cause a change of output state from 0 to 1. No different from what we already know, but if the output data state were already high when the input low to high transition occurred then the data state would change from 1 to 0. It is the input transition edges associated with the transition which causes the output to change from one data state to another. Thats where the Non Return to Zero bit comes in, an input transition to zero does not necessarily mean that the data state returns to 0, it could go to 1. None of this matters so long as the decoder knows what is to happen, and knows its starting states.

It should be obvious that to be a synchronous data transmission system, NRZI must have some sort of synchronising mechanism built in to allow clock recovery. It must know how many bits have passed between one input transition and the next. A continual steam of 1's or 0's is an invite to lost sync. If we sent a stream of 010101010.... then it would be no problem to recover the clock from the data itself, a simple phase lock would do it. Given the proven 'sample and hold' characteristics of phase locks, we could send quite a lot of 0's before we needed to send a 1 to regain the sync, likewise we could send a lot of 1's before we needed to send a 0 to regain sync. This is where the 'bit stuffing' technique comes in. The HDLC logic counts the number of similar bits sent. If five consecutive 1's are sent, then the logic will 'stuff in' an extra 0 in the sixth position to regain the sync. Likewise if five consecutive 0's are sent, then the logic 'stuffs in' an extra 1 in the sixth position. The receiving end knows all about this, and if it sees a transition in the sixth position it knows to throw that bit away. Very simple.

The only time this 'bit stuffing' does not take place is with the flags. So, if there are six consecutive 1's received without the necessary 'stuffed bit', then one of two things has happened. It must be that start or end of a packet. If it's the start, then no preceding data is of consequence, already having been dealt with. If it's the end of a packet then either a data error occurred, in which case the preceding two bytes won't add up to the CRC, making the packet invalid. Or the extra bit did indicate the end of the packet, in which case the CRC does add up and the packet is valid.

Of course with a high speed interface all the HDLC logic must be in hardware, no way can you do the 'bit stuffing', phase lock clock recovery and CRC checking in software when the data rate is approaching the cycle time of the processors involved. Special chips have been developed to handle this and although expensive, they can really shift. Another criteria with very high speed links is the clock recovery itself. Phase shifts in the connecting circuits can cause delays in the arrival of the transitions. These delays can be a substantial part of a 'bit time' when high speeds are considered. This one of the advantages of 'bit stuffing', the clock signal is an integral part

of the data, so that any delays in the data will cause similar delays in the recovered clock signal, hence everything stays in step.

With the 'Packet Radio' concept, the data rate is comparatively slow, 1200 BAUD or thereabouts, so clock recovery could be in software, and all functions could be controlled by software and not expensive beasts like the Zilog Z8530 SCC device. Of course, the data recovery is not the whole story. What about the routing and address information? Well this forms another rather nice feature of 'Packet Radio'. The International Standards Organisation (ISO) have developed a model network structure in a truly generalised form. It's a hierarchical thing with seven layers from the low level primitives which form the sending and receiving part through to the final high level controllers and routing protocols. All clever stuff, and I don't understand half of it - yet!

But whereas, in the last issue, I was thinking of playing with AMTOR, perhaps I'll change my mind and have a go at this instead. With the amateur radio regulations in the state they are, and the very woolly UK definitions regarding data transmission, it should be alright on 2 metres or 70 cms.

Nascom News

Since Lucas took over Nascom, I sometimes wonder what's been happening. In the last two years, Nascom have got the disk system out of the door, rewritten all the manuals, brought out a Nascom 2 in a box, called the Nascom 3, have produced a colour card, made their Nasdos based network work, and bought a lot of software that no-one seems to want. Although this represents a lot of consolidation of the Nascom range, in real terms, it's not a lot. Well Lucas seem to be getting concerned about the lot of nothing which seems to be happening in Warwick. A few heads have rolled and a general shake up seems to be taking place. Work seems to have been happening, and they have a very nice (no, excellent is a better word) piece of software running under CP/M called LOTTI. LOTTI is a CAD package (CAD stands for Computer Aided Design) using the Nascom AVC to full advantage. Coupled to a multicolour chart plotter it is capable of A2 and A3 drawing of considerable complexity. The name Nascom seems to be in the decline however, it's now Lucas Microcomputers, with Nascom being a model name within the range. There's a new range of machines called the LX (looking suspiciously like the Quantum 2000 although with different cards fitted), two printers carrying Lucas badges, and a couple of monitors also carrying Lucas badges. The future of kit Nascoms seems a little doubtful, as the emphasis is now on built, ready to go machines.

Letters and things

A couple more letters have come my way. So let's have a look at them. The first from A. M. Davies of Tewkesbury encloses two programs written for RP/M or CP/M which appear elsewhere in this issue, he also raises a couple of points. Firstly the topic of DISKPEN VG:1 and GEMPEN VG:1. As most readers are aware, these are almost identical products. The confusion arises from DISKPEN VG:3, this is so much of a revision of DISKPEN VG:1 as to be considered as an entirely new product. With version VG:1, distribution was through Gemini, hence the greater number of GEMPEN's around. With DISKPEN VG:3, distribution is through the majority of Gemini dealers, but the product originates from the authors rather than Gemini. Mr. Davies asks, why, having returned the registration form, he was not informed of the enhancements to his DISKPEN/GEMPEN VG:1 (he does not say which). Well this is difficult to answer, if he owns a DISKPEN, then he may have been, as about 50% of DISKPEN owners have been circularized with the remainder to follow in December. If he owns

Title Memory Block Comparison Program		.Z80	
Written source supplied, transcribed DRH 19/11/83.		• Comment "	
This program compares all the bytes in two blocks of memory and types out on the console the HEX values of the addresses in the lower block where the bytes are different from the corresponding bytes in the higher block. The start addresses of the two blocks are defined as block1 and block2, and the top address of block1 to be checked is loaded into <BC>, at block1top. The program runs from OD000H.			
The program was originally used to find a bad byte in an EPROM version of MBASIC-80, which did not run correctly although the tape version of the same did. It took about 500MS to find the one byte in 24K that was incorrect.			
The program is not claimed to optimised in any way whatever."			
B100 E000 0000'	D000 D004 31 E000	<pre> stcksav equ 0e100h newstack equ 0e000h aseg org 0d000h ld (stcksav),sp ; Save the RP/M stack ld sp,newstack ; Set up new stack D007 21 0100 block1: ld hl,100h ; Start addr. of low D00A 11 6100 block2: ld de,6100h ; Start addr. of hi D00D 1A getbyte: ld a,(de) ; Get byte from hi. D00E BE cp (hl) ; Compare with lo. D00F C4 D025 call nz,taddr ; If not equal repeat D012 C4 inc hl ; Increment both pointers D013 13 dec de D014 B5 inc hl D015 B7 push hl ; Save <HL> D016 01 6100 or a ; Clear any carry flag D019 ED 42 bloktop: ld hl,6100h ; Check against top D01B 28 03 sbc hl,bc ; ..for end D01C E1 jr z,exit ; If top then quit D01E 18 ED pop hl ; Restore <HL> and. D020 ED 7B E100 jr getbyte ; ..loop for next block D024 C9 exit: ld sp,(stcksav) ; Get the stack back ret </pre>	

```

F5      taddr: push    ; Save the registers
D026    p      af
D027    p      bc
D028    push   de
D029    p      hl
D02B    CD    e,0ah
D02E    DO5E  e,0ah
D02E    1E OA  e,0ah

; Now put out the current address
B1      push   hl
B1      push   hl
B5      push   hl
B5      push   hl
TC      call   a,h
CD    DO3F  call   a,1
DO33  CD    btyte
DO36  TD    a,1
DO37  CD    btyte
DO3A  B1    hl
D03B  D1    pop   de
D03C  C1    pop   bc
D03D  F1    pop   af
D03E  C9    pop   af
D03F  F5    push   r1ca
D040  07    push   r1ca
D041  07    call   r1ca
D042  07    call   r1ca
D043  07    call   r1ca
D044  CD    DO4C  ther
D047  F1    pop   af
D048  CD    DO4C  ther
D04B  C9    call   ther
D04C  E6    OF    ther:
D04E  CD    DO56  and
D051  5F    call   OFH
D052  CD    DO5E  hexas:
D055  C9    call   hexas
C9      ret    conout
ret    ; Print the nibble

hexas: add   a,'0'
       cp   '9'+1
       ret
       a,7
       add
       ret
       ; Convert to character

D056  06 30  hexas: add   a,'0'
       cp   '9'+1
       ret
       a,7
       add
       ret
       ; Convert to character

D058  FE 3A  hexas: add   a,'0'
       cp   '9'+1
       ret
       a,7
       add
       ret
       ; Convert to character

D05A  D8    hexas: add   a,'0'
       cp   '9'+1
       ret
       a,7
       add
       ret
       ; Convert to character

D05B  06 07  hexas: add   a,'0'
       cp   '9'+1
       ret
       a,7
       add
       ret
       ; Convert to character

D05D  09    hexas: add   a,'0'
       cp   '9'+1
       ret
       a,7
       add
       ret
       ; Convert to character

D05E  F5    conout: push  af
D05F  05    conout: push  bc
D060  D5    conout: push  de
D061  E5    conout: push  hl
D062  0E 02  conout: push  ld
D064  CD 0005  conout: call  c,2
D067  E1    conout: call  0005h
D068  D1    conout: pop   hl
D069  C1    conout: pop   de
D06A  F1    conout: pop   bc
D06B  C9    conout: pop   af
D06B  C9    conout: ret

; ... an LF

; Get <HL> back
; Reserve <HL>-
; Type the hi. order byte
; Type the lo. order byte
; Restore the registers..
; ..and return

; Save <AF>
; Rotate high nibble ...
; ... into low nibble
; Print the nibble
; Get <AF> back
; Print the nibble
; Mask the high nibble
; Print the nibble
; Convert to ASCII
; Check if > 9
; Return if not
; Convert to character

; Save the registers

```

Z80
Title INTEL-HEX dump program
Comment "INTEL-HEX DUMP V1.3, A. M. Davies
Written source supplied, transcribed DRH 19/11/83.
This program dumps out memory contents to the screen and to the serial I/O (if "P" is active) in INTEL-HEX format. The program runs from 8000H and requires two parameters to be entered before running - the start address of the memory area to be dumped must be in locations 8800H and 8801H (LSB first), and the number of 16 byte blocks to be dumped must be in locations 9000H and 9001H (LSB first). For example, 8800H and 8801H might contain 00H and 01H, and 9000H and 9001H might contain 80H and 00H. This gives the starting address as 0100H with a total of 80H blocks, ie, 0128 * 16 = 2048 bytes to be dumped. Note that the start address is updated during the running of the program, but the number of blocks value is not. This facilitates further dumps from the next area of memory without requiring further entry of parameters.

The program was originally written to enable memory contents to be dumped to an EPROM programmer, and could no doubt be improved and made much more user-friendly."

```

        buffer equ 8400h ; 16 byte data buffer
        startadd equ 8800h ; Start address of data to be
                                ; dumped. N.B. This value
                                ; incs as data is dumped.
        rscnt1 equ 8880h ; 16 byte block counter
        recnum equ 9000h ; Number of 16 byte blocks to
                                ; dump. Not incremented by
                                ; dump.

```

```

      3E 00      start: ld    a,0           ; Clear recent1 ...
B0007 32 8880      ld    (recent1),a
B0009 32 8881      ld    (recent1+1),a
B00C 32 9010      ld    (recent2),a
B00F 32 8881      ld    (recent2+1),a
      ; ... and recent2
B012 32 8881      ld    (recent1+1),a

```

INTEL-HEX dump program	W-80	20 Nov 1983	00:43 PAGE 1-1
8015	2A 8800	loadbuff: ld hl,(startadd)	; Get the start pointe
8018	11 8400	ld de,buffer	; Copy data to buffer
801B	ED B0	ldir	; Type out the data
801D	CD 804A	call typerec	; Type out the data
8020	11 0010	ld de,16	; Update the pointer
8023	2A 8880	ld hl,(recnt1)	; in recnt1
8026	19	add hl,de	
8027	22 8880	ld (recnt1),hl	
802A	2A 8880	ld hl,(startadd)	; Update the value
802D	19	add hl,de	
802E	22 8880	ld (startadd),hl	; in startadd
8031	2A 9000	ld hl,(recnum)	; Get no. of blocks to
8034	ED 5B 9010	ld de,(recnt2)	; Get block count value
8038	13	inc de	; bump the count ..
8039	ED 53 9010	ld (recnt2),de	; .. and reseve
803D	B7	or a	; Clear any carry flag
803E	ED 52	sbc hl,de	; Test for end
8040	20 D3	jr nz,loadbuff	; If count < size, do
8042	CD 808E	call typendP1	; .. else end
8045	ED 7B 9200	ld sp,(stacker)	
8049	C9	ret	
804A	CD 8083	typerec: call terlf	; Send a CR LF
804D	1E 3A	ld e,'.'	; Send a block marker
804F	CD 8075	call conout	
8052	16 00	ld d,0	; Clear checksum to zero
8054	06 10	ld b,16	; Set block length in
8056	3E 10	ld a,16	; Set block length in
8058	CD 808E	call tcbtype	; Send the block
805B	2A 8880	ld hl,(recnt1)	; Send <HL> as the add
805E	CD 8085	call tcbaddr	
8061	AF	xor a	; Clear <A>, then send
8062	CD 808E	call tcbtype	; .. as the block type
8065	21 8400	ld hl,buffer	; Get buffer in <HL>
8068	7E	typebyte: ld a,hl	; Get a byte ..
8069	CD 808E	call tcbtype	; .. and send it
806C	23	inc hl	; Point to next
806D	10 F9	djnz typebyte	; Do for times
806F	AF	xor a	; Clear <A>
8070	92	sub d	; Get checksum ..
8071	CD 8096	call tcbtype	; .. and send it
8074	C9	ret	
8075	E5	conout:	; Save the registers
8076	D5	push hl	
8077	C5	push de	
8078	F5	push bc	
8079	0E 02	push af	
		push ld	
		push c1,2	

GEMPEN, then his registration document will have been returned to Gemini, who as far as I know have not circularized the owners of GEMPEN. This is probably because they are more interested in supporting WORDSTAR than later versions of DISKPEN, see the WORDSTAR commercial on vol 2 iss 5 p 24 in the middle of the unsolicited appraisal of DISKPEN. [Ed. - Unsolicited?? Well, I believe you! But the reason that the comment (not commercial) was added was to make sure that anyone reading the article was aware that the 'equal space justification' that the article was printed in is a feature of WordStar, and that PEN output would be visually different. You wouldn't like anyone to be misled, would you?] What the Editor omitted to say was they he has a conversion program that turns PEN text into WORDSTAR text, so that either is equally acceptable.

COMAL-80

Mr Davies also asks about COMAL-80 and the disappearance of the tape based version. The simple answer is that although it existed, it didn't work properly in tape based form. The trouble stems from the way in which it tries to save a file to tape and the simplified workings of RP/M compared with CP/M. I don't remember exactly what was wrong, but it was to do with COMAL checking to see if a file existed and RP/M faking an answer which implied it did, at this point COMAL tried to delete the file and found it couldn't. That doesn't look right, but it was something on those lines, resulting in COMAL getting in a knot. As far as I know no-one has attempted to cure the problem.

Disk Content

Mr. Piper of Sheffield writes complaining of the disk based content of the mag, understanding that we publish what we're sent. He goes on to write that he'd like disks, but lack of pennies prohibits this, "Could someone provide bare pcbs, etc, to allow these facilities to be provided as pocket money allows." The simple answer is yes, a few of the early Henelec/Gemini GM805 single density controllers are still available in both 'pcb plus circuits' form, and in complete kit form at much reduced prices. Disk drives are still a problem, but drives are becoming cheaper and can be bought new for about £170 each by reading the small ads. Secondly, there are few second hand Gemini GM809's knocking around which have been taken as 'trade in's' for the GM829 controller at about £70.00, likewise some dealers have second hand drives, traded in for the same reasons, at prices between £100 and £150 depending upon condition. So it's worth phoneing around. The last pricey thing on the list is an operating system. This I'm afraid is going to hurt the pocket whatever you opt for. One dealer has a few old CP/M 1.4's for the GM805 available, but CP/M 2.2 for most other permutations will cost about £120. Polydos is a viable alternative for the Nascom owner, and cheaper, but will cost about £103. The answer is that you won't get much change out of £300 to put a disk system together, but I'll bet that's a lot cheaper than you thought. The above prices include VAT.

NASPEN Problem

Mr Piper also comes up with a permutation problem with NASPEN. He says he can't do a Read or a Join with Nascom 1 running NAS-SYS 3. Now this is one I haven't heard of. As far as I know, it works, which suggests the EPROMs are corrupt. Get them reprogrammed by Henry's, but check which version, there was a NASPEN VN.1 and a NASPEN VN:1 (subtle difference), the VN:1 version was later. As I said, as far as I know, they should both work as neither Read nor Join was monitor dependant.

MORE HAPPY TALKBy Rory O'Farrell

My note on computer to computer communications in 80-BUS News Vol 2 No 5 has rapidly been outdated. I wrote then of the method of turning the file into HEX. Recently, I found an article in Microsystems (July 83) on the same subject, but much more elegant! Giving credit where it's due, the author is Steven Fisher.

His method of getting the file into HEX is to use a Public Domain utility called UNLOAD. This utility takes a .COM file, and converts it into a file in .HEXformat. He gives the entire object code for this in the form of a HEX listing. This is reprinted below. It can be typed up using a suitable editor, and saved to disc as UNLOAD.HEX. Then you use the command:

A>LOAD UNLOAD

to convert it back to an object file. If you have any mistypings, these will show up as checksum errors, causing LOAD to protest and abort. Correct such errors by retyping or otherwise editing the lines in question, and go through the LOADING process again. When you have UNLOAD on your disc as a COM file, then you can try it out.

It is used by typing:

A>UNLOAD FILE 0100

where FILE must have the extension .COM, which you need not specify, and 0100 is the address at which it is to live. This will create, on the same drive as UNLOAD, a new file called FILE.HEX. So far, so good!

Listing 2 is a short HEX listing of a file called PIP10.HEX. This should be typed up in the same way as UNLOAD.HEX. Do not try to LOAD this. It contains the patch for PIP for communications.

With ZSID or DDT, patch as follows:

```
ZSID PIP.COM
*** *** ;ZSID answers with a size
$1PIP10.HEX ;Insert the name of the file to be used
$RO ;Read it, Zero offset
$GO ;Exit
SAVE 30 PIP.COM
```

A copy of PIP with this modification will need to be on both receiving and transmitting machines. The easiest way is to PIP the HEX files from one to the other, as the HEX files are ASCII, and short enough not to cause any problems with data loss through disc accesses.

To use this method of transfer, set up the PUN: to be a PTP: and the RDR: to be a PTR: on both machines. UNLOAD the file you require to transmit, then on the receiving machine type:

PIP FILENAME.HEX=INP:

and on the transmitter:

PIP PUN:=FILENAME.HEX,EOF:

During the course of the transfer, the computers will each respect the other's need for disc accesses, and the cursor will be restored when the file is finally completely transmitted. Then you need only LOAD it on the receiving machine, and voila!

If you get nulls in front of the .HEX file on the receiving machine, use [H] as a final parameter on the receiver command line. LOAD and UNLOAD only work on the same DRIVE as the .COM or .HEX, so this sets an effective limit to the size of the file you can handle - roughly 25% of your drive capacity, as the .HEX file is 2.81 times the size of the original .COM file. UNLOAD only works on .COM files, so if your file is of another type, then REN it to a .COM type, remembering to change from a .COM type at the receiver.

What happens during transmission is that the transmitter sends a character, then waits for the receiver to transmit the character back again. The receiver gets a character and retransmits it immediately. If either machine is busy, then the acknowledgement does not occur, but the unread transmitted character is held in the UART buffer until read.

I hope that this very simple method of transmission is as much use to readers as it has already been to me - 400k transmitted, with no errors!

LISTING 1 ---- UNLOAD.HEX

```
:100100002A06002BF9C311017E1223130DC2080128
:10011000C9215C00111F010E09CD0801C346010071
:1001200000000000000000000434F4D0000000000FO
:10013000000000000000000000000000000000000000BF
:10014000ED0300040000C3B6012A4201EB2A44017A
:100150007D937C9ADA9F01210000224401EB2A4220
:10016000017B957A9CD291012A400119EB0E1ACDAO
:100170000500111F010E14CD0500B7C28B011180BF
:10018000002A440119224401C35D012A440122428C
:10019000011180000E1ACD0500210000224401EB60
:1001A0002A400119EB2A42017DB43E1AC81A2A449A
:1001B0000123224401C9AF322B01323F0121000447
:1001C0002242012244010EOF111F01CD05003CC245
:1001D000ED010E0911DD01CD0500C300000DOA4E31
:1001E0004F204946494C452046494C4524215C0056
:1001F00011FB010E09CD0801C3220200000000001E
:100200000000000048455800000000000000000009
:1002100000000000000000000000000000ED070004E6
:1002200000000C3A502F52A1E02EB2A20027D937C62
:100230009ADA9502210000222002EB2A1E027B9509
:100240007A9CD287022A1C0219EB0E1ACD050011E6
:10025000FB010E15CD0500B7C268021180002A20EF
:100260000219222002C33A020E09117402CD0500C0
:10027000F1C300000DOA4449534B2046554C4C3AFB
:10028000204F46494C45241180000E1ACD0500210F
:100290000000222002EB2A1C0219EBF1122A200294
:1002A00023222002C9AF320702321B02210004229E
:1002B0001E022100002220020E1311FB01CD0500B9
:1002C0000E1611FB01CD05003CC2ED020E0911D73F
:1002D00002CD0500C300000DOA4E4F2044495220B4
:1002E00053504143453A204F46494C452421000193
:1002F0000600116D001A13D630DA1403FE0ADA0B69
:1003000003D607DA1403FE10D214032929294F32
:1003100009C3F50222EA03CD4901CA8A03F53E3A30
:10032000CD2502AF32EC033E10CD4E033AEBO3CDA8
```

```

:100330004E033AEAO3CD4E03AFCD4E03F10610C58E
:10034000CD4E03C105CA7003CD4901C33F034F3AE7
:10035000EC039132EC03790FOFOFOFC5F0379E6B9
:10036000FC630FE3ADA6A03C607C5CD2502C1C9F9
:100370003AEC03CD4E033EOCD25023EOACD2502BB
:100380002AEA0311100019C314033E3ACD250206D0
:1003900005AFC5CD4E03C105C291033EOCD25026B
:1003A0003EOACD25022A20027DE67FC2B103221E2D
:1003B000023E1AF5CD2502F1C2A5030E1011FB0174
:1003C000CD05003CC2E7030E0911D203CD0500C3E1
:1003D000E7030DOA43414E4E4F5420434C4F5345C3
:1003E000204F46494C4524C3000000000000000000000000097
:1003F000000000000000000000000000000000000000000000000FD
:0000000000


```

LISTING 2 ---- PIPIO.HEX


```

:10010300C30A01C31901000E03CD05003209015FC3
:100113000E04CD0500C9590E04CD05000E03CD050F
:0201230000C911
:0000000000

```



CIRCUIT No. 1



CIRCUIT No. 2.

THREE SIMPLE NASCOM 2 MODS.By K. HamlynTape Motor switching

For some while there has been a lack of urgency in the switching on and off of the tape recorder under firmware control. Having tried various commercial and homemade interfaces, it was realised that under the R and W command (also CLOAD and CSAVE), LED2 was illuminated (quick, this fellow - eh?). A stirring of the grey matter brought to mind the opto-isolator, which after all requires no more driving than a normal LED. See circuit 1. The internal transistor is effectively switched on by the illumination of the internal LED. It was decided that transistor output was not on as large currents occur in the motor drive, particularly at switch on and off; proven by the number of fatalities of BFY51's having meant bulk purchases in the past. Thus the final motor control was chosen to be electromechanical, under the drive of the BFY51. The whole exercise is heavily over engineered, but this is to ensure a long and healthy life.

PSU Droop

One of the problems of the Nascom 3A power supply, or at least mine, is that the no load output of the +5 volt rail is a nominal +5 volts, but under load drops to +4.8 volts. The first steps in attempting to raise the output voltage, and also providing a 5 amp output, was to replace the LM323 (IC1 on the PSU circuit diagram) with a 78H05 5 volt 5 amp regulator. This was attached to a very large heat sink remote from the board, and connected with very thick cables. To further improve the current handling capacity of the supply, the 9 volt winding on the mains transformer was dispensed with and a new 12 volt 50 VA transformer used for the 5 volt rail instead. The current capacity was now there, but the supply resolutely remained at 4.8 volts.

A resistor, in this case 56R was introduced into the earth lead of the regulator, and had the desired affect of raising the voltage to + 5 volts under load. See circuit 2. (Note: that inserting a resistor this way is quite legit, but as the case of the regulator is the earthy connection it means that the regulator must be isolated from the heat sink, or the heat sink must be isolated from system ground (0 volts). -DRH.) A word of caution though. The exact effect on the voltage of inserting a resistor is difficult to predict, even if you are good at sums, as the final value is device dependant. It is best to disconnect the computer and replace it with a dummy load whilst selecting the appropriate resistor, as life can become expensive if the voltage is allowed to rise above 5.25 volts (7 volts is absolute max. according to the book, but I agree with the precaution. -DRH). Certainly there has been an improvement in the video quality, probably caused by the rumoured increase in speed of TTL at the correct operating voltage (not of course the computer itself, as this is crystal controlled). I thoroughly recommend the use of silicon based heat sink compound between the heatsink and the regulator.

Backplane mod.

Finally, there appears to be some mileage in 'flow-soldering' the power tracks of the Vero backplane. Not a new trick, but it does make the whole thing more solid. Mind you it does take some time to avoid inadvertently bridging tracks.

No claims for originality are made for these modifications, particularly the last two, but they might help someone out of a hole!!

RANDOM RUMOURS (& TRUTHS?)**By S. Monger****This is where they are.**

In my last bit, in Vol. 2 Iss. 3, I asked the whereabouts of several products that had been announced, but at that time had not actually materialised. We are now six months further on, and so what is the current position? Well, the Sinclair Microdrive has appeared and is NOT a disk, but a continuous loop tape - consequently the person that I'd mentioned who intended to try to interface one to his 80-BUS machine has long since abandoned the idea. I believe that Lucas now have Winchesters available, and understand that if you open them up (the units, not the Winchesters !) and look inside you'll find a Gemini GM829 FDC/SASI board! The Gemini GM818 serial board has now materialised, but beware! The GM818 is now a daughter board for the GM816 I/O board, and contains two 8250 type UARTs - the originally announced synchronous board has been redesignated the GM848 and is still some weeks away from availability. IO Research's Pallette is now available, for those that can afford it, and for those that can't the Mini Pallette is a meagre £300ish 'cheap' lower spec alternative. Still no sign of IO-Net.

Other New Products.

One item that was sneaked out without my prior knowledge was the Belectra Arithmetic Co-Processor board, but this was covered in some depth in the last issue by David Parkinson. Another co-processor board has also been announced, but no delivery date has yet been given. The Gemini GM886 will contain an iAPX186 (otherwise known as 80186 - i.e. a super GT 8088/8086) and a 'large' amount of RAM (256K?) as well as a socket for the 8087 (ultra high speed, ultra high price number cruncher). As already mentioned, the board will be added to an 80-BUS system as a co-processor board. i.e. the existing Z80 system will continue to handle all keyboard, screen, printer and disk requirements, whilst the 186 will be capable of running CP/M86, Concurrent CP/M and MS-DOS (Gemini are vague as to which they will be making available).

Much more imminently available is the Gemini GM832 SVC (Super Video Controller) board. This is a considerably enhanced GM812 IVC. For a start the 4MHz Z80A has been replaced with a 6MHz Z80B, and consequently, along with the effects of a number of other hardware and software changes, the board is much faster. The programmable character set has been extended to all 256 displayable characters and so the board becomes much more suitable for supporting foreign languages (as well as being more flexible for 'Space Invader' type applications!). Character attributes are also available - half-intensity, blinking and inverse characters, and half-tone backgrounds, plus combinations of these (although different attributes cannot be used on different character cells at the same time). A buzzer is also fitted. But to many the most interesting addition will be the graphics mode, providing a 256x256 bit-mapped display, with graphics primitives of line and circle drawing, polygon fill etc being included in the on-board monitor program. It is here that the Z80B comes into its own, and the plotting speed is very impressive. Estimated price is £195 (+VAT), with availability from 2Q84.

And Finally.

Mention has been made in the last couple of these rags of alleged infringement of copyright of Gemini's CP/M BIOS. Partially because of this, and partially because of Gemini's policy of constantly adding further facilities to their BIOS anyway, I understand that BIOS Version 3.0 is almost upon us, and that this will provide some 'interesting' facilities. More importantly (for existing customers), it will be made available as an upgrade at a 'very reasonable' price. Watch this page for further details.

GENER-80 Z80 ASSEMBLER

Gener-80 is a new assembler which is not only incredibly fast but also memory efficient. This is because its editor does as much processing as possible on source lines as they are entered. The processing includes syntax and label-definition checking, and the creation of semi-assembled code which takes up less memory. All this means a great deal less for the assembler to do, hence it's much faster (approximately 500 lines per second at 4MHz!).

Gener-80 is easy to use, too. For example, its full-screen editor with 16 control commands makes light work of creating and editing a source file. Error messages (not numbers!) are given on a separate status line, and there's even a keyboard inhibit to prevent accidental loss of bad lines.

Other features include named tape files (with automatic merge for easy use of your subroutine library), paged and titled listings, and comprehensive checksum protection.

Only £9.95 inclusive

Runs on all standard tape-based Nascoms (Nascom 1 requires Nas-Sys and Cottis-Blandford interface). Mail order only. Dealer enquiries invited.

SEVEN STARS PUBLISHING

Dept B, 15 Gloucester Avenue, London NW1 7AU

THIS SPACE FOR

ONLY

£35

WRITE TO

80-BUS NEWS

FOR DETAILS.

SKYTRONICS EPROM PROGRAMMER

Programs most types of Eprom from most types of computer

The SKYTRONICS EPROM PROGRAMMER can easily be attached to almost any microcomputer.

EPROMS catered for include:

2708, 2716, 3 Rail

2508, 2758, 2516, 2716, 2532, 2732, Single Rail.

****	Uses two 8 Bit Parallel ports	****
****	Zero insertion force socket	****
****	Built & Tested or Kit	****

The unit is controlled from two 8 bit parallel ports, and can therefore be driven from most I/O devices. (e.g. Z80 PIO or 6521 PIA).

A transformer is included to supply a stable +25V programming voltage.

Complete listing of BASIC program is supplied, plus detailed description of how to use the programmer, enabling it to be used on any micro.

****	Built & Tested.....£59.95+VAT	****
****	Kit form.....£49.95+VAT	****

Tapes also supplied for Nascom, Gemini Multiboard. Disks also supplied for Nascom, Gemini CP/M*

Further details from: Skytronics Ltd. (0602) 781742
 "Computerama"
 357 Derby Road
 Nottingham NG7 2DZ

*TM of Digital Research

Mike York Ph.D

Microcomputer Services

9 Rosehill Road
 London SW18 2NY
 Tel: 01-874 6244



UCSD p-SYSTEM

This extremely versatile operating system with its code-level portability to almost any other computer is now available for 80-Bus/NasBus computers and includes a variable format BIOS for free! The latest version supports the GM833 RAMdisc card which, utilising the automatic overlay and random record addressing facilities of UCSD, enables your Z80 to behave as if addressing megabytes! The only limit to your programs now is your disc capacity. Try and get this under CP/M.....

Program development system: (Includes screen editor, filer, linker, macro assembler and one compiler & variable format BIOS).....£375
 Extra Compiler (Pascal,BASIC,FORTRAN).....£150

Native Code Generator.....£ 75
 TurtleGraphics (adaptable system).....£ 75

CP/M to UCSD utility.....£ 25

Applications packages (can operate without the program development system) are available for accounting, word-processing (and type-setting), relational database, etc., as well as "vertical markets".....POA

DON'T BE LEFT BEHIND BY 32 BITS

CMOS RAM BOARD RB32KC**RB32KC C.M.O.S. BATTERY BACKED RAM BOARD**

POWER FAILURE? Memory contents are preserved during power failure by a Ni-cad battery that is automatically recharged when the board is powered up. Contents are secure for up to 40 days.

PAGE MODE SCHEME SUPPORTED. The board may be configured as one 32K page or two 16K pages.

FLEXIBLE ADDRESS DECODING. Any 4K memory block may be located on any 4K boundary in the processor address space.

NO SOLDERING. All options are selected by wire links pushed into gold plated connectors.

EPRON OPTION. On this board, RAM and EPROMs may be mixed.

EPROM PROGRAMMER/ERASERS ARE NO LONGER REQUIRED because by loading a RAM block and then using the hardware write protect link, the block becomes equivalent to EPROM.

FEATURES HARDWARE AND/OR SOFTWARE READ/WRITE PROTECTION. FULLY 80-BUS AND NASBUS COMPATIBLE.

BACKPLANE BP14C**BP14C 14 SLOT 80-BUS & NASBUS TERMINATED BACKPLANE**

(Bare Board Weight 15oz!)

- * Ground plane on one side of double sided 2.4mm thick printed circuit board.
- * All active BUS signals interlaced with ground 'shield' tracks.
- * All active BUS signals terminated into a potential balanced R.C. filter.
- * Proper implementation of both the interrupt and BUS request daisy chains.
- * Large tracks for power lines.
- * Size 15" x 8". Fits neatly into 19" rack.
- * Easily cut for smaller systems.

Supplied built and tested without connectors.

PRICES	RB32KC 32K Bytes - £225.00	BP14C - £57.00
	16K Bytes - £193.00	Memory
	2K Bytes - £165.00	HM6116LP-3 - £5.00
	Plus £1.50 per board post and packing, plus VAT.	

SPECIAL OFFER. While stocks last

£30.00 off any RB32KC board ordered with this advertisement.
Applies to mail order sales from this address only.
Offer closes July 31st, 1984. Cash sales only.

Cheques/PO's made payable to:-



MICROCODE (CONTROL) LTD.
40 Well Terrace, Clitheroe,
Lancs., U.K. Tel. 0200 27890

SPARTACODE LTD**Your South Coast 80-BUS Dealer****Mr John Stuckey****69 London Road****BOGNOR REGIS****PO21 1DE****0243 826161****TRIED AND TESTED CP/M SOFTWARE SPECIALLY SELECTED FOR YOUR GALAXY COMPUTER**
Phone or write today for latest details and price list**WORD PROCESSING**

		£
Wordstar (3.3)	MicroPro	295
Mailmerge (3.3)	MicroPro	145
Spellstar (3.3)	MicroPro	145
Starindex (3.3)	MicroPro	116
Wordstar Professional	MicroPro	414*

DATABASE & FILE MANAGEMENT

		£
Infostar	MicroPro	295
dBase II	Ashton-Tate	437
Friday!	Ashton-Tate	195
Quickcode	Fox & Geller	200
Personal Pearl	Pearl Software	190

FINANCIAL PLANNING

		£
Calcstar	MicroPro	116
Supercalc	Sorcim	126
Supercalc 2	Sorcim	195

CRITICAL PATH ANALYSIS ETC.

		£
Milestone	Organic Software	233
Datebook	Organic Software	233
Pertmaster	Abtex	650

Add 15% VAT to all prices**LANGUAGES**

		£
BASIC interpreter	Microsoft	259
BASIC compiler	Microsoft	295
ECO-C	Ecosoft	233
Pro Fortran	Prospero	220
CIS Cobol	Microfocus	425
Macro-80	Microsoft	149
Pro Pascal	Prospero	220

GAMES

		£
Deadline	Infocom	40
Enchanter	Infocom	40
Infidel	Infocom	40
Planetfall	Infocom	40
Starcross	Infocom	33
Suspended	Infocom	40
Witness	Infocom	40
Zork I	Infocom	33
Zork II	Infocom	33
Zork III	Infocom	33

Special introductory offer*Access and Visa card holders welcome**

Either enclose a cheque made payable to 'Business Computer Developments' or quote your credit card number. Please state which disk format you require. Products referred to are trademarks or registered trademarks of the companies of origin. CP/M is a registered trademark of Digital Research Inc.

We specialise in many business applications in addition to the popular products listed above. Don't waste a second, phone or write today for further details.

B-C-D

Business Computer Developments
The Saddlery
113 Station Road
Chingford
E4 7BU Phone 01-524 2537