Login and validate work orders

Scan Employee Badge



041517863199 - Ernest Reed

Scan Manufacturing Order



WH/MO/DEMO1

Select Work Center

drill1 - Drill 1

Start Work Order



OBTPAUS

Pause Work Order



OBTPAUS

Mark As Done



OBTCLWO

Select Work Center



assembly1 - Assembly 1

Scan Manufacturing Order



WH/MO/DEMO1

Mark As Done



OBTCLWO

Scan Manufacturing Order



WH/MO/DEMO1

Close Production



OBTCLMO

Consume components and validate production

Scan Work Center

drill1 - Drill 1

Scan Manufacturing Order



WH/MO/DEMO2

Scan Product



601647855646 - Drawer Black - FURN_2100

Scan Lot Number



0000000010001

Scan Product



601647855647 - Drawer Case Black - FURN_5623

Scan Lot Number



0000000020045

Mark As Done



OBTCLWO

Select Work Center



assembly1 - Assembly 1

Scan Manufacturing Order



WH/MO/DEMO2

Mark As Done



OBTCLWO

Scan Manufacturing Order



WH/MO/DEMO2

Close Production



OBTCLMO