Feature Name	Good	Bad	Absolute Difference	Relative Difference
FirstStageombinerOperationTemperature2	86.13	78.83	7.30	0.09
Machine3RawMaterialProperty2	206.94	199.13	7.81	0.04
Machine1MotorRPM	11.12	10.84	0.28	0.03
FirstStageombinerOperationTemperature1	109.34	106.79	2.55	0.02
Machine3MotorRPM	13.23	13.47	0.24	0.02
Machine1MotorAmperage	70.15	71.28	1.13	0.02
Machine3RawMaterialProperty1	9.07	9.21	0.14	0.02
Machine3RawMaterialProperty3	425.73	421.39	4.34	0.01
Machine1RawMaterialFeederParameter	1240.76	1252.84	12.08	0.01
Machine3MaterialPressure	247.13	244.80	2.33	0.01
Machine1ExitZoneTemperature	76.08	75.37	0.71	0.01
Machine2RawMaterialProperty3	565.69	570.30	4.61	0.01
Machine1RawMaterialProperty1	11.87	11.78	0.09	0.01
Machine1RawMaterialProperty2	205.94	204.38	1.56	0.01
Machine3MaterialTemperature	74.23	73.68	0.55	0.01
Machine1MaterialTemperature	81.54	81.13	0.41	0.01
Machine3RawMaterialProperty4	203.20	202.22	0.98	0.00
Machine1MaterialPressure	408.74	410.30	1.56	0.00
Machine2RawMaterialFeederParameter	202.70	202.05	0.65	0.00
Machine1RawMaterialProperty4	248.99	248.28	0.71	0.00
Machine3RawMaterialFeederParameter	202.47	201.94	0.53	0.00
Machine1RawMaterialProperty3	952.04	949.63	2.41	0.00
Machine2RawMaterialProperty1	12.80	12.77	0.03	0.00
Machine2MaterialPressure	226.04	226.54	0.50	0.00
Machine2RawMaterialProperty2	239.99	239.47	0.52	0.00
Machine3MotorAmperage	345.02	345.61	0.59	0.00
Machine2MotorAmperage	73.41	73.32	0.09	0.00
Machine2MaterialTemperature	76.82	76.76	0.06	0.00
Machine1Zone2Temperature	72.01	72.05	0.04	0.00
Machine2RawMaterialProperty4	256.20	256.31	0.11	0.00
Machine2Zone1Temperature	69.00	68.99	0.01	0.00
Machine3Zone2Temperature	78.00	78.01	0.01	0.00
Machine2ExitZoneTemperature	60.00	60.00	0.0	0.0
Machine3Zone1Temperature	78.01	78.01	0.0	0.0
Machine2MotorRPM	13.90	13.90	0.0	0.0
Machine2Zone2Temperature	69.10	69.10	0.0	0.0
Machine3ExitZoneTemperature	65.01	65.01	0.0	0.0
Machine1Zone1Temperature	72.01	72.01	0.0	0.0
FirstStageombinerOperationTemperature3	80.00	80.00	0.0	0.0