Feature	Score
Machine3MaterialTemperature	0.17
FirstStageombinerOperationTemperature2	0.17
Machine3MaterialPressure	0.11
FirstStageombinerOperationTemperature1	0.06
Machine3MotorRPM	0.04
Machine1MaterialTemperature	0.04
Machine1Materiariemperature  Machine1MotorRPM	0.03
Machine1RawMaterialProperty3	0.03
Machine2MaterialTemperature	0.03
Machine3RawMaterialProperty3	0.02
Machine3RawMaterialProperty4	0.02
Machine3RawMaterialProperty2	0.02
Machine3RawMaterialProperty1	0.02
Machine1MotorAmperage	0.01
Machine1ExitZoneTemperature	0.01
Machine1RawMaterialProperty4	0.01
Machine1RawMaterialProperty2	0.01
Machine2RawMaterialProperty2	0.01
Machine2RawMaterialProperty4	0.01
Machine2RawMaterialProperty1	0.01
Machine2MotorAmperage	0.01
Machine2MaterialPressure	0.01
Machine3Zone1Temperature	0.01
Machine1Zone2Temperature	0.01
Machine2RawMaterialProperty3	0.01
Machine3MotorAmperage	0.01
Machine1RawMaterialProperty1	0.01
Machine2MotorRPM	0.01
Machine1Zone1Temperature	0.00
Machine1RawMaterialFeederParameter	0.00
Machine2Zone2Temperature	0.00
Machine2Zone1Temperature	0.00
FirstStageombinerOperationTemperature3	0.00
Machine1MaterialPressure	0.00
Machine3Zone2Temperature	0.00
Machine3ExitZoneTemperature	0.00
Machine2ExitZoneTemperature	0.00
Machine3RawMaterialFeederParameter	0.00
Machine2RawMaterialFeederParameter	0.00