	<u>ISO 1400</u> 1:2018	EMS - E	Environmental	Audit	Checklist
	Form				
	8632		5/15		
	Case Number		Audit Date		
	Imdon		United State	3	
Official City Stamp	City		Country		

Mark Wang, Tobias kowalski Auditor Team Members

	Evaluation Checkli		
Topic	Required Evidence	Audit Observation	C/N
Water Color	Water should be clear with particles of natural substances. There should be no tinge of color in the water.	Water is clear with no unnatural substances	C
Smell	There should be no chemical or unatural kinds of smells. There should also be no sulfuric smell near the water or water source.	No unnastral Smells	C
Surface Temperature	The average of three tests should range between 60 F and 90 F. The tests should be taken at least three meters apart.	Tenperature has an arrege of 72°F	_
Surface Observation	There should be no bubbles or foam along the surface. There should also be only natural things on the surface of the water.	There is nothing unnatural along the surface of the water. It is clear.	_
Bottom Observation	There should be nothing unatural along the bottom of the water. If there are algae along the bottom, it should only be green.	There is nothing uneatural along the bodon of the water.	C
Wildlife Observation	Auditors should be able to see living organisms in the water. There should be nothing dead floating in the water.	All wildlise looles healthy upon inspection. Nothing Dead.	C

Lead Auditor Signature