	ISO 14001:2018	EMS - Env	ironmental	Audit	Checklist
	Form				
	0633	2 1	5/15		
	Case Number		Audit Date		
	Inda		United States		
Official City Stamp	City J		Country		
Fiore Su					
Lead Auditor					
Marke Wang , I	obi Kowalski				
Auditor Team Membe	ers				

Coal Mine Evaluation Checklist						
Topic	Required Evidence	Audit Observation	C/N			
Equipment Quality	All Equipment should be in usable and sturdy conditions. Machinery should be up to code with manuals and checks often.	Example is in Sixty shape. Mechine is also good.	C			
Safety Regulations	Mining equipment and breathing apparatuses should be provided to the miners everyday.	Il equipmet is good and breedly was is also good	C			
Clean Air Check	Check the air quality. Air must be suitable for breathing. There should be no smell of gas, sulfur, or anything that could be harmful.	The Au is cleared and Folkered within the mans of the South are is also purped into it too	<u>_</u>			
Clean Soil Check	Soils in the mine should be clean with no residue from mining and machinery.	Soil is clear from Pander of Im machine & mining	_			
Proper Lighting and Power Generation	The mines should be well lit. The power source should be regularly checked and have manuals.	Mins ar well let with generators checlard constantly.	C			
Waste Correctly Disposed	All mining wastes should be disposed correctly. There is a clear regulation on a safe method of disposing wastes.	waste is disposed of condy and seak for the environment	_			