

Process 1	Confirmation of mass production transition	Personnel resource	No designation
		Material resource	No designation

INPUT

The suppliers shall evaluate the mass production process for compliance with Honda requirements prior to the start of mass production of new products according to the items listed in below.

The suppliers shall comply with Honda's request to witness an evaluation of the transition to mass production.

Rationale documents and items for mass production transition confirmation (PPAP documents)

No.	Items	Related requirements
1	Statutory and regulatory conformity	SQM 2.2 Statutory and Regulatory Requirements
2	Reflection status of past nonconformities (in-house, delivery and market claim)	SQM 2.3 Verification of Past Problems
3	<u>Design Records (Drawings and specifications)</u>	—
4	<u>Engineering Change Documents</u>	SQM 2.4 Drawing and Specification Change and Application
5	<u>Customer Engineering Approval</u>	—
6	<u>DFMEA</u>	—
7	<u>Delivery Packaging Specification</u>	SQM 3.2 Delivery Packaging
8	Process Quality Control Table (I) / Process flow chart	SQM 3.3 Process Quality Control Table (I) / Process Flow Chart
9	PFMEA	SQM 3.5 Process Failure Mode and Effects Analysis (PFMEA)
10	Process Quality Control Table (II) / Control plan	SQM 3.7 Process Quality Control Table (II) / Control Plan
11	Operation standard, Working instruction	SQM 3.8 Operation standard
12	Training for operators and inspectors	SQM 3.8 Operation standard
13	<u>Measurement system analysis</u>	SQM 4.3 Measurement System Analysis (MSA)
14	Dimension measurement results (All measurement results of dimensions and specifications defined in design records and control plan)	SQM 3.7 Process Quality Control Table (II) / Control Plan
15	Corrective actions for defects that were identified in previous evaluation events	SQM 4.1 Delivery Quality at Pre-production Stage
16	Records of Material / Performance Test Results (Including operational feeling, and easiness of mounting to Honda products)	SQM 3.7 Process Quality Control Table (II) / Control Plan SQM 4.1 Delivery Quality at Pre-production Stage SQM 4.5 Production Validation Testing
17	Process capability	SQM 4.4 Preliminary Process Capability Study
18	<u>Qualified Laboratory Documentation</u>	SQM 2.6 Installation and control of measurement systems
19	Appearance Approval Report (AAR)	SQM 2.5 Requirements for the Production Facility, Mold, Jig and Tool, etc. SQM 3.6 Limit Sample and Master Sample
20	<u>Sample Production Parts</u>	SQM 4.1 Delivery Quality at Pre-production Stage
21	Limit sample and master sample	SQM 3.6 Limit Sample and Master Sample
22	Inspection jigs	SQM 2.6 Installation and control of measurement systems
23	Sub-supplier readiness	SQM 6.2 Sub-Supplier Management
24	<u>Conformity records of customer specific requirements</u>	—
25	Part Submission Warrant (PSW)	SQM 4.6 Production Part Approval Process (PPAP)

The suppliers delivering products to the following Honda locations must meet site-specific requirements in addition to the above requirements.

Location name	Site-specific requirements
<u>Honda Motor Co., Ltd.</u>	The suppliers shall also evaluate that the items specified in the mass production transition declaration meet Honda requirements if requested by Honda.
<u>Four-wheeled vehicle manufacturing and parts plant</u>	
<u>Guangqi Honda Automobile Co., Ltd. (GHAC)</u>	
<u>Honda Cars India Ltd. (HCIL)</u>	

Process 2	Mass production transition declaration	Personnel resource	Quality Assurance Representative or Site Quality Representative
		Material resource	No designation
INPUT			
Based on the results of confirmation of mass production transition, the supplier's representative shall confirm that there are no problems regarding product quality and productivity, then implement the mass production transition declaration.			
Also, if the suppliers find any problems in the mass production transition declaration that do not conform to Honda requirements, the suppliers shall implement the followings:			
a) Development of the corrective action plan			
b) Implementation of the corrective actions			
c) Re-implementation of the mass production transition declaration (if necessary)			